## I Jeep

## **Diagnosis and Repair Bulletin**

Subject: Carbon Knock

Application: 1980-81 Jeep Vehicles with Four-, Six-, or Eight-Cylinder Engine File: POWER PLANT Engines

No.81-2 Feb. 19, 1981

The four-, six-, and eight-cylinder engines used in 1980-81 Jeep vehicles may develop a knock caused by carbon buildup on the pistons and combustion chambers. Carbon knock is more likely to occur on high mileage engines but may also occur on low mileage engines depending on the type of driving involved. Carbon knock is not sensitive to engine loading and is most noticeable when the engine is not under load. Carbon knock may be loudest when the engine is cold and may continue after the engine warms up.

Service correction involves removing carbon buildup using Jeep Carburetor and Combustion Area Cleaner, or equivalent, if the knock is not sensitive to engine load.

The following part may be required.

Description	Quantity	Part No.	Group
CLEANER, Carburetor and Combustion Area	Case of 12	8993813	15.410

### PROCEDURE

- (1) Remove air cleaner top.
- (2) Operate engine until it is at normal operating temperature.
- (3) Operate engine at fast idle speed and spray cleaner directly into carburetor venturi until container is empty.
- (4) Stop engine when container is empty and allow cleaner to penetrate carbon for five minutes.
- (5) Start engine and open and close throttle rapidly for two minutes.
- (6) Install air cleaner top.

The following standard servicing operation and work time will apply:

OPERATION DESCRIPTION	COST	OPERATION		YEA	R AND T	IME	SKILL
	CODE	NUMBER	MODEL	80	81	82	LEVEL
COMBUSTION CHAMBERS, CYLINDER HEAD — CLEAN	1.059	1117	All	0.3	0.3		G

81-039-01A/J

## **VI** American Motors Sales Corporation

Service Engineering Department • 14250 Plymouth Road • Detroit, Michigan 48232

Jeec

Subject: Six-Cylinder Camshaft Pin Breakage Application: 1977-80 Jeep Vehicles With Six-Cylinder Engines File: POWER PLANT Engines

No. 80-3 Feb. 4, 1980

If incorrect valve timing is indicated after checking valve timing, the cause may be a broken camshaft pin. It is no longer necessary to replace the camshaft because of pin failure. A spring pin is now available as a service replacement part.

Service correction involves replacing a broken camshaft pin with a new spring pin.

The following parts are available and will be required.

Description	Quantity	Part No.	Group
PIN, Spring			
(Camshaft)	1	GM456384	1.040
GASKET SET.			
<b>Timing Case Cover</b>	1	8129097	1.121
SCREW, Hex			
Washer Head			
Tapping	1	G448423	17.671

### PROCEDURE

- (1) Disconnect battery negative cable.
- (2) Drain radiator.

**NOTE:** Do not waste usable coolant. Collect drained coolant in a clean container.

(3) Remove fan and shroud.

(4) Disconnect overflow hose, radiator hoses and transmission cooler lines from radiator and remove radiator.

- (5) If equipped with air conditioning:
  - (a) Remove air conditioning belt intermediate pulley.
  - (b) Disconnect and remove alternator.

CAUTION: Do not loosen or disconnect any air conditioning system fittings. Move the condenser aside as a complete assembly.

- (c) Remove air conditioning condenser attaching bolts and move condenser up and out of way.
- (6) Remove all drive belts.
- (7) Remove crankshaft vibration damper.
- (8) Remove timing chain cover.

(9) Remove camshaft gear bolt and remove gear and chain.

CAUTION: The following procedural step must be performed to prevent the camshaft from damaging the rear camshaft plug during pin installation.

(10) Remove fuel pump. Insert suitable tool into fuel pump opening and wedge tool against side of opening and camshaft to prevent camshaft movement.

- (11) Inspect damaged camshaft pin.
  - (a) If pin is spring pin, remove broken pin by inserting G448423 screw into pin and carefully pulling pin from camshaft.
  - (b) If pin is dowel pin: CAUTION: Be sure the exact center is located when center punching the pin.
    1. Center punch pin.
    - 2. Drill through pin center using 5/32-inch drill bit.
    - Insert G448423 screw into drilled pin and carefully pull pin from camshaft.
      NOTE: Cover the open oil pan area to prevent metal chips from entering the pan.
- (12) Clean camshaft pin hole of any loose material.

(13) Compress replacement spring pin in center using vise grips. Carefully drive pin into camshaft until it is seated.

## **VI American Motors Sales Corporation**

Service Engineering Department • 14250 Piymouth Road • Detroit, Michigan 48232

CAUTION: If the camshaft moves rearward, reposition the tool wedged against the camshaft so that the camshaft cannot move. If the camshaft moves rearward, damage to the rear camshaft plug may result.

(14) Install camshaft gear and timing chain. Tighten camshaft gear bolt to 50 foot-pounds (68 N·m) torque. Check valve timing as outlined in 1980 Jeep Technical Service Manual.

(15) Remove tool wedged in fuel pump opening. Install fuel pump. Tighten pump bolts to 16 footpounds (22 N-m) torque and connect fuel lines.

(16) Remove timing case cover seal and clean cover.

(17) Position oil pan tab gaskets on oil pan and use RTV type sealer to hold gasket in place. Coat both sides of timing case cover gasket with sealer. Apply 1/8-inch (3 mm) bead of sealer to joint formed at oil pan and cylinder block.

(18) Loosen front four oil pan bolts about 3 turns to allow oil pan movement during timing case cover installation.

(19) Position timing case cover on engine. Place timing case alignment tool and seal installer J-22248, in crankshaft opening of cover.

(20) Install and tighten oil pan and front cover screws.

NOTE: Tighten 1/4-20 oil pan screws to 7 footpounds (9 N·m) torque and 5/16-18 oil pan screws to 11 foot-pounds ( $15 N \cdot m$ ) torque.

(21) Remove cover aligning tool and position replacement oil seal on tool with lip facing outward. Apply

The following operation and standard work times will apply:

light film of AMC Perfect Seal, or equivalent, on outside diameter of seal.

(22) Position tool and seal in front cover opening. Use vibration damper bolt to pull seal into front cover. Turn bolt until tool bottoms against cover.

(23) Remove tool and install vibration damper on crankshaft. Tighten damper bolt to 80 foot-pounds (108 N·m) torque.

NOTE: If the crankshaft turns before the damper bolt torque value is reached, the damper can be held from turning by placing two  $5/16 \times 1-1/2$ -inch bolts into the vibration damper front pulley holes and wedging a bar between them. Rotate the bar until it contacts the frame member to prevent the damper from turning.

(24) If equipped with air conditioning:

- (a) Install air conditioning belt intermediate pulley.
- (b) Install alternator.
- (c) Install air conditioner condenser.

(25) Install drive belts on pulleys.

(26) Install radiator. Connect radiator hoses, transmission cooler lines if equipped and fill cooling system.

(27) Install fan and shroud.

(28) Follow belt tightening procedure outlined in 1980 Jeep Technical Service Manual.

(29) Tighten fan assembly nuts to 18 foot-pounds (24  $N \cdot m$ ) torque.

(30) Connect battery negative cable.

OPERATION DESCRIPTION	COST	OPERATION NUMBER	OPERATION NUMBER MODEL	1	:	SKILL		
	CODE			77	78	79	80	LEVE
PIN, SPRING CAMSHAFT GEAR DRIVE— REPLACE	1.040	1163	6-Cyl.	1.7 0.3 0.4	1.7 0.3 0.4	1.7 0.3 0.4	1.7 0.3 0.4	G
Includes 6 minutes helper time.								

80-044-01A/J

## /I Jeep

# **Diagnosis and Repair Bulletin**

Subject: Exhaust Manifold to Exhaust Pipe Studs and Nuts

Application: 1980 Jeep Vehicles with Six-Cylinder Engines File: POWER PLANT Engines

No. 80-2 Nov. 2, 1979

A new design exhaust manifold locking stud and hexagon nut has been introduced for 1980 six-cylinder engines.

The stud incorporates a special thread design that contains a locking feature (the thread design can be recognized by its shallow thread depth). The stud also has a triangular shaped surface (as opposed to a round surface) that helps in the locking process. The hexagon nut is coated with "Seez Pruf" coating and is an SAE grade 8 nut. These are the only stud and nut assemblies that should be used on 1980 six-cylinder engines.

Because of the assembly design, special procedures are needed for service. When servicing the joint only, as in the case of a cylinder head removal, follow the Nut Removal Procedure. If stud(s) are being replaced, as in the case of stud damage or loss of the "shallow thread" locking feature, the Stud Removal Procedure must be followed to prevent possible damage to the exhaust manifold.

## NUT REMOVAL PROCEDURE

(1) Saturate stud and nut assemblies with AMC/Jeep Heat Valve Lubricant part number 8993552 and allow to penetrate for approximately five minutes.

CAUTION: Do not use impact tools as this can damage the stud and/or manifold.

- (2) Remove existing nuts using hand tools.
- (3) Clean stud of foreign material.
- (4) Position exhaust pipe flange over studs.

The following operations and standard work times will apply:

(5) Install two new hexagon nuts and tighten them in equal amounts to 20 foot-pounds  $(27 \text{ N} \cdot \text{m})$  torque.

### STUD REMOVAL PROCEDURE

- (1) Clean foreign matter from stud.
- (2) Turn two standard 3/8-inch x 16 nuts down stud.

(3) Using hand tools, turn nuts in opposite directions to lock together.

(4) Using hand tools, remove stud using locked nuts as leverage point.

(5) Start standard 3/8-inch x 16 nut onto new stud. Install nut onto end that contains approximately 1 inch of threads before band.

(6) Start stud into manifold.

(7) Carefully tighten nut until about four threads are exposed past nut.

NOTE: Do not tighten nut down on stud any farther than necessary as stud locking design may be disturbed.

(8) Start another standard 3/8-inch x 16 nut onto exposed threads. Using hand tools, tighten nuts in opposite directions to lock together.

(9) Tighten stud into manifold to 20 foot-pounds  $(27 \text{ N} \cdot \text{m})$  torque.

(10) Remove two nuts taking care not to back out stud.

OPERATION DESCRIPTION	COST	OPERATION	MODEL	YEA	RAND	TIME	SKILL
	CODE	NUMBER	MODEL	80	81	82	LEVEL
STUD, EXHAUST PIPE FLANGE TO MANIFOLD REPLACE Both	4.178 4.178	4192 A	6-Cyl.	0.7 0.9			G G

80-020-04AJ

## American Motors Sales Corporation

Service Engineering Department • 14250 Plymouth Road • Detroit, Michigan 48232

/ Jeeo.

Subject: Rear Crossmember and Torque Reaction Bracket Reposition Application: 1980 CJ-7 Four-Cylinder Equipped Vehicles Built Between VIN J0M93XX009040 and J0M93XX014233 File: POWER PLANT Engines

No. 80-1 Oct. 30, 1979

Some 1980 CJ-7 four-cylinder equipped vehicles built between VIN J0M93XX009040 and J0M93XX014233 were assembled with the torque reaction bracket installed in the rear (towards the rear of the vehicle) set of holes in the transmission-to-transfer case adapter and the rear crossmember positioned incorrectly. This combination results in a noise being caused by contact between the transfer case and the rear crossmember reinforcement.

Service correction involves moving the torque reaction bracket to the front set of holes in the adapter and correctly positioning the rear crossmember.

### PROCEDURE

(1) Raise vehicle.

(2) Support transfer case assembly.

(3) Remove rear engine mount nuts and torque reaction bracket stud nut.

(4) Remove rear crossmember bolts and rear crossmember.

(5) Remove torque reaction bracket from transmission-to-transfer case adapter.

(6) Install torque reaction bracket to adapter using forward (towards the front of vehicle) set of holes in adapter. Tighten bolts to 30 foot-pounds  $(41 \text{ N} \cdot \text{m})$  torque.

forward hole in frame (see illustration). Install rear engine mount nuts loosely to hold crossmember in place while crossmember bolts are installed. Tighten crossmember bolts to 30 foot-pounds (41 N·m) torque.

(7) Align forward slot in rear crossmember over



**Rear Crossmember Location** 

(8) Tighten rear engine mount nuts to 40 footpounds (54 N·m) torque. Install and tighten torque reaction bracket stud nut to 25 foot-pounds (34 N·m) torque.

- (9) Remove support at transfer case.
- (10) Lower vehicle.

The following operation and standard work time will apply:

OPERATION DESCRIPTION	COST	OPERATION	MODEL	YEA	RAND	TIME	SKILL
	CODE	NUMBER	MODEL	80	81	82	
CROSSMEMBER, REAR AND TORQUE REACTION BRACKET - REPOSITION	1.010	1215	93	0.3			G

80-021-BSA

## **VI American Motors Sales Corporation**

Service Engineering Department • 14250 Plymouth Road • Detroit, Michigan 48232 Additional copies of this bulletin are available through your zone office.

80-5

### **Jeep**

# **Diagnosis and Repair Bulletin**

Subject: Coolant Recovery Return Hose Kinked

Application: 1980 Cherokee, Wagoneer and Truck Models With Six-Cylinder Engine

necessary.

return hose.

submerged in coolant.

coolant into the recovery bottle.

radiator cap.

(2) Remove radiator cap.

(3) Inspect radiator upper hose for signs of pressure

or fan belt rubbing. Replace radiator upper hose if

(4) Remove coolant recovery hose clamps at radia-

(5) Remove and discard existing coolant recovery

(6) Trim replacement coolant recovery hose as follows: Cut 1.25 inches from short end of hose and cut 5.25 inches from long end of hose. Cut short hose end at 45° angle and cut long end at 90° angle.

(7) Install replacement coolant recovery hose. Insert short end of hose into coolant recovery bottle

and install long end on radiator filler neck. Be sure hose end inserted in recovery bottle will always be

(8) Install hose clamps. Refill radiator and install

NOTE: If the radiator fills prior to complete usage

of the expelled coolant, pour the remainder of the

NOTE: Do not waste reusable coolant.

tor and coolant recovery bottle.

File: POWER PLANT Cooling

No. 80-1 March 31, 1980

On some 1980 Cherokee, Wagoneer and Truck models with a six-cylinder engine and coolant recovery system, the coolant return hose may kink near the coolant recovery bottle. A kinked hose may not allow coolant to return from the recovery bottle to the radiator and may cause the radiator upper hose to collapse.

Service correction involves replacing the existing coolant recovery return hose with a molded-type hose.

The following part is available and required.

Description	Quantity	Part No.	Group
HOSE, Coolant			
<b>Recovery Bottle</b>			
to Radiator	1	3237203	2.025

### PROCEDURE

(1) Place drain pan under radiator.

WARNING: Cooling system pressure must be relieved before removing the radiator cap. Place two or three shop towels over the cap. Turn the cap counterclockwise to its safety catch and allow pressure to release. Do not press the cap down or attempt to remove it until all pressure is released.

The following operations and standard work times will apply:

OPERATION DESCRIPTION	COST	OPERATION	MODEL	YEAR AND TIME			SKILL
	CODE	NUMBER		80	81	82	LEVEL
HOSE, RADIATOR CORE OVERFLOW – REPLACE	2.020	2026	6 Cyl.	0.2			м
HOSE, COOLING SYSTEM - REPLACE Includes hose clamps as required		2020	0				M
Upper radiator	2.038		6 Cyl.	0.3			

80-089-02J

## 71 American Motors Sales Corporation

Service Engineering Department • 14250 Plymouth Road • Detroit, Michigan 48232 Additional copies of this bulletin are available through your zone office.

Subject: Spark Knock Repair

Application: 1980 49-State Cherokee and J-10 Truck Models With Manual Transmission, 360-CID Engine, and Standard or Heavy-Duty Cooling

File: POWER PLAN'T Engine Electrical

No. 80-2 April 10, 1980

### Some early production 49-State Cherokee and J-10 Truck models with manual transmission, 360 CID eight-cylinder engine, and standard or heavy-duty cooling may develop a persistent spark knock at a steady speed of about 40 mph.

Service correction involves adding a vacuum ported spark CTO switch, relocating the EGR CTO switch on models with heavy-duty cooling, and replacing the EGR valve restrictor plate.

The following parts kit is required and will be available the week of May 5, 1980. Do not order parts before this date.

Description	Quantity	Part No.	Group
KIT, Spark Knock Eliminate	1	8130428	4.700

This kit contains the following parts:

Description	Quantity	Part No.	Group
TEE, Vacuum Ported			
Switch and Heater			
Hose Nipple-to-			
Manifold	1	G444150	4.704
TEE, Vacuum	1	3210891	4.701
GASKET, Exhaust Gas	2	3221283	4.700
TEE, Vacuum Hose	1	3233134	4.701
PLATE, Exhaust			
Gas Recirculating			
Valve Restrictor	1	3235342	4.700
SWITCH, Vacuum			
Ported (Spark CTO)	1	3229450	4.704
HOSE 0.0156 ID			
50 Inches Long	1	8125812	4.701

The following parts may be required:

Description	Quantity	Part No.	Group
GASKET, Thermostat	AR	3187543	2.102
HOUSING, Thermostat	AR	3210852	2.102

## INSPECTION PROCEDURE

Determine if vehicle has standard or heavy-duty cooling as follows:

- If vehicle has CTO switch in thermostat housing, vehicle has heavy-duty cooling system. Refer to Correction Procedure — With Heavy-Duty Cooling.
- If vehicle does not have CTO switch in thermostat housing, vehicle has standard cooling system. Refer to Correction Procedure — With Standard Cooling.

## Correction Procedure - With Standard Cooling

(1) Remove air cleaner assembly.

(2) Remove EGR valve. Discard EGR valve restrictor plate and gaskets but retain EGR valve.

(3) Position gasket on each side of replacement EGR restrictor plate and install restrictor plate and EGR valve. Tighten valve attaching bolts to 14 footpounds (19 N·m) torque.

(4) Drain approximately three quarts of engine coolant from radiator into clean container.

WARNING: Be very careful when draining the coolant as it may be hot enough to cause potentially serious injury through scalding.

(5) Remove pipe plug from rear of thermostat housing.

NOTE: If the thermostat housing does not contain a pipe plug, replace the thermostat housing with housing 3210852.

(6) Install ported vacuum spark CTO switch in pipe plug hole in thermostat housing. Tighten switch to 20 foot-pounds  $(27 \text{ N} \cdot \text{m})$  torque.

(7) Remove reverse delay valve and short length of vacuum hose that connects valve to distributor vacuum advance. Retain delay valve and short length of hose.

## **FI** American Motors Sales Corporation

Service Engineering Department • 14250 Plymouth Road • Detroit, Michigan 48232 Additional copies of this builetin are available through your zone office. (8) Connect hose from vacuum line T-connector to distributor vacuum advance unit. Then disconnect opposite end of this hose and connect it to center port of spark CTO switch.

(9) Connect 12-inch length of vacuum hose to vacuum line T-connector and to inner port of spark CTO switch.

(10) Connect short length of vacuum hose and reverse delay valve to top port of spark CTO switch. Be sure brown color coded side of delay valve is toward spark CTO switch.

(11) Connect a two-inch length of vacuum hose to reverse delay valve and install vacuum line Tconnector, supplied in kit, in opposite end of this hose.

(12) Using vacuum line T-connector as guide, cut vacuum hose connected to diverter valve and manifold vacuum port and connect cut ends of this hose to T-connector.

(13) Fill cooling system and purge system of air.

(14) Verify vacuum hose routing. Refer to Figure 1.

(15) Install air cleaner and close hood.

Correction Procedure - With Heavy Duty Cooling

(1) Remove air cleaner.

(2) Remove EGR valve. Discard EGR valve restrictor plate and gaskets but retain EGR valve.

(3) Position gasket on each side of replacement EGR valve restrictor plate and install restrictor plate and EGR valve. Tighten valve attaching bolts to 14 foot-pounds (19 N·m) torque.

(4) Drain approximately three quarts of engine coolant from radiator into clean container.

WARNING: Be very careful when draining the coolant as it may be hot enough to cause potentially serious injury through scalding.

(5) Remove EGR CTO switch from front of intake manifold. Retain switch.

NOTE: It may be necessary to remove the coil bracket to gain access to the EGR CTO switch.

(6) Disconnect heater hose from heater hose elbow and remove elbow from intake manifold.

(7) Install heater hose elbow in female end of vacuum ported switch and heater hose nipple-tomanifold tee. (8) Install two-port EGR CTO switch (removed previously) in nipple-to-manifold tee and tighten switch to 20 foot-pounds (27 N·m) torque. Position CTO switch so switch ports are pointing upward. Tighten tee so that CTO switch faces front of vehicle.

(9) Connect heater hose to heater hose elbow.

(10) Remove and discard vacuum hose connected to carburetor spark port. Replace this hose with 24-inch length of vacuum hose and connect new hose to carburetor spark port and to inner port of EGR CTO switch.

(11) Connect EGR thermal vacuum switch hose to remaining port on EGR CTO switch. Shorten hose as necessary to obtain satisfactory hose routing.

(12) Install three-port vacuum ported spark CTO switch in front of intake manifold at location formerly occupied by EGR CTO switch. Tighten switch to 20 foot-pounds ( $27 \text{ N} \cdot \text{m}$ ) torque.

(13) Remove reverse delay valve and vacuum harness that connects top port of CTO switch (in thermostat housing) to carburetor spark port tee fitting. Retain harness and delay valve.

(14) Connect nine-inch length of vacuum hose to carburetor spark port tee fitting and to bottom port of three-port vacuum ported spark CTO switch in manifold.

(15) Locate vacuum hose that connects manifold vacuum tee fitting to bottom port of CTO switch in thermostat housing and remove manifold vacuum tee fitting tee and replace it with four-port hose tee supplied in kit.

(16) Connect vacuum hose from bottom port of CTO switch in thermostat housing to a port on four-port hose tee.

(17) Install vacuum harness and reverse delay valve. Connect short vacuum hose to top port of three-port vacuum ported spark CTO switch and connect long hose to remaining open port of four-port vacuum tee.

(18) Connect 9-inch length of vacuum hose to top port of CTO switch in thermostat housing and to center port of three-port vacuum ported spark CTO switch.

(19) Fill cooling system and purge system of air.

(20) Install coil bracket if removed.

(21) Verify correct hose routing. Refer to Figure 2.

(22) Install air cleaner and close hood.



Fig. 1 49-State 360 With Manual Transmission and STD Cooling



Fig. 2 49-State 360 With Manual Transmission and HD Cooling

The following operation and standard work time will apply:

OPERATION DESCRIPTION	COST	OPERATION		YEA	RAND	TIME	SKILL
	CODE	NUMBER	MODEL	80	81	82	LEVEL
KIT, SPARK KNOCK ELIMINATE – INSTALL	4.700	4297					G
With standard cooling With heavy-duty cooling			Cke-Trk Cke-Trk	0.5 0.7			

80-075-04J

## / Jeep

# **Diagnosis and Repair Bulletin**

Subject: Electric Choke and Idle Solenoid Feed Wire Routing

Application: 1980 Jeep Models Equipped with Six-Cylinder Engine File: POWER PLANT Engine Electrical

No. 80-1 Oct. 26, 1979

On 1980 Jeep models with six-cylinder engines, the idle solenoid wire and the electric choke wire should be routed with a clearance of at least 1/4 inch from the air injection manifold. If these wires have less than 1/4 inch clearance, they must be relocated,

NOTE: The electric choke and idle solenoid feed wires are fused to protect the circuit if a short or overload should occur.

Service correction involves routing the harness containing both wires OVER the diverter valve hose and between the carburetor and choke diaphragm.

### PROCEDURE

(1) Remove air cleaner.

(2) Disconnect electric choke feed wire from electric choke.

(3) Disconnect idle solenoid feed wire from idle solenoid.

NOTE: The idle solenoid is not used on manual transmission equipped vehicles and the feed wire must be tied back with a nylon strap, part number 3223227 (see illustration).

(4) Route harness containing both feed wires OVER diverter valve hose and between carburetor and choke diaphragm (see illustration).

(5) Connect idle solenoid feed wire to idle solenoid if equipped.

The following operation and standard work time will apply:



### Electric Choke and Idle Solenoid Feed Wire Routing

(6) Connect electric choke feed wire to electric choke.

(7) Install air cleaner,

CAUTION: Route and secure wires and hoses so that they are not pinched, kinked, pulled too tight or interfering with moving parts such as the carburetor linkage or edges of the hood.

OPERATION DESCRIPTION	COST	OPERATION		YEA		TIME	SKILL
	CODE	NUMBER	MODEL	80	81	82	LEVEL
WIRES, IDLE SOLENOID AND ELECTRIC CHOKE FEED — REPOSITION	3.165	3315	6-Cyl.	0.1			G

80-007-03J

### **VII American Motors Sales Corporation**

Service Engineering Department • 14250 Plymouth Road • Detroit, Michigan 48232

Jeep,

## **Diagnosis and Repair Bulletin**

Subject: Altitude Performance Adjustments Application: 1968-80 Jeep Vehicles File: POWER PLANT -Fuel and Exhaust

No. 80-7 Nov. 10, 1981

This bulletin is being issued to outline the altitude performance adjustments for 1968-80 Jeep vehicles required under a newly established Federal standard. The adjustments are intended to improve driveability performance as well as emissions performance at altitudes other than that for which the vehicles were originally certified.

Any Jeep vehicle that has been so adjusted must have a unique emission control information label installed. These unique labels are available in a kit, part number 3242106 from the following facility:

American Motors Corporation Distribution Services 37200 Amrhein Road Livonia, Michigan 48150

The adjustment procedures and unique labels must be made available at no cost to independent repair facilities and the general public. A notification is also provided in current owners manuals to make customers aware of these adjustments.

#### ADJUSTMENT PROCEDURES

On Jeep vehicles originally sold for operation at altitudes **below** 4,000 feet that are being operated above 4,000 feet, the ignition timing, as shown on the vehicle emission control label located in the engine compartment or specified in the appropriate Jeep Technical Service manual should be advanced  $5^{\circ}$  (not to exceed  $15^{\circ}$  total advance). The engine idle speed should be reset according to the procedures and idle speed specification outlined in the appropriate Jeep Technical Service Manual for the year of vehicle being serviced.

After performing these adjustments, attach emission control label, part number EF 8130457, to the engine compartment dash panel. Do not attach the label to any component that can be readily removed from the vehicle.

These adjustments apply to all 1968-80 Jeep vehicles that were sold for principal use at altitudes below 4,000 feet. Refer to the vehicle emission control label in the engine compartment to identify these vehicles.

On 1968-80 Jeep vehicles originally sold for operation at altitudes **above** 4,000 feet that are being operated below 4,000 feet, the ignition timing, as shown on the vehicle emission control label located in the engine compartment or specified in the apropriate Jeep Technical Service Manual should be retarded 5°. The engine idle speed should be reset according to the procedures and idle speed specifications outlined in the appropriate Jeep Technical Service Manual for the year of the vehicle being serviced. After performing these adjustments, attach emission control label, part number EF 8130458, to the engine compartment dash panel. Do not attach the label to any component that can be readily removed from the vehicle.

These adjustments apply only to 1968-80 Jeep vehicles that were sold for principal use at altitudes above 4,000 feet. Refer to the vehicle emission control label in the engine compartment to identify these vehicles.

81-114-04A/J

### 71 American Motors Sales Corporation

/ Jeep =

## **Diagnosis and Repair Bulletin**

Subject: Exhaust Gas Recirculation (EGR) System Revision

Application: 1980 49-State Cherokee Wagoneer, and Truck Models With 360 CID Engine, Automatic Transmission, 2.73 or 3.31 Ratio Axles and Standard or Heavy-Duty Cooling System File: POWER PLANT Fuel and Exhaust Systems

No. 80-6 Oct. 27, 1980

The EGR system on 1980 Cherokee, Wagoneer, and Truck models with 360 CID engine, automatic transmission, 2.73 or 3.31 ratio axles, and standard or heavy-duty cooling system may be revised to improve acceleration. This revision is an EPA approved change and applies to all similiarly equipped 1980 Cherokee, Wagoneer, and Truck models.

Service revision involves replacing the EGR valve restrictor plate and forward delay valve, and adding a non-linear valve to the EGR system.

The following parts kit is required and available:

Description	Quantity	Part No.	Group
KIT, EGR System			
Revision	1	8130437	4.700
Kit Contents:			
GASKET, EGR			
Valve	2	3221283	4.700
FITTING, Vacuum			
Hose Connector	1	3233134	4.701
VALVE, Non-Linear	1	3233991	3.051
Valve, Forward Delay	1	3235261	4.700
RESTRICTOR			
PLATE, EGR. Valve			
(Code T)	1	3235343	4,700
HOSE. Vacuum	-		
Eight Inches Long	1	3228064	4.700
FITTING, Vacuum			
Hose Tee (H.D.			
Cooling)	1	3210891	3.050

#### PROCEDURE

#### **Inspection Procedure**

Determine if vehicle has standard or heavy-duty cooling as follows:

• If vehicle has EGR/CTO switch in right front corner of intake manifold, vehicle has standard cooling. Refer to Revision Procedure With Standard Cooling. • If vehicle has EGR/CTO switch in right rear corner of intake manifold, vehicle has heavyduty cooling system. Refer to Revision Procedure — With Heavy-Duty Cooling System.

#### **Revision Procedure – With Standard Cooling**

(1) Remove air cleaner assembly.

(2) Remove EGR valve and remove valve gaskets (2) and restrictor plate. Retain valve but discard gaskets and plate.

(3) Install replacement gaskets and restrictor plate (code T) on EGR valve and install valve on manifold. Tighten valve attaching bolts to 14 foot-pounds (19 N·m) torque.

(4) Remove and discard forward delay valve from vacuum hose that connects EGR/CTO switch to EGR/TVS switch.

(5) Install replacement forward delay valve in hose with black side of valve toward EGR/CTO switch (Fig. 1).

(6) Remove and discard tee fitting in manifold vacuum-to-diverter valve vacuum hose and install vacuum hose connector fitting in place of tee fitting.

(7) Connect 4-inch length of vacuum hose to center port of non-linear valve and to open port on vacuum hose connector fitting installed in previous step (Fig. 1).

(8) Disconnect vacuum hose attached to tee fitting in canister purge valve signal-to-carburetor hose and connect hose to bottom port of non-linear valve (Fig. 1).

(9) Connect 4-inch length of vacuum hose to upper port of non-linear valve and to open port of tee fitting in canister purge valve signal-to-carburetor hose (Fig. 1).

### **VII** American Motors Sales Corporation

Service Engineering Department • 14250 Plymouth Road • Detroit, Michigan 48232



Fig. 1 Standard Cooling System

Revision Procedure-With Heavy-Duty Cooling System

(1) Remove air cleaner assembly.

(2) Remove EGR valve and remove valve gaskets (2) and restrictor plate. Retain valve but discard gaskets and plate.

(3) Install replacement gaskets and restrictor plate (code T) on EGR valve and install valve on manifold. Tighten valve attaching bolts to 14 foot-pounds (19 N-m) torque.

(4) Remove and discard forward delay valve from vacuum hose that connects EGR/CTO switch to carburetor (Fig. 2).

(5) Install replacement forward delay valve in hose with black side of valve toward carburetor (Fig. 2).

(6) Connect 4-inch length of vacuum hose to center port of non-linear valve.

(7) Locate vacuum hose that connects bottom port of spark/CTO switch to vacuum tee fitting and cut hose midway between switch and tee fitting. Connect hose from spark/CTO switch to bottom port of nonlinear valve and connect hose from the fitting to top port of non-linear valve (Fig. 2).

(8) Locate vacuum hose that connects reverse delay valve to manifold vacuum fitting and cut hose midway between valve and fitting; then connect cut ends of hose to vacuum hose tee fitting supplied in kit.

(9) Connect 4-inch length of vacuum hose attached to center port of non-linear valve to vacuum hose tee fitting installed in previous step.



Fig. 2 Heavy-Duty Cooling System

The following standard servicing operation and work time will apply:

OPERATION DESCRIPTION	COST CODE	OPERATION NUMBER		YEAR AND TIME			SKILL
			MODEL	80	81	82	LEVEL
EGR SYSTEM—REVISE Includes replacement of EGR valve restrictor plate, forward delay valve, and installation of non-linear valve	4.700	4289	Cke-Wag-Trk	0.4			G

80-158-04J

**FI Jeep**,

Subject: Running Change to Four-Cylinder Engine Choke System Application: 1980 CJ Models With Four-Cylinder Engine File: POWER PLANT Fuel and Exhaust Systems

No. 80-5 July 18, 1980

The choke operating time has been extended on 1980 CJ models with four-cylinder engines. This revision entered production as an EPA approved running change in April of this year and can also be applied to 1980 four-cylinder CJ models built before April.

Service revision of 1980 four-cylinder CJ models built before April of this year involves installing a revised choke cover and adjusting primary side vacuum break, fast idle cam position, and fast idle speed.

The following parts are required and are available.

Description	Quantity	Part No.	Group
COVER AND COIL, Choke	1	8133347	4.001
RIVET, Drive	3	8133348	4.001

### PROCEDURE

(1) Raise hood and inspect number on sticker attached to choke cover.

(a) If number on sticker is 70172, revised choke cover has been installed. Return automobile to owner.

(b) If number on sticker is other than number indicated in step (a), proceed to step (2).

(2) Remove carburetor air cleaner.

(3) Disconnect fuel line, vapor vent line, vacuum hoses, electrical connectors, and throttle linkage from carburetor.

(4) Remove bolts and nuts attaching carburetor to manifold and remove carburetor.

(5) Mount carburetor on holding fixture J-9789-118. CAUTION: The holding fixture must be used to avoid damaging the carburetor throttle plates.

(6) Cut heads from rivets that attach choke cover to carburetor choke housing using hammer and small chisel (Fig. 1). Take care to avoid damaging choke housing or choke cover retainers when removing rivet heads.

(7) Remove remainder of each rivet from choke housing using hammer and small pin punch. Do not damage choke housing when removing rivets.

(8) Remove retainers and choke cover. Discard choke cover but keep retainers.

(9) Rotate fast idle cam until fast idle adjusting screw is on highest step of cam.

(10) Position replacement choke cover on choke housing and align notch on cover with projection on choke housing to index cover.



Fig. 1 Removing Choke Cover Rivets

### **VI American Motors Sales Corporation**

NOTE: Be sure the tang on the choke cover coil is engaged with the choke coil lever in the choke housing.

(11) Install choke cover retainers and secure cover to choke housing using drive rivets. Tap rivets into place using hammer and punch to expand and seat rivets in housing (Fig. 2).

(12) Perform Primary Side Vacuum Break Adjustment to obtain setting of 19°. Refer to page 83 in 1980 Jeep Technical Service Manual Supplement for procedure.

NOTE: The vacuum break adjustment setting of 19<sup>o</sup> is a revised specification. Please note this change in your 1980 Jeep Technical Service Manual Supplement.

(13) Perform Fast Idle Cam Position Adjustment to obtain setting of 18°. Refer to page 82 in 1980 Jeep Technical Service Manual Supplement for procedure.

(14) Install carburetor on manifold. Tighten carburetor attaching bolts and nuts to 13 foot-pounds  $(17 \text{ N} \cdot \text{m})$  torque.

(15) Connect fuel line, vapor vent line, vacuum hoses, electrical connectors, and throttle linkage to carburetor.

(16) Perform Fast Idle Speed Adjustment to obtain setting of 2500 RPM. Refer to page 84 in 1980 Jeep Technical Service Manual Supplement for procedure.

(17) Install carburetor air cleaner.





The following standard servicing operations and work times will apply:

	COST	COST OPERATION CODE NUMBER		YEA	SKILL		
OPERATION DESCRIPTION	CODE		MODEL	80	81	82	LEVEL
COVER, CARBURETOR CHOKE -							
INSPECT.	4.021	4131	4-cyl.				
Model 2SE				0,1			G
Cover, carburetor choke - Replace	4.021	A					
Model 2SE.				0.7			G
Primary side vacuum break — Adjust	4.906	В		0.1			
Model 25E	4 009			0.1			L G
Fast fole cam position – Adjust	4.900			01			G
Idle sneed fast $-\Delta diust$	4 908	n l		0.1			U .
Model 2SE.	2,000			0.1			G
						1	

80-103-05J

/I Jeep,

Subject: Fuel Tank Sending Unit Service Application: 1980 Cherokee and Wagoneer Models Built After December 17, 1979 File: POWER PLANT Fuel and Exhaust Systems

No. 80-4 April 2, 1980

It is not necessary to lower the fuel tank to service the fuel gauge sending unit on Cherokee and Wagoneer models built after December 17, 1979. Vehicles built after this date will have an access hole in the rear floorpan that allows the sending unit to be serviced from within the vehicle.

When servicing the fuel tank sending unit on subject models use the procedure provided in this bulletin.

The following parts are required:

Description	Quantity	Part No.	Group
RIVETS (.125 x .275 inch)	4	4005899	20.035
GASKET-IN-A-TUBE	AR	8993317	15.260
PR	OCEDURE		

(1) Fold rear seat forward and secure seat by attaching holding strap to B-post.

(2) Remove rear mat retainer, if equipped, and remove skid strips as necessary.

(3) Remove heads from rivets that attach access cover to floorpan using a 5/32 drill.

CAUTION: Do not drill through the floorpan.

(4) Remove access cover using a chisel or large flat blade screwdriver.

(5) Remove remaining rivets and clean rivet holes. Remove all rivet material from top of fuel tank. (6) Disconnect sending unit wire and ground wire.

(7) Disconnect fuel lines from sending unit.

(8) Remove locknut that retains sending unit in fuel tank and remove sending unit.

(9) Inspect condition and fit of sending unit O-ring in groove around tank opening. Replace O-ring if it is damaged or does not fit properly.

(10) Install sending unit and locknut. Tighten locknut to 14-18 foot-pounds (19-24 N·m) torque.

NOTE: Socket Wrench J-23726 may be used to tighten the locknut.

(11) Connect fuel lines to sending unit.

(12) Connect sending unit wire and ground wire.

(13) Apply 1/8-inch bead of RTV silicone sealer around outer edge of access cover.

(14) Install and secure access cover using  $0.125 \times 0.275$  rivets. Remove any excess sealer after installing rivets.

CAUTION: Do not use screws to attach the access cover to the floorpan.

(15) Position mat or carpet and install retainer, if equipped.

(16) Place seat in upright position and latch seat securely.

The following operations and standard work times will apply:

OPERATION DESCRIPTION	COST OPER	OPERATION	MODEL	YEA	SKILL		
	CODE	NUMBER		80	81	82	LEVEL
SENDING UNIT, FUEL TANK – REPLACE Includes R & R fuel tank	3.614	4154	83-93 Wag-Cke-Trk	0.8 1.0			G
With floor access cover			Wag-Cke-Trk	0.3			
Fuel tank — Drain and refill as required		A	18	0.2			G
			1041 87				1

I American Motors Sales Corporation

80-072-04J

Service Engineering Department • 14250 Plymouth Road • Detroit, Michigan 48232 Additional copies of this bulletin are available through your zone office.

/I Jeep

Subject: Microprocessor (ECM) Shield

Application: 1980 California CJ Models With Four-Cylinder Engine Built Prior to VIN J0M93AB058103

File: POWER PLANT Fuel & Exhaust Systems

No. 80-3 June 16, 1980

1980 California CJ Models with a four-cylinder engine built after VIN J0M93AB058103 are equipped with a protective shield for the microprocessor (ECM).

This shield may also be installed on 1980 California CJ models with four-cylinder engine that were built prior to VIN J0M93AB058103. Service installation involves affixing a decal to the shield, then installing the shield over the microprocessor (ECM).

The following parts are available for service installation.

Description	Quantity	Part No.	Group
KIT, Shield	1	8130433	3.053
Kit Contents:			
SHIELD,			
Microprocessor			
(ECM)	1	5752624	
DECAL	1	5752657	
RETAINER,			
Shield	2	4200319	
NUT, Shield			
Retainer	2	4200408	

### PROCEDURE

(1) Clean smooth, recessed area on face of shield with isopropyl alcohol and allow area to dry.

(2) Remove backing from decal and affix decal to cleaned area on shield.

NOTE: Do not touch the adhesive surface of the decal after it is exposed.

(3) Remove nuts attaching microprocessor to left inner cowl panel and move microprocessor away from panel. Remove nylon spacers from microprocessor studs and set spacers aside. (4) Disconnect harness connectors from microprocessor and remove microprocessor.

(5) Insert two shield retainers into slots in microprocessor.

(6) Install shield on retainers using two holes in shield as guide. Position shield on microprocessor studs and install shield retainer nuts finger-tight.

(7) Install microprocessor on left inner cowl panel and install nylon spacers on mounting studs with small shoulder of spacers facing microprocessor (see illustration).

(8) Connect plug connectors to microprocessor.

(9) Install and tighten microprocessor attaching nuts to 3 foot-pounds  $(4 \text{ N} \cdot \text{m})$  torque.

NOTE: If the protective felt on the cowl seam near the microprocessor interferes with microprocessor installation, trim the felt as necessary.



**Microprocessor Shield Installation** 

## **VI** American Motors Sales Corporation

80-18

Service Engineering Department • 14250 Plymouth Road • Detroit, Michigan 48232 Additional copies of this bulletin are available through your zone office. The following operation and standard work time will apply:

.

OPERATION DESCRIPTION	COST	OPERATION		YEA	SKILL		
	CODE	NUMBER	MODEL	80	81	82	
SHIELD, MICROPROCESSOR (ECM) INSTALL (California)	4.750	4051	4-Cyl.	0.3	_	-	G
		alain da la seconda da la s				80	-081-04

÷

80-19

Subject: Vacuum Diagram Correction to 1980 Jeep Technical Service Manual Application: 1980 49-State Cherokee and J-10 Truck Models with 360 CID Eight-Cylinder Engine, Manual Transmission, and Heavy Duty Cooling File: POWER PLANT Fuel and Exhaust Systems

No. 80-2 March 12, 1980

The vacuum diagram on page V-23 of the 1980 Jeep Technical Service Manual is incorrect. The diagram is for 49-State Cherokee and J-10 Truck Models equipped with 360 CID eight-cylinder engine, manual transmission, and heavy duty cooling. Please correct your manual by moistening and affixing the attached correction diagram over the existing diagram on page V-23.

80-063-04J

## American Motors Sales Corporation

Service Engineering Department • 14250 Plymouth Road • Detroit, Michigan 48232 Additional copies of this bulletin are available through your zone office.



49 STATE 360 WITH MANUAL TRANSMISSION AND HD COOLING

80-21

Subject: Exhaust Pipe to Exhaust Manifold Leak

Application: 1980 Six-Cylinder Equipped Jeep Models File: POWER PLANT Fuel and Exhaust Systems

No. 80-1 Oct. 31,1979

Some early built six-cylinder engine equipped Jeep vehicles may develop an exhaust leak between the exhaust pipe and exhaust manifold. This may be due to the loss of the design interference locking feature of the locking stud and hexagon nut.

If a leak should occur, service correction involves tightening the existing nut to 20 foot-pounds  $(27 \text{ N} \cdot \text{m})$  torque and installing a second nut to lock it in place.

The following parts are available and will be required.

Description	Quantity	Part No.	Group	
NUT, Hexagon	2	4006567	4.178	

The following operation and standard work time will apply:

PROCEDURE

(1) Raise vehicle.

(2) Tighten existing nuts to 20 foot-pounds (27 N·m) torque.

(3) Turn second nut onto each stud.

(4) While holding first nut, tighten second nut on each stud to 20 foot-pounds  $(27 \text{ N} \cdot \text{m})$  torque.

- (5) Lower vehicle.
- (6) Start engine and check for exhaust leaks.

OPERATION DESCRIPTION	COST	OPERATION	MODEL	YEA	RAND	TIME	SKILL
	CODE	NUMBER	MODEL	80	81	82	LEVEL
NUTS, EXHAUST PIPE FLANGE TO MANI- FOLD TIGHTEN AND INSTALL	4.178	4219	6-Cyl.	0.3			м

80-017-04J

## **VI American Motors Sales Corporation**

Service Engineering Department • 14250 Plymouth Road • Detroit, Michigan 48232 Additional copies of this bulletin are available through your zone office.

80-22

## **/I** Jeep,

# **Diagnosis and Repair Bulletin**

Subject: T-176 Four-Speed Manual Transmission Used in 1980 Four-Cylinder CJ Models Application: 1980 Four-Cylinder CJ Models Built Between VIN J0M93AB725578 and VIN J0M93EB727300 File: CHASSIS Clutch – Manual Transmission

No. 80-4 June 16, 1980

Due to a supplier shortage of SR-4 four-speed manual transmissions, 1980 four-cylinder CJ models built between VIN J0M93AB725578 (March 24, 1980) and VIN J0M93EB727300 (April 22, 1980) were equipped with a T-176 four-speed manual transmission and 4.09:1 ratio axles.

The following parts list outlines the components that are unique to these models.

Description	Quantity	Part No.	Group
TRANSMISSION,			
T-176 (83-93)	1	5359390	6.001
HOUSING, CLUTCH			
(83-93)	1	3251256	5.054
PIPE, Éxhaust (83)	1	5362826	4.178
PIPE, Exhaust (93)	1	5362827	4.178
SHAFT ASSEMBLY,			
Front Propeller	4	5969015	0 100
(83-93)		0002010	9.100

Description	Quantity	Part No.	Group
SHAFT ASSEMBLY,			
Rear (83)	1	5362813	9.100
SHAFT ASSEMBLY			
Rear (93)	1	5362814	9.100
KNOB, Gear Shift			
Lever (83-93)	1	5361405	7.030
LEVER, Floor Gear	10		
Shift (83-93)	1	5359835	7.001
WIRE, Backup Lamp			
(83-93)	1	5751748	3.318
BRACKET,			
Transmission Exhaust			
Pipe Support (83-93)	1	5362829	18.200

The standard servicing operations and work times as published in the current SSO Manual are not affected by this bulletin.

80-121-06J

### **VI** American Motors Sales Corporation

Service Engineering Department • 14250 Plymouth Road • Detroit, Michigan 48232

Subject: Clutch Pedal Return Adjustment

Application: 1980 CJ Models With Manual Transmission and Six- or Eight-Cylinder Engine

File: CHASSIS Clutch - Manual Transmission

No. 80-3 May 28, 1980

- If the clutch pedal on 1980 CJ models with manual (4) Cheat transmission and six- or eight-cylinder engine does not return completely after the pedal is released, the pedal may be adjusted using the procedure provided to or
- Service correction involves adjusting clutch pedal freeplay and installing an additional return spring on the clutch pedal if necessary.
- The following part is available and may be required.

Description	Quantity	Part No.	Group	
SPRING	1	3197208	8.180	

### PROCEDURE

(1) Raise vehicle.

in this bulletin.

(2) Check clutch linkage operation. Repair binding or bent linkage components if necessary.

(3) Adjust clutch pedal freeplay to 1/2- to 3/4-inch maximum freeplay.

The following operation and standard work time will apply:

(4) Check clutch pedal operation.

(a) If pedal returns completely, return vehicle to owner.

(b) If pedal does not return completely, proceed to next step.

(5) Modify hooked-end of spring 3197208 by reshaping it to configuration shown in illustration.



Modifying Spring 3197208

(6) Install modified spring as follows: Install modified end of spring on clutch pedal stop and install opposite (curved end) in unused hole in overcenter spring bracket.

(7) Lower vehicle.

OPERATION DESCRIPTION	CÔŜT CODE	OPERATION NUMBER	MODEL	YEAR AND TIME			SKILL
				80	81	82	LEVEL
SPRING, CLUTCH PEDAL RETURN — INSTALL Includes adjust clutch pedal free play	5.135	5007	83-93	0.3			G

80-103-05J

## I American Motors Sales Corporation

Service Engineering Department • 14250 Plymouth Road • Detroit, Michigan 48232 Additional copies of this bulletin are available through your zone office.

## / Jeep

## **Diagnosis and Repair Bulletin**

Subject: T-176 4-Speed Manual Transmission Shift Problems Application: 1980 Jeep CJ, Cherokee and J-10 Truck Models With T-176 4-Speed Manual Transmission File: CHASSIS Clutch-Manual Transmission

No. 80-2 March 20, 1980

Some early production T-176 4-speed manual transmissions used in the subject models may develop shifting problems such as high shift effort, loose shifting, or the transmission locks in two gears at once preventing vehicle movement with the clutch engaged. These conditions may be the result of loose transmission case cover shift lever fulcrum pins, a damaged reverse rocker arm assembly, missing poppet balls, springs, or interlock rings or burrs on the edges of the shift lever pivot ball.

Service correction involves replacing the transmission case cover and any missing poppet balls, springs and interlocks, and chamfering rough edges on the shift lever pivot ball if necessary.

The following parts are required and will be available the week of April 7, 1980. Do not order parts before this date.

Description	Quantity	Part No.	Group
KIT, Transmission			
Case Cover Repair	1	8130431	6.009
Kit contents:			
Cover Assembly	1	8130429	
Parts Package	1	8130430	

### PROCEDURE

(1) Remove transfer case and transmission shift lever knobs, trim rings and boots.

(2) Remove floor covering and transmission access cover from floorpan.

(3) Shift transmission into third gear.

(4) Remove transmission control housing cap (Fig. 1). Push cap down and turn counterclockwise to remove.

(5) Remove transmission case cover attaching bolts.

(6) Remove transmission case cover.

(7) Position transmission case cover in vise so shift forks are facing upward. Use wood blocks to protect cover from vise jaws and do not overtighten vise.

(8) Place all shift forks in neutral position.

(9) Remove shift rail support plate attaching bolts and tabbed washers and remove support plates (Fig. 1).

(10) Remove first-second shift rail.

(11) Remove third-fourth shift rail, shift lug, and interlock pin.

(12) Remove reverse shift rail.

(13) Remove poppet balls.

(14) Remove shifter interlock rings.

(15) Remove poppet springs.

(16) Remove cover from vise.

(17) Clean all components in solvent and dry using compressed air.

(18) Inspect all components. Replace any components that are nicked, cracked, broken or excessively worn.

(19) Clamp replacement transmission case cover and reverse rocker arm assembly in vise using protective wood blocks and install replacement fulcrum pins in cover.

CAUTION: To avoid damaging the cover do not overtighten the vise jaws.

(20) Lubricate shift rails and shift rail grooves in cover with petroleum jelly.

(21) Install replacement poppet springs in transmission case cover bores.

## American Motors Sales Corporation

Service Engineering Department • 14250 Plymouth Road • Detroit, Michigan 48232



Fig. 1 Transmission Case Cover Assembly – Model T-176

(22) Install poppet balls (one on each spring).

(23) Position reverse gear shift rail and fork on reverse rocker arm in transmission case cover.

NOTE: Be sure the notch on the shift rail is positioned over the reverse poppet ball and that reverse rocker arm is engaged in the reverse fork slot.

(24) Install third-fourth shift rail and shift fork assembly in transmission case cover.

**NOTE:** Be sure the interlock pin is in position in the shift rail before further assembly.

(25) Install first-second shift rail and fork assembly. Be sure shift rail notch is over poppet ball in transmission case cover.

(26) Install shifter interlock rings in cover and between poppet balls.

(27) Press downward on shift rails to compress poppet balls and springs. Use wood block long enough to contact all three shift to rails to press rails down-ward evenly.

(28) While holding shift rails downward, position shift rail retaining plates on housing and install plate attaching bolts and tabbed washers finger-tight. (29) Remove wood block and tighten shift rail retaining bolts to 12-15 foot-pounds (16-19 N·m) torque. Be sure tabbed washers are in correct position before bending washer tabs.

(30) Check shift rail operation. Each rail must slide smoothly in cover groove. Be sure it is not possible to over shift into another gear position. After checking shift operation, place forks in third gear position.

(31) Install replacement gasket on transmission case cover.

(32) Install transmission case cover and gasket on transmission. Be sure all shift forks are seated in corresponding gear sleeves, and be certain that reverse fork is seated in reverse sliding gear groove. (33) Apply sealant to threads of transmission case cover attaching bolts.

(34) Install two transmission case cover shoulder bolts (only) to hold cover in position. Tighten bolts to 12-15 foot-pounds (16-19  $N \cdot m$ ) torque.

(35) Grind and file edges of shift lever pivot ball slot to approximate chamfer of 1/32-inch (Fig. 2). This will ensure smooth contact surface with fulcrum pins in transmission case cover.

(36) Install shift lever, spring, spring retainer, and control housing cap (Fig. 1). Push cap downward and turn clockwise to install and seat. Be sure transmission is still in third gear before installing shift lever.

(37) Check shift operation in all gear positions. If operation is OK, install and tighten remaining case cover attaching bolts to 12-15 foot-pounds (16-19  $N \cdot m$ ) torque. If shift problem persists, loosen cover attaching bolts and align cover on transmission case.

(38) Install access cover, floor covering, boots, trim rings, and shift lever knobs.





The following standard servicing operation and work times will apply:

	COST OPERATIC			YEA	YEAR AND TIME		
OPERATION DESCRIPTION	CODE	NUMBER	MODEL	YEAR AND       80     81       0.7     0.9       0.5     0.5	81	82	LEVEL
COVER, TRANSMISSION CASE – R & R Includes replace gasket	6.009	6006	83-93 Cke-Trk	0.7 0.9			G
Transmission case cover Overhaul With carpet Add	6.009	A		0.5 0.1			G
		<u>.                                    </u>				80	)-065-06J

/ Jeep,

Subject: Inspection of Clutch Housing and Clutch Lever Clearance Application: 1980 Cherokee, Wagoneer and Truck Models with Manual Transmission Built Prior to VIN JOD25NN008776 File: CHASSIS Clutch-Manual Transmission

No. 80-1 Jan. 11, 1980

If one of the specified vehicles requires clutch service, the clutch housing and clutch lever clearance must be inspected.

On the specified vehicles, service correction requires an initial inspection to determine which clutch housing has been installed and modification and/or replacement of the clutch housing as necessary.

The following parts may be required and will be available after Jan. 7, 1980. Do not order parts before this date.

Description	Quantity	Part No.	Group
HOUSING, Clutch			
15-16-17-18-25-45			
(6-Cyl.)	1	3238423	5.054
HOUSING, Clutch			
15-16-17-18-25-45			
(V-8)	1	3235827	5.064
HOUSING, Clutch			
46 (V-8)	1	3235826	5.054
STUD.			
Adapter-to-Clutch			
Housing	1	5356352	5.054
NUT. Hex			
(9/16 inch			
x 12)	1	G9419144	6.005
WASHER, Lock			
(9/16  inch)	1	G120898	17.820
(0,20			

### INSPECTION PROCEDURE

(1) Raise vehicle.

(2) Inspect clutch housing release lever opening. If opening is 3-1/2 inch x 2-1/8 inch, replace housing as described in Clutch Housing Replacement and Modification Procedure.

(3) Loosen clutch lever release lever boot and read casting numbers (see illustration).

- a. On six-cylinder engines:
  - Casting number must be 3238422.
    - If not, replace housing.



**Clutch Housing Inspection** 

- b. On eight-cylinder engines:
- Casting numbers must be 3235887 or 3238422.
- On J-20 Trucks left lower transmission bolt (next to lever opening) must be removed and shortened to 1.25 inch (32 mm).

## I American Motors Sales Corporation

Service Engineering Department • 14250 Plymouth Road • Detroit, Michigan 48232

**NOTE:** If transmission bolt threads are damaged in clutch housing on J-20 Trucks, refer to Clutch Housing Replacement and/or Modification Procedure.

(4) Inspect core injection boss (see illustration) for interference with clutch throwout lever. If throwout lever is contacting ejection boss, refer to Core Ejection Boss Removal Procedure.

### CORE EJECTION BOSS REMOVAL PROCEDURE

(1) Remove front propeller shaft at front axle U-joint yoke.

(2) Using long punch, centerpunch starter hole in boss.

(3) Using 3/8 inch drill bit, drill hole through boss.

(4) Using sharp chisel, chip away remainder of boss.

(5) Remove clutch housing inspection plate. Use compressed air to remove all loose metal.

(6) Install clutch housing inspection plate.

(7) Install boot and connect clutch linkage and adjust pedal free play.

(8) Install front U-joint straps and bolts and tighten to 15 foot-pounds (23 N·m) torque.

(9) Lower vehicle.

### CLUTCH HOUSING REPLACEMENT AND/OR MODIFICATION PROCEDURE

(1) Disconnect battery negative cable.

(2) Remove shift and transfer case lever boot.

**CAUTION:** Be sure shift lever pin does not fall into transmission.

(3) Unscrew shift lever cap, remove pin and shift levers.

(4) Mark front and rear propeller shafts and yokes for assembly reference. Disconnect rear propeller shaft at transfer case.

(5) Disconnect speedometer cable at transfer case.

(6) Disconnect parking brake cable at crossmember and at C-clips.

(7) Support transmission, disconnect rear crossmember bolts and remove crossmember. (8) Disconnect transfer case shift rod at transfer case.

(9) Disconnect front propeller shaft at transfer case.

(10) Remove lower bolts from adapter plate to transmission. Loosen exhaust pipe bracket and remove exhaust support.

(11) Disconnect transfer case vent hose and lockout switch connectors.

• (12) Support transfer case. Remove upper bolts from adapter to transmission and remove transfer case.

(13) Disconnect backup light switch connector from transmission.

(14) Support engine. Remove transmission bolts at clutch housing and remove transmission.

(15) Remove starter motor bolts and cable and remove starter motor.

(16) Remove clutch release idler pivot bolts and disconnect adjuster and lever spring.

(17) Remove inspection plate.

(18) Remove clutch housing bolts and housing.

(19) Remove clutch throwout lever spring, lever, throwout bearing, and pivot ball from housing.

CAUTION: Do not allow the hole to be machined larger than 0.6250 inch.

(20) On J-20 Truck, drill out lower left (next to lever opening) transmission hole to 5/8 inch. Coat lower half of stud (opposite-threaded end) with Loctite 271 or equivalent. Press stud into housing.

(21) Completely remove core ejection boss, if present, following steps (2) through (4) of Core Ejection Boss Removal Procedure.

NOTE: This step applies to an original or a new clutch housing if the core ejection boss is found.

(22) Coat pivot ball with grease and install in clutch housing.

(23) Install clutch housing, tighten top retaining bolts to 30 foot-pounds (41 N·m) torque. Tighten dowel bolts to 45 foot-pounds (61 N·m) torque.

(24) Install starter motor	. Tighten bolts to 20 foot-
pounds (27 N·m) torque	e. Tighten starter terminal
nut to 55 inch-pounds (6 J	N·m) torque.



(25) Install inspection cover, inner support bracket with bellcrank, and tighten bolts to 14 foot-pounds  $(19 \text{ N} \cdot \text{m})$  torque.

(26) Install transmission aligning clutch shaft and clutch driven plate splines and tighten bolts to 55 foot-pounds  $(75 \text{ N} \cdot \text{m})$  torque.

(27) Install clutch throwout lever boot. Loosen jamnut and adjuster to obtain freeplay. Align linkage to throwout lever and remove freeplay.

(28) Connect backup lamp switch wires.

(29) Clean mating surface of transmission and transfer case, apply Permatex No. 3 or equivalent sealer to both sides of replacement transfer case-to-transmission gasket and position gasket on transmission.

(30) Align and install transfer case assembly. Be sure transfer case input gear splines are aligned with transmission output shaft.

NOTE: Do not install any transfer case attaching bolts until transfer case is completely seated against transmission.

(31) Attach exhaust pipe support bracket. Install transfer case retaining bolts and tighten to 40 foot-pounds (54  $N \cdot m$ ) torque.

(32) Tighten exhaust pipe clamp.

The following operation and standard work times will apply:

YEAR AND TIME COST OPERATION SKILL **OPERATION DESCRIPTION** MODEL CODE NUMBER LEVEL 80 81 82 HOUSING, CLUTCH-INSPECT ..... 5.054 5031 G Wag-0.1 Cke-Trk J-20 G 5.054 0.1 Bolt, Transmission-Shorten..... A G B Boss, Core Ejection-Remove ..... 5.0540.5Housing, Clutch- Replace G C 2.4 5.054and/or Modify.....

(33) Connect vent line and retaining clip. Connect lockout switch connector.

(34) Connect transfer case shift rod, wave washer, flat washer and cotter pin.

(35) Install speedometer cable.

(36) Install front propeller shaft using reference marks made during removal. Tighten shaft-to-yoke bolts to 15 foot-pounds (20 N·m) torque.

(37) Install crossmember. Tighten bolts to 35 footpounds (48 N·m) torque. Remove support stand.

(38) Connect parking brake cable and adjust.

(39) Install rear propeller shaft using reference marks made during removal. Tighten bolts to 15 footpounds (20 N·m) torque.

(40) Check and refill transmission and transfer case if necessary.

(41) Install gear shift lever, locating pin and tighten shift lever cap.

(42) Install shift lever and transfer case lever boot.

(43) Connect battery negative cable.

(44) Reset clock.

(45) Check and adjust clutch pedal freeplay if necessary.

(46) Check transmission and transfer case for proper shifting.

80-022-05J

## Jeep,

# **Diagnosis and Repair Bulletin**

Subject: Moan or Buzzing Noise From Automatic Transmission When Shifting Into Reverse Application: 1980 Jeep CJ Models With Model 999 Automatic Transmission Built Prior To Build Date Code 6863 File: CHASSIS Automatic Transmission

No. 80-1 Mar. 17, 1981

On some 1980 CJ models with a model 999 automatic transmission built prior to build date code 6863, the transmission may occasionally produce a moan or buzzing noise when shifted into reverse or when the gearshift selector lever is between the Park and Reverse detents. This condition may be caused by the normal rapid flow of transmission fluid over the finely machined center land of the switch valve in the transmission valve body. On transmissions built after date code 6863, a new switch valve with an undercut center land was phased into production and is now available for service (see illustration). The new valve design eliminates the possibility of any occasional noise caused by normal fluid flow over the center land.

Service correction involves verifying the condition using the diagnosis procedure provided in this bulletin and installing the new switch valve if diagnosis indicates this is necessary.

The following part is available and may be required.

Description	Quantity	Part No.	Group
VALVE. Switch	1	8130452	16.495

### **DIAGNOSIS PROCEDURE**

- Check transmission build date code. If transmission was built prior to date code 6863, proceed to step (2). If transmission was built after date code 6863, refer to automatic transmission diagnosis section in Chapter 2C of Technical Service Manual for additional diagnosis.
- (2) Apply parking brake firmly.
- (3) Start engine and apply service brakes.
- (4) Shift transmission into all gear ranges; then shift transmission into Neutral.
- (5) Check transmission fluid level and condition as outlined in Technical Service Manual. Correct fluid level if necessary.



PREVIOUS SWITCH VALVE DESIGN



NEW SWITCH VALVE DESIGN

Switch Valve Comparison

- (6) Apply service brakes and shift transmission into Reverse.
- (7) Increase engine speed until moan or buzzing noise occurs. Maintain engine speed at point where noise is loudest for approximately one minute then return engine to idle speed.

**CAUTION:** If the noise is loudest at an engine speed that is at or near torque converter stall speed, do not maintain engine speed for more than 5 seconds.

- (8) Shift transmission into Park, remove dipstick immediately, and inspect oil on dipstick for evidence of foaming (aeration).
  - (a) If oil does not display evidence of foaming (aeration), proceed to Switch Valve Replacement procedure.
  - (b) If oil does display evidence of foaming, refer to automatic transmission diagnosis section in Chapter 2C of Technical Service Manual for additional diagnosis.

## **FI American Motors Sales Corporation**

Service Engineering Department • 14250 Plymouth Road • Detroit, Michigan 48232

### **Switch Valve Replacement**

- (1) Raise vehicle on hoist.
- (2) Remove transmission oil pan and valve body as outlined in Chapter 2C of Technical Service Manual.
- (3) Remove oil filter from valve body.
- (4) Remove screws that attach throttle pressure adjusting screw spring retainer and bracket and remove retainer and bracket. Hold retainer and bracket firmly against spring force while removing last attaching screw.
- (5) Release pressure applied to spring retainer and bracket and remove bracket, line pressure adjusting screw assembly, line presure regulator spring, switch valve spring, and switch valve. Do not disturb line and throttle pressure adjusting screw settings during removal.
- (6) Install replacement switch valve in valve body bore. Be sure valve is new-type with undercut on center land (see illustration).
- (7) Install switch valve and line pressure regulator springs.

- (8) Install line pressure adjusting screw assembly and spring retainer and bracket. Tighten bracket attaching screws to 35 inch-pounds (4 N·m) torque.
- (9) Install replacement oil filter on valve body. Tighten filter attaching screws to 35 inch-pounds (4 N·m) torque.
- (10) Install valve body and oil pan as outlined in Chapter 2C of Technical Service Manual.
- (11) Lower Vehicle.
- (12) Fill transmission to correct level with AMC, Dexron, or equivalent automatic transmission fluid.
- (13) Verify noise correction by performing steps (2) through (7) of Diagnosis Procedure again.
  - (a) If noise is eliminated, return vehicle to owner.
  - (b) If some noise is still present, check for restriction in transmission oil cooler and cooler lines and correct as necessary. Refer to oil cooler and cooler line flushing procedure in Technical Service Manual.

The following standard servicing operations and work times will apply:

OPERATION DESCRIPTION	COST OPERATION CODE NUMBER		YEAR AND TIME			SKILL	
		NUMBER	MODEL	79	80	81	LEVEL
NOISE AUTOMATIC TRANSMISSION — DIAGNOSE Switch valve — Replace Includes oil pan and valve body R & R	36.495	16221 A	904-998	0.1 0.8	0.1 0.8		G G

81-068-16A/J



FILE: Axles-Suspension-Brakes-Steering (CHASSIS -Transfer Case/Quadra-Trac)

No. 3-04-82 Mar. 8, 1982

# **TECHNICAL BULLETIN**

PROBLEM ANDTransfer case shift lever rattles or makes a buzzing noise in someAPPLICATION:1980-82 CJ and Scrambler models.

CORRECTION: Install a flat washer and rubber bumper on the transfer case shift lever ball-end (see illustration).

PARTS:	Description	Quantity	Part Number	Group
	WASHER, Flat	1	G131016	17.814
	BUMPER, Rubber	1	637936	35,300

WARRANTY Reimbursable within the provisions of the applicable warranty. ELIGIBILITY:

SSO INFORMATION:

Operation Description	Cost Code	Operation Number	Model	Year -80-	and -81-	Time -82-	Skill Level
LEVER, TRANSFER CASE SHIFT - MODIFY	18.135	18019	CJ	0.2	0.2	0.2	G

### **PROCEDURE:**

- 1. Raise the vehicle.
- 2. Remove the shifter shaft nut and slide the shifter shaft out of the shift lever.
- 3. Lift the shift lever upward and out of the shift control link.
- 4. Install the flat washer and rubber bumper on the ball-end of the shift lever (see illustration). Be sure the flat washer is seated against the shoulder at the ball-end of the shift lever.

### (continued)

### **VI** American Motors Sales Corporation

Service Engineering Department • 14250 Plymouth Road • Detroit, Michigan 48232 Additional copies of this bulletin are available through your zone office. 5. Seat the shift lever firmly in the shift control link. Reinsert the shifter shaft into the shift lever and front output bearing cap and install the shifter shaft nut.

-2-

6. Lower the vehicle.





.

71 Jeeo

Subject: Transfer Case Drive Sprocket Thrust Washer Noise Application: 1980 Jeep Cherokee, Wagoneer, and Truck Models with Model 208 Transfer Case File: CHASSIS — Transfer Case/ Quadra-Trac

No. 80-3 Oct. 2, 1981

On some 1980 Cherokee, Wagoneer, and Truck models with a model 208 transfer case, the transfer case drive sprocket thrust washer inside diameter may have a rough surface finish that could cause a squeal noise to occur occasionally. The noise is most noticeable in the 30-55 mph range and only when the transfer case is in two wheel drive high (2H) position, the front hubs unlocked, and when the transfer case is at normal operating temperature.

Service correction involves road testing to verify the noise condition and replacing the transfer case drive sprocket thrust washer if necessary.

The following parts may be required and will be available after October 19, 1981. Do not order parts before this date.

Description	Quantity	Part No.	Group
WASHER, Thrust	1	8134130	18.820
SEAL, Output	1	8133432	18.870

#### PROCEDURE

- (1) Road test vehicle in 30-55 mph range with hubs unlocked and with transfer case in two-high position and at normal operating temperature.
  - (a) If squeal noise occurs, proceed to step (2).
  - (b) If squeal noise does not occur, thrust washer is not problem. Refer to 1980 Jeep Technical Service Manual for additional diagnosis.
- (2) Raise vehicle on hoist.
- (3) Position drain pan under transfer case. Remove fill plug and drain plug and drain lubricant from transfer case.
- (4) Mark rear propeller shaft and transfer case yoke for assembly alignment reference.
- (5) Disconnect rear propeller shaft from transfer case yoke and secure shaft to underside of vehicle.
- (6) Remove speedometer adapter and cable.
- (7) Remove and discard transfer case rear yoke retaining nut and seal. Use tool J-8614-01 to hold yoke while removing nut.

- (8) Remove transfer case rear yoke using tools J-8614-01, -02, -03 if necessary.
- (9) Inspect output seal in rear retainer if seal exhibits signs of oil leakage, remove and discard seal.
- (10) Remove speedometer driven gear and sleeve from rear retainer.
- (11) Mark rear retainer for assembly alignment reference and remove retainer attaching bolts. Tap retainer with rubber mallet to loosen it and remove retainer.
- (12) Remove pump housing.
- (13) Remove speedometer gear.
- (14) Remove oil pump.
- (15) Remove drive sprocket retaining ring.
- (16) Remove and discard drive sprocket thrust washer (see illustration).



Drive Sprocket Thrust Washer Removal/Installation

### **VI** American Motors Sales Corporation

- (17) Clean rear case and rear retainer mating surfaces thoroughly.
- (18) Check pump housing seal for nick, cuts, or signs of abrasion. Replace seal if damaged.
- (19) Lubricate replacement drive sprocket thrust washer with 10W-30 motor oil and install thrust washer.
- (20) Install drive sprocket retaining ring.
- (21) Install oil pump.
- (22) Install speedometer gear.
- (23) Install output seal in retainer if necessary.
- (24) Lubricate lip of rear seal and pump housing seal and tabs of pump housing with petroleum jelly.
- (25) Install pump housing in rear retainer.
- (26) Apply Loctite 515, or equivalent sealer, to mating surfaces of rear case and rear retainer.
- (27) Align rear retainer and rear case index marks and install rear retainer on case. Install and tighten rear retainer attaching bolts to 23 foot-pounds (31 N·m) torque.

- (28) Install transfer case rear yoke and install replacement yoke seal and retaining nut. Tighten retaining nut to 120 foot-pounds (163 N-m) torque.
- (29) Install replacement O-ring on speedometer adapter and install adapter and cable. Tighten adapter retainer bolt to 100 inch-pounds (11 N·m) torque.
- (30) Install and tighten drain plug to 18 foot-pounds (24 N·m) torque.
- (31) Fill transfer case to edge of fill plug hole with 10W-30 motor oil.
- (32) Install and tighten fill plug to 18 foot-pounds (24 N·m) torque.
- (33) Connect rear propeller shaft to transfer case yoke. Align shaft and yoke using reference marks made at disassembly. Tighten shaft clamp strap bolts to 14 foot-pounds (19 N·m) torque.
- (34) Lower vehicle and verify proper transfer case operation.

The following standard servicing operations and work times will apply:

OPERATION DESCRIPTION	COST CODE		MODEL	YEAR AND TIME			SKILL
				80	81	82	LEVEL
ROAD TEST (c)		0717		0.3			G
DRIVE SPROCKET THRUST WASHER — REPLACE	18.350	18.011	Cke-Wag-Trk	0.8			G

#### 81-109-18J
# **Diagnosis and Repair Bulletin**

Jeep.

Subject: Transfer Case Output Shaft Seal Leak Diagnosis Application: 1980-81 Jeep Vehicles Equipped with Model 219 Quadra-Trac Transfer Case File: CHASSIS Transfer Case/Quadra-Trac

No. 81-1 Feb. 23, 1981

On some 1980-81 Jeep vehicles with a model 219 Quadra-Trac transfer case built prior to 10-28-80, the adhesive tape strip on the vent chamber seal may separate from the seal and block the rear retainer vent passage. If the vent passage becomes blocked, pressure buildup within the transfer case could cause lubricant to leak from one or both output shaft seals and be incorrectly diagnosed as a seal problem. Model 219 transfer cases built on or after 10-28-80 have a new self adhering vent chamber seal that does not require an adhesive tape strip.

Service diagnosis and correction of a leak condition involves first checking the transfer case build date, replacing the vent chamber seal if necessary, and replacing one or both output shaft seals if diagnosis indicates this is necessary.

The following parts are available and required:

Description	Quantity	Part No.	Group
SEAL, Vent Chamber	1	8133743	18.000
SEAL, Front and Rear	AR	8130808	18.000

### PROCEDURE

### Vent Chamber and Rear Output Shaft Seal Replacement

- (1) Raise vehicle on hoist.
- (2) Remove transfer case fill and drain plugs and drain hubricant from transfer case.
- (3) Mark rear propeller shaft and transfer case yoke for assembly alignment reference.
- (4) Disconnect rear propeller shaft at transfer case yoke and secure shaft to underside of vehicle.

- (5) Remove and discard transfer case rear yoke nut and seal washer. Use tool J-8614-01 to hold yoke while removing nut.
- (6) Remove rear yoke using tools J-8614-01, 02, 03, if necessary.
- (7) Remove speedometer cable and adapter from rear retainer. Discard adapter seal, it is not reusable.
- (8) Mark rear retainer and rear case half for assembly alignment reference and remove rear retainer bolts and retainer. Tap retainer with rawhide or plastic mallet to loosen and pry retainer from case using slots in retainer only.
- (9) Remove vent chamber seal from retainer interior and clean seal mating surface in retainer thoroughly. Clean mating surfaces of retainer and rear case and dry both surfaces thoroughly.
- (10) If diagnosis indicated that rear output seal (in retainer) was leaking, remove seal and clean seal bore in rear retainer thoroughly.
- (11) Coat outer edge of replacement output seal with silicone sealer and install seal in retainer using tool J-29162.
- (12) Install replacement vent chamber seal. Remove seal adhesive protector strip and position seal over vent hole inside retainer. Be sure hole in seal is aligned with hole in retainer and that length of vent seal is parallel with front face of retainer.
- (13) Coat retainer mating surface of rear case with silicone sealer.
- (14) Align rear retainer and rear case reference marks and install retainer on case.
- (15) Install and tighten retainer attaching bolts to 23 foot-pounds (31 N.m) torque.
- (16) Install rear yoke, replacement yoke seal washer, and replacement nut. Tighten nut to 120 footpounds (163 N.m) torque.

# **FE American Motors Sales Corporation**

Service Engineering Department e 14250 Plymouth Road e Detroit, Michigan 48232

Additional copies of this bulletin are available through your zone office.

**CAUTION:** Do not attempt to reuse the original yoke nut. This nut is a self locking design and should not be reused.

(17) Install replacement speedometer adapter seal and install speedometer driven gear assembly in transfer case.

**NOTE:** Do not reuse the adapter O-ring seal, it is designed to swell in service to provide improved sealing qualities and could be cut or torn if reuse is attempted.

- (18) Install and tighten transfer case drain plug to 18 foot-pounds (24 N.m) torque.
- (19) Align and connect rear propeller shaft to yoke using assembly alignment reference marks. Tighten clamp strap bolts to 15 foot-pounds (20 N.m) torque.

**NOTE:** If diagnosis indicated that the front output shaft seal was leaking, proceed to Front Output Shaft Seal Replacement.

- (20) Fill transfer case to edge of fill plug opening with 10W30 motor oil, API grade SF or SE.
- (21) Install and tighten transfer case fill plug to 18 foot-pounds (24 N.m).
- (22) Lower Vehicle.

### Front Output Shaft Seal Replacement

(1) Mark front propeller shaft and transfer case yoke for assembly alignment reference.

- (2) Disconnect front propeller shaft from yoke and secure shaft to underside of vehicle.
- (3) Remove and discard transfer case front yoke nut and seal washer. Use tool J-8614-01 to hold yoke while removing nut.
- (4) Remove transfer case front yoke using tools J-8614-01, 02, 03, if necessary.
- (5) Remove front output shaft seal. Clean seal bore thoroughly.
- (6) Coat replacement front output seal outer surface with silicone sealer.
- (7) Install replacement output seal in front case bore using tool J-29162.
- (8) Install front yoke, replacement yoke seal washer, and replacement yoke nut. Tighten yoke nut to 120 foot-pounds (163 N.m) torque.

**CAUTION:** Do not attempt to reuse the original yoke nut. It is a self-locking design and should not be reused.

- (9) Align and connect front propeller shaft to yoke using assembly reference marks. Tighten clamp strap bolts to 15 foot-pounds (20 N.m) torque.
- (10) Fill transfer case to edge of fill plug hole with 10W30 motor oil, API grade SE or SF.
- (11) Install and tighten fill plug to 18 foot-pounds (24 N.m) torque.
- (12) Lower vehicle.

The following standard servicing operations and work times will apply:

	COST OPERATION		YEAR AND TIME			SKILL	
OPERATION DESCRIPTION	OPERATION DESCRIPTION CODE NUMBER MODEL		MODEL	80	81	82	LEVEL
SEAL, VENT CHAMBER — REPLACE Includes rear bearing retainer R & R and rear output shaft replacement if	18.436	18009	Cke-Wag -Trk	0.8	0.8		G
necessary SEAL, FRONT OUTPUT SHAFT - REPLACE	18.218	18007	Cke-Wag -Trk	0.6	0.6		G
					<b></b>		_ <u></u>

81-046-18A/J

# / Jeep.

# **Diagnosis and Repair Bulletin**

Subject: Transfer Case Shift Lever Rattle

Application: 1980 Cherokee. Wagoneer, and Truck Models With Automatic Transmission

(4) Install shift lever on shift rod.

on shift rod (see illustration).

(6) Install cotter pin.

lever operation.

File: CHASSIS Transfer Case

No. 80-2 July 29, 1980

Some 1980 Cherokee, Wagoneer, and Truck models with automatic transmission may develop a transfer case shift lever rattle. The rattle occurs at the point where the transfer case shift lever is connected to the upper shift rod (see illustration).

Service correction involves installing a spring washer and flat washers on the upper shift rod to decrease clearance between the shift rod and shift lever.

The following parts are required.

Description	Quantity	Part No.	Group
WASHER, Spring	1	815535	7.125
WASHER, Flat	2	943961	7.125
PIN, Cotter	1	4004295	23.406

### PROCEDURE

(1) Raise vehicle on hoist.

(2) Remove shift lever-to-shift rod retainer and disconnect lever from rod.

(3) Install one flat washer on shift rod (see illustration).

The following standard servicing operation and work time will apply:

OPERATION DESCRIPTION	COST CODE	OPERATION NUMBER	MODEL	YEAR AND TIME			SKILL
				80	81	82	LEVEL
LEVER, TRANSFER CASE SHIFT — Correct	18.450	18049	Cke- Wag-Trk	0.2			G

80-133-09J

# **VI** American Motors Sales Corporation

Service Engineering Department • 14250 Plymouth Road • Detroit, Michigan 48232 Additional copies of this bulletin are available through your zone office.

### 80-39



(5) Install spring washer and remaining flat washer

(7) Lower vehicle and check transfer case shift

**Correcting Transfer Case Shift Lever** 

# / Jeep

# **Diagnosis and Repair Bulletin**

Subject: Transfer Case Shift Lever and Shaft Replacement

**Application: 1980 CJ Models** 

File: CHASSIS Transfer Case/ Quadra-Trac

No. 80-1 Jan. 9, 1980

Some 1980 CJ models may have a transfer case that is difficult to shift. This may be the result of the transfer case shift lever shaft being bent at the threaded end.

Service correction involves replacement of the shift lever shaft and lever, if necessary.

The following parts are required and well be available the week of Jan. 28, 1980. Do not order parts before this date.

Description	Quantity	Part No.	Group
SHAFT, Transfer Case Shift	1	5360045	18.180
LEVER, Transfer Case 83-93(w/4-cyl. and SR 93(w/6 or 8-cyl. and T176)	4) 1	5360044	18.125
LEVER, Transfer Case 93(w/SR4 and 6-cyl.)	1	5360129	18.125

### PROCEDURE

(1) Remove transfer case as outlined in Chapter 2D of 1980 Technical Service Manual and remove broken shift lever shaft from transfer case.

(2) Inspect shift lever and replace if bent, distorted or fractured. If fractured, be sure to remove threaded portion of shift lever shaft from shift lever.

(3) Install replacement shift lever shaft on transfer case.

(4) Install transfer case as outlined in Chapter 2D of 1980 Technical Service Manual.

The following standard servicing operations and work times will apply:

OPERATION DESCRIPTION	COST CODE	OPERATION NUMBER	MODEL	YEAR AND TIME			SKILL
				80	81	82	LEVEL
CASE ASSEMBLY, TRANSFER-R & R Shaft, Shift Lever-Replace	18.135 18.135	18000 E	83-93	1.0 0.1			G G

80-041-09J

### **71** American Motors Sales Corporation





Date: June 19, 1980 Application: 1979-80 Jeep Cherokee, Wagoneer and J-10 Trucks File: CHASSIS-Prop. Shaft-Axles

This is a Type "S" Product Recall Campaign subject to all campaign procedures and involving safety-related elements.

Some 1979 and 1980 Jeep Cherokee, Wagoneer and J-10 Truck models equipped with the AMC/Jeep rear axle built between 1979 VIN numbers J9A18NN069283 and J9F45NC154704 and 1980 VIN numbers J0E18NN000048 and J0D45NN024993 may have rear wheel bearing retainers and seals on some of the subject models which may have been assembled improperly during production. This condition could result in wheel bearing damage and possible disengagement of the wheel and axle shaft from the axle while the vehicle is in motion.

Service correction involves an inspection to determine what type of axle (Dana or AMC/Jeep) is in the vehicle and replacement of *BOTH* right and left rear wheel bearings, seals, retainer rings, and retainer plates on AMC/Jeep axles.

The following parts kit is required:

NOTE: Each vehicle will require TWO kits.

Description	Qtv.	Part No.	Group	Price
KIT Bear Wheel			<u></u> -	
Bearing	2	8130510	8.300	\$13.40

KIT Contents: inner oil seal, retaining ring, wheel bearing, outer seal, retainer plate

The Zone will provide a VIN list and an initial supply of parts equal to 40% of the vehicles on your VIN list for each dealer with any vehicles involved. However, the campaign procedures apply to all dealers. On all undelivered, campaign-involved vehicles, the correction must be made before the vehicle is sold or otherwise put in service.

Additional parts can be ordered, as needed, on or after July 7, 1980. Because campaign parts supplies are limited, replacement rear wheel bearing kits are not to be ordered for dealer stock!

### **INSPECTION PROCEDURE**

(1) Raise and support vehicle.

(2) Inspect rear axle housing cover to determine what type of axle is in vehicle.

(a) If axle has round, dome shaped cover (Fig. 1), vehicle has AMC/Jeep axle and will require repair if campaign identification mark is not present. Place campaign-inspection identification paint mark on cover (Fig. 1) and proceed to repair procedure.

(b) If axle has oval, irregular shaped cover (Fig. 1), vehicle has Dana axle and does not require any repairs.

(3) Lower vehicle.



Fig. 1 Axle Housing Cover Identification

### JEEPAXLE REPAIR PROCEDURE

### **Axle Shaft and Bearing Removal**

- (1) Raise and support vehicle and remove rear wheels.
- (2) Remove rear brake drums.

**NOTE:** Make sure that the brake linings are kept free of grease and oil.

(3) Remove nuts attaching brake support plates and retainers to axle tube flanges. Nuts are accessible through holes in axle shaft flanges.

(4) Remove axle shafts using Adapter Tool J-21579 and Slide Hammer J-2619-01 (See Fig. 2).



Fig. 2 Axle Shaft Removal ---Cherokee-Wagoneer-J-10 Truck

(5) If cup portion of wheel bearing assembly remains in the axle housing after the axle shafts are removed, remove the bearing cups using tools J-2619-01 and J-26941.

(6) Remove axle shaft inner oil seals from axle housing tubes.

### **Axle Shaft Bearing Replacement**

**CAUTION:** Under no circumstance should the axle shaft retaining ring or bearing be removed using a torch. Heat will transfer into the axle shaft bearing journal and weaken it.

(1) Mount axle shaft in vise. Use protective jaws on vise to avoid scratching or damaging shaft.

(2) Drill ¼-in. (6mm) diameter hole in retaining ring. Hole depth should be approximately three-fourths of ring thickness.

CAUTION: Do not allow drill to contact the axle shaft.

(3) Position a chisel over the drilled hole in the retaining ring and cut a deep groove in the retaining ring with the chisel. This will enlarge or split the ring allowing the ring to be removed from the axle shaft (See Fig. 3).

(4) Slide retaining plate and oil seal toward axle shaft flange to provide room for bearing removal tool between seal and bearing.

(5) Remove axle shaft bearing using arbor press and tool J-22912-01 or J-23674 (See Fig. 4).

(6) Inspect axle shaft bearing and seal surfaces for scratches. Remove scratches using crocus cloth.

(7) Install retainer plate on axle shaft.



Fig. 3 Notching Bearing Retaining Ring — Cherokee-Wagoneer-J-10 Truck Axle

(8) Pack wheel bearing lubricant in cavity of replacement oil seal and between seal lips and install seal on axle shaft seat. Outer face of seal must face axle shaft flange.

**NOTE:** In order to prevent damaging the seal, it is important that the seal lips be lubricated before installation and that the seal lips contact the machined portion of the shaft only.

(9) Pack replacement wheel bearing with wheel bearing lubricant. Force lubricant through cup rib ring end until it comes out at other end, around bearing.

(10) Install wheel bearing on axle shaft. Be sure cup rib ring is facing axle shaft flange.

(11) Install bearing retainer ring on axle shaft.

(12) Press bearing and retainer ring on axle shaft simultaneously using tool J-22192-01 or J-23674 and



Fig. 4 Axle Shaft Bearing Removal — Cherokee-Wagoneer-J-10 Truck Axle

arbor press. Be sure bearing and retainer ring are properly seated (squarely) against axle shaft shoulder.

**NOTE:** When the seal and bearing seat against each other, some lubricant should be forced out of the other side of the bearing.

### Axle Shaft and Bearing Installation

(1) Clean inner oil seal and bearing bores in axle housing tube and install replacement inner seal using tool J-25135-01, then apply wheel bearing lubricant to seal and to bottom one-third of cavity between seal and bearing bore shoulder.

(2) Apply thin coating of wheel bearing lubricant to outside diameter of wheel bearing cup and outer oil seal.

**CAUTION:** Take care to avoid damaging the oil seal when installing the shaft.

(3) Insert splined end of shaft into differential side gears and start cup rib rings and seals into axle tube.

(4) Align retainer plate and bolts and push axle shaft into housing as far as possible. Install nuts on bolts finger tight only.

**NOTE:** The outer oil seal must be squarely seated against the bearing.

(5) Tighten all nuts alternately and evenly in a cross pattern (Fig. 5) to approximately 15 foot-pounds (20 N.m.) torque to seal and cup rib ring evenly in axle tube. **CAUTON:** This procedure is necessary to ensure that the seal and bearing cup rib ring are seated squarely in the axle tube. The seal can be damaged if this procedure is not followed.



Fig. 5 Axie Tube Flange Bolt and Nut Tightening Sequence

(6) Tighten nuts to final torque of 50 foot-pounds (68 N.m) torque in a cross pattern (Fig. 5).

(7) Install rear brake drum, locknuts and wheels. Tighten rear wheel nuts to 72 foot-pounds (98 N.m.) torque.

(8) Remove supports and lower vehicle.

**ALPHA** SERVICE CODE YEAR & TIME SKILL **OPERATION DESCRIPTION** FOR CLAIM MODEL -79--80-LEVEL **REAR AXLE** — Inspect & Identify (includes Drive-In/Drive out) ..... A Wag-Che Truck 0.1 0.1 G BEARINGS, REAR AXLE SHAFT — Replace both sides (includes inspection and Drive-in/Drive-out) ..... B 1.4 1.4 G

# The following operation and standard work time will apply:

### **CLAIM HANDLING & CAMPAIGN REPORTING**

Owners of record will be mailed the AMC and Jeep combined Product Recall Campaign Notice and Claim Form (Fig. 6). This form is to be used in place of a warranty claim and a campaign reporting card.

This Product Recall Campaign Notice and Claim Form is a six-page form that is pre-printed with the customer's name and address and the campaign name and number. The entire form will be mailed to the owner of record along with a cover letter outlining the defect and instructions to present the complete form to the dealer at the time the vehicle is serviced.

The six copies are:

Cover Sheet: contains instructions for the owner and shows the dealer where to imprint his dealer plate.

**CCD Copy:** to be submitted to CCD for campaign reporting and crediting.

Factory Copy: to be used as a packing copy for returnable parts when required.

Dealer Accounting/Dealer Service/Owner File Copy: this copy is for the dealer file.

Customer Copy: to be given to the customer as a record of the campaign service performed.

**Reply Card:** to be used by the owner if ownership or address has changed.

Upon presentation of this form by an owner, the dealer should:

- Imprint the combined notice and claim form in the upper right hand corner with his dealer plate and remove the cover sheet.
- Complete the header information boxes.
- Have the owner sign the form on the owner signature line.
- Perform the required campaign service as outlined in the DRB.
- Complete the form by entering the R.O. date, mileage and placing an X in the appropriate alpha code box indicating the campaign service which was performed. (The alpha code, which takes the place of the cost code and operation number, can be found on page 3 of this DRB.)
- Sign the form in the area provided and mail the CCD copy to CCD in Milwaukee.

**NOTE:** Do not make out a separate warranty claim. The new form is the warranty claim.

In the event the owner misplaces or neglects to bring in the campaign notice and claim form, the dealer should use a blank Campaign Notice and Claim Form. A small supply is included with this DRB. Should you need more forms, they are available from your Zone Service Department.

Before providing campaign services for a vehicle where the owner fails to present the campaign notice and claim form, the dealer must check the Vehicle Identification Number (VIN) against his Campaign VIN List or the total campaign VIN range contained in the Campaign DRB to ensure the vehicle is eligible to receive campaign services.

When using a blank form, be sure to enter the owner's name and address, VIN, Zone PDC and Dealer Code, campaign name or number, date of compliance and dealer's signature in the areas provided and X the appropriate service box as outlined in the Diagnosis and Repair Bulletin.

Based on the alpha box checked, the dealer will automatically be credited on the mid or end-of-month memorandum of warranty transactions (code 40) referencing the claim number on the form. The single credit shown will include Drive-in/Drive-out, corresponding labor, parts cost and applicable parts mark-up.

Although it will no longer be necessary for the dealer to enter the parts and labor costs for processing of the recall claim, the dealer may wish to complete the internal records box in the lower left hand corner of the claim. The figure shown in this box should be entered on the dealer's claim register along with the claim number.

Starting with this JEEPAXLE Campaign, it will no longer be necessary to complete a warranty claim form and a campaign reporting card after servicing an AMC or Jeep vehicle involved in a product recall campaign.

**PLEASE NOTE:** All prior campaign claims will continue to be handled as in the past.

Sales Corporation	BC 147 401-3215	7619 8 326919
PRODUCT RECALL CAMPAIGN NOTICE (AND CLAIM FORM) suborts free the repair work to suborts free the repair work to suborts the suborts to suborts to suborts t	LL SERVICING DEALER: Ahar the required campaign service has been performed, prease improv your plate to the right and sign the claim and comprete the applicable information balow. Follow the in- structione in the Diagnose and Recare Buildenin (DRB) for this campaign, Please be accurate and legible and creating. Mail this claim to CCD in Metwates. If returnable parts are involved, lottow the applicable builden instructions.	
AC CATE MARKET COMMAN AND AND AND AND AND AND AND AND AND A	Carrange No 2 8003	Agengrate Basiasi se balina n Basian are Ratar Balan A B -C D E F Q
Authorized Dealer Signature X <u>J. W. Jacker</u> The is to carity that the required campaign service has a performed fee of charge to the owner of the above vehic Upon completion this form should be submitted with your Warranty Claims to CCD.	OWNER INFORMATION NAME ADDRESS CITY, STATE, ZIP VEHICLE IDENTIFICATIO	Ann Owner 1234 Drieans Road Anytown, USA 12345 DN NO. JOE18NN000048
	Campaign Name and No.	JEEPAXLE (8003)
	Case Approval	Totel Claim Remains Damaid Resart Claim
COBT SALE		Danie Caste

Fig. 6 Sample Completed Combined Product Recall Campaign Notice and Claim Form

**NOTE:** This sample claim represents inspection and replacement of the rear axle shaft bearings. An inspection only would be alpha code A.



hg

This is a Type "S" campaign subject to all campaign procedures and involving safety-related elements.

haf

Joi

Some 1979 Jeep CJ models built between VIN J9M83AC849545 and J9M83AC851591 and 1980 Jeep CJ models built between VIN J0M93AH700384 and JOM83AC701781 may have been assembled with other than specified universal joint to yoke attaching clamps and bolts. As a result, these bolts may not hold torque due to interference between the bolthead flange and the clamp. This could result in the loosening of the bolts, uncoupling of the propeller shaft U-joints and yokes and loss of drive to the front and/or rear wheels.

Service correction involves inspecting the subject vehicles for the proper universal joint to yoke clamps and bolts and replacing the substandard components. Refer to the Inspection Procedure.

The Zone will provide a VIN list to each dealer with vehicles involved. However, the campaign procedures apply to all dealers. On all undelivered campaigninvolved vehicles, the inspection/correction must be made before the vehicle is sold or otherwise put in service.

The parts required for this campaign have already been shipped to all dealers on a no-charge basis. Each dealer has received bolts and clamps for every vehicle on his VIN list. Additional parts may be ordered as needed from your Zone Parts Distribution Center.

The following parts may be required:

Description	Qty.	Part No.	Group
BOLT, Propeller Shaft to Yoke	A/R	4006363	9.100
CLAMP, Propeller Shaft to Yoke	A/R	3235473	9.100

### INSPECTION PROCEDURE

File: CHASSIS - Axle and

**Prop Shaft** 

(1) Place transmission gear selector in neutral and raise vehicle.

(2) Rotate propeller shafts and inspect the following U-joint to yoke attaching clamp bolts with Torx heads.

1979 CJ Models — Inspect bolts and clamps at both front axle yoke and rear axle yoke.

1980 CJ Models - Inspect bolts and clamps at all yokes.

If all bolt heads have small flange (Fig. 1) and there is no interference with clamp, clean yoke using wire brush and shop cloth with solvent. Color every yoke with dab of light colored paint where screws and clamps were correct to note campaign completion, and return vehicle to owner.



If any bolt heads have large flange (Fig. 2), then clamp and bolts must be replaced. Refer to the Replacement Procedure.

### **REPLACEMENT PROCEDURE**

(1) Remove and discard propeller shaft yoke bolts and clamps identified as faulty during inspection.

**NOTE:** These torx head bolts require a thin wall, E8 Torx-drive socket as found in the J-25359-02 Torx bit and socket set.

(2) Install new bolts and clamps and tighten replacement bolts to 15 ft. lbs. (19N.m) torque.

(3) Clean yoke using wire brush and shop cloth with solvent.

(4) Color every yoke with dab of light colored paint where screws and clamps were replaced to note campaign completion. (0.418 - 0.438) inch

Fig. 2

(5) Lower vehicle.

The following operations and standard work times will apply:

DPERATION DESCRIPTION	ALPHA SERVICE CODE FOR CLAIM	MODEL	YEAR & TIME -7980-	SKILL LEVEL
BOLTS/CLAMPS, Propeller Shaft to Yoke — Inspect (includes Drive-in/Drive-out)	A	83-93	0.2	Μ.
Replace (includes Drive-in/Drive-out and Inspection Time Allowance)				
Dne	В		0.4	
lwo	С		0.5	
fhree	D		0.6	
W	E		0.7	

### **CLAIM HANDLING AND CAMPAIGN REPORTING**

Beginning with this campaign, owners of record will be mailed a new AMC and Jeep combined Product Recall Campaign Notice and Claim Form (Fig. 3). This new form is to be used in place of a warranty claim and a campaign reporting card.

This new Product Recall Campaign Notice and Claim Form is a six-page form that is pre-printed with the customer's name and address and the campaign name and number. The entire form will be mailed to the owner of record along with a cover letter outlining the defect and instructions to present the complete form to the dealer at the time the vehicle is serviced.

The six copies are:

**Cover Sheet:** contains instructions for the owner and shows the dealer where to imprint his dealer plate.

**CCD Copy:** to be submitted to CCD for campaign reporting and crediting.

Factory Copy: to be used as a packing copy for returnable parts when required.

**Dealer Accounting/Dealer Service/Owner File Copy:** this copy is for the dealer file.

**Customer Copy:** to be given to the customer as a record of the campaign service performed.

**Reply Card:** to be used by the owner if he or she no longer owns the vehicle or has moved.

Upon presentation of this form by an owner, the dealer should:

• Imprint the combined notice and claim form in the upper right hand corner with his dealer plate and remove the cover sheet.

Complete the header information boxes.

• Have the owner sign the form on the owner signature line.

• Perform the required campaign service as outlined in the DRB.

• Complete the form by entering the R.O. date, mileage and placing an X in the appropriate alpha code box indicating the campaign service which was performed. (The alpha code, which takes the place of the cost code and operation number, can be found in the SSO Block of this DRB).

• Sign the form in the area provided and mail the CCD copy to CCD in Milwaukee.

In the event the owner misplaces or neglects to bring in the campaign notice and claim form, the dealer should use a blank Campaign Notice and Claim Form. A small supply is included with this DRB. Should you need more forms, they are available from your Zone Service Department.

If an owner fails to present the campaign notice and claim form, the dealer must check the Vehicle Identification Number (VIN) against his Campaign VIN List or the total campaign VIN range contained in the Campaign DRB to ensure the vehicle is eligible to receive campaign services.

When it is necessary to use a blank campaign form, be sure to enter the owner's name and address, VIN, Zone PDC and Dealer Code, campaign name or number, date of campaign service and dealer's signature in the areas provided and "X" the appropriate service box as outlined in the Diagnosis and Repair Bulletin.

Based on the alpha box checked, the dealer will automatically be credited on the mid or end-of-month memorandum of warranty transactions (code 40) referencing the claim number on the form. The single claim credit will include Drive-in/Drive-out, corresponding labor, parts cost at dealer net and applicable parts mark-up.

Although it will no longer be necessary for the dealer to enter the parts and labor costs for processing of the recall claim, the dealer may wish to complete the internal records box in the lower left hand corner of the claim. The figure shown in this box should be entered on the dealer's claim register along with the claim number.

Starting with this UJOINT Campaign, it will no longer be necessary to complete a warranty claim form and a campaign reporting card after servicing an AMC or Jeep vehicle involved in a product recall.

**PLEASE NOTE:** All prior campaign service claims must be handled as in the past, (using a warranty claim form properly completed for the campaign repair.)

American Motors	1.000 to	4 . 440-123	4 7230	A=04347
PRODUCT RECALL CAMPAIGN NOTICE (AND CLAIM FORM) authorize that the repair work be enformed on the described motor entice. The vehicle may be operated by ou or your personnel for test and rspection purposes	NG DEALER: required campaign service has b print your plate to the right and sig the applicable information below in the Diagnosis and Repair Bullet Please be accurate and legible sin e used for campaign reporting ann to CCD in Milwaukee. If return follow the applicable bulletin instri	een performed, in the claim and . Follow the in- in (DR8) for this noce this informa- d crediting. Mail hable parts are luctions.	SERVICING Late Deale Server 45 St Caste	S DEALER IDENTIFICATION 31080 RED CARPET MOTORS DOBUGOD AMPRICA ANY TOKN, MI DOBUG 00-D000 SOF 10.00
Allos W         Clam No           3 21 80         Xianders I:           Woo Day Year         (No Sentis)	VIN .3/3000048	Campaign Na 8002	X Appropriate Box the Oragnosis and A B	lesi as outlingd m Rojiar Buitean C D E F
Authorized Dealer Signature X	Leco we campaign service has been he owner of the above vehicle. submitted with your CD.	OWNER INFORMAT NAME ADDRESS CITY, STATE, ZIP VEHICLE IDENTIFIC	ION	ANN OKNER 1234 ORLEANS BOAD ANYTONN, USA 12345 JOEL8NN000048
FOR SERVICING DEALER INTERNAL RECORDS USE ONLY COST SALE Labor Value S	CD USE STATUS CODE	Cian Appro	7 Total Claim Denied <u>Is</u> Denial Code	Clam Renarks Return Codes Initials Date
Net Parts Value \$			19.100 AV	

### Fig. 3 — Completed Combined Product Recall Campaign Notice and Claim Form

The above is a sample claim illustrating Drive-In/Drive-Out and inspection plus replacement of 3 bolts/clamps.

# **Diagnosis and Repair Bulletin**

Jeep.

Subject: Revised Procedure for Measuring and Correcting Steering Knuckle Ball Stud Preload

Application: 1980 CJ Models

File: CHASSIS Axles – Propeller Shaft

No. 80-1 Aug. 12, 1980

A revised procedure for measuring and correcting steering knuckle ball stud preload on 1980 CJ models has been developed. The procedure for 1980 Cherokee, Wagoneer and Truck models remains the same as outlined in the 1980 Jeep Technical Service Manual.

The revised procedures involve measuring ball stud preload, adjusting torque on the upper ball stud split ring seat or replacing the upper and lower ball studs, road testing to evaluate steering, and adjusting front axle caster if necessary.

The following parts may be required and will be available the week of August 4, 1980. Do not order parts before this date.

Description	Quantity	Part No.	Group
RING, Split	2	8121365	10.004
Knuckle Ball (Upper)	2	8122495	10.006
Knuckle Ball (Lower)	2	8122496	10.006
to Axle (3 <sup>0</sup> )	2	8129807	11.100

### PROCEDURE

### **Ball Stud Preload Measurement**

- (1) Raise vehicle.
- (2) Remove front wheels,

(3) If vehicle has steering damper, disconnect damper at tie rod and move damper aside.

(4) Unlock steering column.

(5) Disconnect steering connecting rod at rightside steering knuckle.

(6) Remove cotter pin and retaining nut that attach tie rod to right-side steering knuckle. Retain nut but discard cotter pin.

(7) Rotate both steering knuckles through complete arc several times. Work from right side of vehicle to rotate knuckles.

(8) Assemble socket and 0-50 foot-pound (0-68 N·m) capacity torque wrench and install wrench on tie rod retaining nut.

NOTE: The torque wrench must be positioned at a  $90^{\circ}$  angle to the steering knuckle arm to obtain an accurate reading.

(9) Rotate knuckles slowly and steadily through a complete arc and measure torque required to rotate knuckles.

(a) If reading is less than 25 foot-pounds (34 N·m), turning effort is within specifications, check steering gear, pump, or column.

(b) If reading is more than 25 foot-pounds (34 N·m), turning effort is excessive. Proceed to next step.

(10) Disconnect tie rod from both steering knuckles.

(11) Install  $1/2 \ge 1$  inch bolt, flat washer, and nut in tie rod stud mounting hole in one steering knuckle. Tighten bolt and nut securely.

(12) Install socket and 0-50 foot-pound (68 N·m) capacity torque wrench on bolt previously installed in steering knuckle.

NOTE: The torque wrench must be positioned at a  $90^{\circ}$  angle to the steering knuckle arm to obtain an accurate reading.

### American Motors Sales Corporation

(14) Install bolt, flat washer, nut, torque wrench and socket on opposite steering knuckle and measure torque required to rotate knuckle.

(a) If reading is less than 10 foot-pounds (14 N·m), steering effort is within specifications, check for tight or damaged tie rod ends, lubricate or replace as necessary, and proceed to next step.

(b) If torque reading is more than 10 footpounds (14 N·m), turning effort is excessive. Proceed to Ball Stud Preload Correction procedure.

(15) Install tie rod. Tighten tie rod retaining nuts to 40 foot-pounds (54 N·m) minimum torque and install replacement cotter pins.

(16) Install connecting rod. Tighten connecting rod retaining nuts to 40 foot-pounds (54 N·m) minimum torque and install replacement cotter pins.

(17) Install front wheels.

(18) Lower vehicle.

**Ball Stud Preload Correction** 

(1) Remove front axle shafts as outlined in chapter 2F of the 1980 Jeep Technical Service Manual.

(2) Loosen lower ball stud jamnut.

(3) Remove cotter pin and slotted nut from upper ball stud.

(4) Unseat upper and lower ball studs by striking studs with lead hammer.

(5) Remove upper ball stud split ring seat using Tool J-23447. Discard seat after removal.

(6) Remove lower ball stud jamnut and remove steering knuckle. Discard jamnut after removal.

(7) Clean following surfaces thoroughly: Upper ball stud split ring seat threads, lower ball stud taper in steering knuckle, threads and tapered surfaces of ball studs, and upper ball stud retaining nut thread. (8) Position steering knuckle on axle and install replacement lower ball stud jamnut finger-tight (only).

(9) Install and tighten upper ball stud slotted nut to 10-20 foot-pounds (13-27 N-m) torque to draw lower ball stud into tapered hole in axle yoke. Do not install upper ball stud split ring seat at this time.

(10) Tighten replacement lower ball stud jamnut to 80 foot-pounds (108 N·m) torque.

(11) Remove upper ball stud slotted nut and install replacement split ring seat using Tool J-23447. Tighten seat to 65 foot-pounds (88 N·m) torque.

(12) Install slotted nut on upper ball stud. Tighten nut to 100 foot-pounds (136  $N \cdot m$ ) torque. Align and install cotter pin without loosening slotted nut.

**NOTE:** If the cotter pin holes in the nut and stud are not aligned, tighten the nut (only) to align the holes. Never loosen the nut to align the holes.

(13) Install front axle shafts and steering spindles loosely and measure turning effort of each steering knuckle as described in Ball Stud Preload Measurement.

(a) If turning effort is less than 10 foot-pounds (14 N-m) torque, proceed to step (14).

(b) If turning effort is more than 10 footpounds (14 N·m) torque, replace upper and lower ball studs with replacement parts described in this bulletin and repeat Ball Stud Preload Correction procedure, but, tighten split ring seat to 50-foot pounds (68 N·m) torque instead of torque value indicated in step (11). Then tighten upper ball stud slotted nut to 80 foot-pounds (108 N·m) torque instead of torque value indicated in step (12).

(14) Install front axle shafts.

(15) Connect tie rod to steering knuckle arms. Tighten tie rod end retaining nuts to 40 foot-pounds (54  $N \cdot m$ ) minimum torque and install replacement cotter pins.

(16) Attach connecting rod to steering knuckle arms. Tighten connecting rod end retaining nut to 40 footpounds (54 N-m) minimum torque.

(17) Connect steering damper to tie rod, if equipped.

(18) Install front wheels. Tighten wheel retaining nuts to 75 foot-pounds (102 N·m) torque.

(19) Lower vehicle.

(20) Road test vehicle to verify steering effort correction and also check steering wheel returnability after making turns.

(a) If steering wheel returns toward center unassisted after turns, return vehicle to owner.

(b) If steering wheel requires assistance to return toward center after making turns, proceed to next step.

. .....

(21) Install  $+3^{\circ}$  shim between each front spring and axle spring pad to increase caster to desired maximum angle of  $+6^{\circ}$ .

NOTE: To maintain proper seating of the spring center bolts in the spring pads, caster should not be increased by more than  $+3^{\circ}$ .

The Standard Servicing Operations and work times as published in the current SSO Manual are not affected by this bulletin.

80-095-10J

# **Diagnosis and Repair Bulletin**

Jeep.

Subject: Disc Brake Noise

Application: 1978-79-80 Cherokee, Wagoneer, and Truck Models File: CHASSIS Brakes-Wheels-Tires

No. 80-1 Sept. 29, 1980

Some 1978-80 Cherokee, Wagoneer, and Truck models may develop a low frequency disc brake noise that is similar to a squeal-type noise. This noise is caused by the disc brakeshoes.

Service correction involves replacing the inboard and outboard disc brakeshoes on both front wheels with a shoe set that has a steel noise insulator on the outboard brakeshoe.

The following new brakeshoe set is required and will be available the week of October 6, 1980.

Quantity	Part No.	Group
1	8130435	8.000
	<u>Quantity</u> 1	Quantity Part No. 1 8130435

#### PROCEDURE

(1) Remove disc brake calipers and brakeshoes. Refer to Chapter 2G in 1978-79-80 Jeep Technical Service Manuals for procedure. (2) Inspect braking surfaces of each disc brake rotor.

(a) If surfaces are only lightly rusted or scored, remove rotors as outlined in appropriate Technical Service Manual, mount rotors in disc brake lathe, and clean rotor surfaces using flat sanding discs while turning rotors in lathe.

(b) If rotor surfaces are severely scored, cracked, chipped, excessively worn, or have hard spots (a series of shiny or dark-colored spots), replace rotor as outlined in appropriate Technical Service Manual.

(3) Install replacement brakeshoes and disc brake calipers on each front wheel as outlined in appropriate Technical Service Manual.

The standard servicing operations and work times as published in the 1978-79-80 SSO Manuals are not affected by this bulletin.

80-100-08J

### **71** American Motors Sales Corporation



FILE: Windshield-Windows -Body Hardware (BODY -Body General)

No. 5-01-82 Feb. 15, 1982

# **TECHNICAL BULLETIN**

PROBLEM ANDPower windows on some 1980-82 Wagoneer, Cherokee, and Truck modelsAPPLICATION:may make a scraping, clicking sound when operated or may not open<br/>completely. This may be due to the door glass bottom channel<br/>becoming cocked on the glass and catching on the regulator arm.

CORRECTION: Install a polypropylene wedge at each end of the door glass bottom channel to prevent cocking.

### PARTS:

Part Description	Quantity	Part Number	Group
WEDGE, Door Glass Bottom	AR	5762644	25.030
Channel			

WARRANTY Reimbursable within the provisions of the applicable warranty. ELIGIBILITY:

#### SSO INFORMATION:

	Cost	Operation		Year	and	Time	Skill
Operation Description	Code	Number	Model	80	-81-	82	<u>rever</u>
CHANNEL, FRONT OR REAR							
DOOR GLASS BOTTOM-							
INSTALL WEDGES		25045	Wag-Cke-Trk				G
One door				0.8	0.8	0.8	
Each additional						_	
door - Add				0.7	0.7	0.7	
Replace bottom							
channel - Add				0.2	0.2	0.2	
Front	25.030						
Rear	25.032						

### **PROCEDURE**:

- 1. Remove the door glass and bottom channel as outlined in chapter 3J of the 1980-82 Jeep Technical Service Manuals.
- 2. Inspect the bottom channel. Replace the channel if bent, distorted, or otherwise damaged.
- 3. Position the sides of the bottom channel parallel to the door glass and install a polypropylene wedge at each end of the channel. Position the wedges between the side of the channel and the seal and press the wedges to the bottom of the channel as shown in the illustration. (continued)

### I American Motors Sales Corporation

4. Install the door glass and bottom channel as outlined in chapter 3J of the 1980-82 Jeep Technical Service Manuals.

Caution: Be sure that the division and glass side channels are securely attached to the door. The bottom channel can contact the regulator if either of these channels are loose.

5. Verify proper power window operation.



Installing Wedges in Bottom Channel

\*

82-031-J

# **Diagnosis and Repair Bulletin**

Jeep,

Subject: Underbody Spare Wheel Mounting Bar Application: 1980 Cherokee and Wagoneer Models Built Prior to VIN JOM17NC065724 (June 19, 1980) File: BODY Body General

No. 80-2 July 18, 1980

On some 1980 Cherokee and Wagoneer models built prior to VIN JOM17NC065724 and equipped with an underbody mounted spare wheel, an intermittent underbody noise may occur when the vehicle travels over bumps. This condition may be the result of contact between the spare wheel mounting bar and rear axle housing cover.

Service correction involves inspecting the rear axle housing cover for scratch marks, which indicate that contact has occurred, and modification of the spare wheel mounting bar if necessary.

### PROCEDURE

- (1) Raise and support vehicle.
- (2) Inspect rear axle housing cover for scratch marks.

(a) If scratch marks are evident, proceed to step (3).

(b) If scratch marks are not evident, inspect all other underbody components for source of noise and repair as necessary.

(3) Remove spare wheel and tire assembly.

(4) Remove cotter pin, washer, and spring from hinge pin that attaches mounting bar to mounting plates (see illustration).

(5) Remove hinge pin and remove spare wheel mounting bar.

The following operations and standard work times will apply:

(6) Clamp mounting bar in vise and straighten bar mounting leg until it is at  $90^{\circ}$  angle to bar frame (see illustration).

(7) Position mounting bar in mounting plates and install hinge pin, spring, washer, and cotter pin.

- (8) Install spare wheel and tire assembly.
- (9) Remove supports and lower vehicle.



**Spare Wheel Mounting Bar Modification** 

OPERATION DESCRIPTION	COST	OPERATION		YEA	R AND	TIME	SKILL
	CODE	NUMBER	MODEL	80	81	82	LEVEL
BAR, SPARE WHEEL MOUNTING (UNDERBODY) - INSPECT	14.150	20141 A	Wag-Cke	0.1 0.2			G

<sup>80-129-</sup>BSJ

### I American Motors Sales Corporation

# **FI** Jeep

# **Diagnosis and Repair Bulletin**

Subject: Soft Top With Metal **Door Fit** 

Application: 1980 CJ Models With Soft Top and Metal Doors

File: BODY **Body General** 

No. 80-1 Feb. 6, 1980

On some 1980 CJ models with a soft top and metal doors, the inside top snap on the vertical support blades may be difficult to fasten. This condition may be caused by a misaligned hole in the horizontal support rod.

Service correction involves checking hole position in each support rod and replacing the support rods if the holes are misaligned.

The following parts are available and may be reauired:

Description	Quantity	Part No.	Group
ROD, Horizontal Support	2	8132799	40.014

### PROCEDURE

(1) Unsnap soft top from vertical support blade and body side panel.

(2) Unsnap soft top from roof bow and reposition roof bow.

(3) Remove horizontal support rod from vertical support rod and remove horizontal support rod from socket (see illustration).

(4) Check hole position in horizontal support rod. Hole should be located 28 inches from end of rod (see illustration). Replace rod if hole is misaligned.

The following standard servicing operation and work time will apply:

OPERATION DESCRIPTION	COST	OPERATION	MODEL	YEA		TIME	SKILL
	CODE	NUMBER	MODEL	80	81	82	LEVEL
RODS, HORIZONTAL SUPPORT – REPLACE BOTH	35.682	28015	93	0.2			G

80-062-BSJ

### I American Motors Sales Corporation

Service Engineering Department • 14250 Plymouth Road • Detroit, Michigan 48232 Additional copies of this bulletin are available through your zone office.

(5) Insert horizontal support rod into socket.

(6) Engage vertical support rod tab in horizontal support rod.

(7) Reposition soft top roof bow and strap on soft top.

(8) Loosen vertical support blade.

(9) Adjust blade position as necessary to align it with supports.

(10) Snap soft top to body panels and vertical support blade.





FILE: Body/Chassis Electrical (BODY - Body Electrical)

No. 8-05-82 Sept. 10, 1982

# **TECHNICAL BULLETIN**

PROBLEM AND011 pressure gauge needle flutters during engine operation on someAPPLICATION:1979-82 CJ and Scrambler models.

CORRECTION: Install the improved gauge that was phased into production on February 24, 1982. The improved gauges are date coded beginning with code B201 (2-1-82).

PARTS: Description Quantity Part Number Group GAUGE, 011 1 5750279 3.605 Pressure

S.R.T. INFORMATION:

		Operation	
Operation Description	<u>T.I.C.</u>	Number	S.R.T.
CO. GAUGE, OIL PRESSURE			
REPLACE	8-352	8999	0.3

DEALER Reimbursable within the provisions of the applicable warranty. REIMBURSEMENT:

**PROCEDURE:** 

- 1. Remove the original oil pressure gauge as outlined in Chapter 1L of the appropriate Jeep Technical Service Manual.
- Obtain a replacement oil pressure gauge and check the gauge date code before installation to be sure it is one of the improved gauges. The code must be B201 (2-01-82) or later.
  - NOTE: Code letter B indicates the month, such as B for February, C for March, or D for April. The first number indicates the year, which in this case is 1982. The last two numbers represent the day of the month. For example, code C217 would represent March 17, 1982 and code D208 would represent April 8, 1982. Letter I is not used as a code letter.
- 3. Install the replacement oil pressure gauge as outlined in Chapter 1L of the appropriate Jeep Technical Service Manual.

82-064-J

### **71** American Motors Sales Corporation

Service Engineering Department 

14250 Plymouth Road 

Detroit, Michigan 48232

Additional copies of this bulletin are available through your zone office.

80-56

# /I Jeep

# **Diagnosis and Repair Bulletin**

Subject: Power Sun Roof Option

Application: 1980 Wagoneer Limited Models File: BODY Body Electrical

No. 80-8 Aug. 11, 1980

A power sun roof is now available as an option on 1980 Wagoneer Limited models. The sun roof features a sliding glass panel operated by an electric motor and a manually operated sun screen. A nylon knit, onepiece headliner with bonded foam backing and a padded vinyl roof are standard on every Wagoneer model equipped with the optional sun roof.

The electric motor that operates the sliding glass panel is activated by a two-position switch mounted in the windshield header. The electric motor itself is mounted in the forward portion of the sun roof housing assembly. Electrical feed to the motor is through the A/C terminal of the fuse panel. Circuit protection is provided by the A/C terminal fuse and by a 20 amp, in-line fuse in a harness wire located just below the left A-pillar.

An additional feature of the sun roof is the ability to close the sliding glass panel manually if an electrical power failure should occur. A cranking tool is provided with the sun roof for this purpose. Refer to Manual Operation of Glass Panel procedure.

A rubber drain hose is used at each corner of the sun roof housing. These hoses remove any water that may bypass the weatherstrip seal surrounding the roof opening. The forward hoses are routed downward through the A-pillars. The rearward hoses are routed downward through the D-pillars.

Whenever it is necessary to service the power sun roof, refer to the procedures provided in this bulletin.

### POWER SUN ROOF SERVICE AND ADJUSTMENTS

**Halo Assembly Removal** 

(1) Open glass panel partially and remove halo assembly attaching screws (Fig. 1).

(2) Grasp center of halo assembly and pull assembly downward to disengage front tabs from track.



Fig. 1 Removing/Installing Halo Assembly Attaching Screws



Fig. 2 Removing/Installing Halo Assembly

### **71** American Motors Sales Corporation

Service Engineering Department e 14250 Plymouth Road e Detroit, Michigan 48232

Additional copies of this bulletin are available through your zone office.

(3) Close glass panel fully, slide nalo assembly forward, and remove assembly from vehicle (Fig. 2).

#### Halo Assembly Installation

(1) Close glass panel and position rear portion of halo assembly on glass panel.

(2) Open glass panel partially.

(3) Install halo assembly attaching screws.

### **Glass Panel Removal**

(1) Remove halo assembly. Refer to Halo Assembly Removal.

(2) Close glass panel and remove outboard screws from front guide shoe assemblies (Fig. 3). Then loosen inboard screws and rotate guide shoes to disengage slide portion from track.

(3) Release rear slide tension springs by rotating them to inboard position (Fig 3).

(4) Remove screws attaching rear guide shoes and retainers to tabs in glass panel and remove retainers (Fig. 3).

(5) Working from outside of vehicle, raise front of glass panel and slide panel forward and out of vehicle.

### **Glass Panel Installation**

(1) Position glass panel in vehicle.

(2) Install rear guide shoes and retainer brackets on glass panel and install guide shoe and retainer bracket attaching screws.

(3) Install rear slide tension springs (Fig. 3).

**NOTE:** Be sure the spring is positioned under the spring lock roller.

(4) Engage slide portion of front guide shoe assemblies in track and install guide shoe attaching screws.

(5) Install halo assembly. Refer to Halo Assembly Installation.





#### Sunscreen Removal

(1) Remove halo assembly and glass panel. Refer to Halo Assembly Removal and Glass Panel Removal procedures.

(2) Open sunscreen fully.

(3) Working from outside of vehicle, push sunscreen upward at center of screen and slide screen forward and upward to remove it (Fig. 4).

### Sunscreen Installation

(1) Working from outside of vehicle, curve sunscreen upward at center of screen and slide screen rearward and downward into sun roof opening (Fig. 4).

(2) Install glass panel and halo assembly. Refer to Glass Panel Installation and Halo Assembly Installation procedure.



Fig. 4 Sunscreen Removal/Installation

**Cable and Side Track Removal** 

(1) Remove halo assembly, glass panel and sunscreen. Refer to removal procedures outlined in this bulletin.

(2) Remove screws that attach cable front cover and remove cover (Fig. 5).

(3) Remove drive gear plate (Fig. 5),

(4) Remove side track cover screws and remove side track cover (Fig. 5).

(5) Disengage cable from front track and motor gear and remove cable by pulling it upward and outward.

NOTE: It may be necessary to reposition the front cable guide before the cable can be removed from the track.

(6) Lift side track upward and remove side track.



81106E

1



#### **Cable and Side Track Installation**



(2) Slide cable assembly into side track and install cover on side track.

(3) Pull cable until rear guide shoe contacts side track cover.

NOTE: If both cables have been disengaged from the motor gear, be sure both rear guide shoes are in contact with the side track covers before proceeding. This is very important.

(4) Position cables in front track and engage cables with teeth of drive gear.

(5) Install drive gear plate.

CAUTION: Do not operate the motor at this time as the cables could be damaged.

(6) Install cable front cover.

(7) Install sunscreen, glass panel, and halo assembly. Refer to installation procedures outlined in this bulletin.

### **Power Sun Roof Housing Removal**

(1) Remove halo assembly, glass panel, and sunscreen. Refer to removal procedures outlined in this bulletin.

(2) Remove headlining. Refer to Headlining Removal.

(3) Disconnect ground wire at right A-pillar and move wire away from housing assembly.

(4) Disconnect sun roof switch from motor harness.

(5) Disconnect drain tubes from sun roof housing (Fig. 5).

(6) Remove housing attaching nuts.

(7) Remove shims, if equipped.

(8) Support housing and remove housing attaching hardware from brackets.

(9) Lower housing assembly away from reinforcement ring and remove housing from vehicle.

#### **Power Sun Roof Housing Installation**

(1) Position housing assembly in vehicle.

(2) Raise and support housing on reinforcement ring.

(3) Install shims if equipped, and tighten housing attaching hardware.

(4) Connect drain tubes to housing assembly (Fig. 5).

(5) Connect sun roof switch to motor harness.

(6) Position ground wire on housing assembly and connect wire to right A-pillar.

(7) Install headlining. Refer to Headlining Installation.

(8) Install sunscreen, glass panel, and halo assembly. Refer to Installation Procedures outlined in this bulletin.

### Vinyl Roof Removal

(1) Remove moulding clips and remove mouldings around vinyl roof.

(2) Remove all sealing material around openings to expose vinyl top edges.

(3) Mask cowl top, sides and rear of vehicle, and windows with paper. Insert paper in windows, then close windows to hold paper in place.

(4) Remove luggage rack. Refer to Chapter 3L in 1980 Technical Service Manual for procedure.

(5) Loosen vinyl material at front pillars and along windshield header.

NOTE: It may be easier to remove the vinyl material and padding simultaneously.

(6) Remove material and sealer from drip rail. Pry sealer loose using screwdriver or other suitable tool if necessary.

(7) If vinyl material and padding is difficult to remove, soak adhesive next to fabric using rag dampened with 3M General Purpose Adhesive Cleaner or equivalent.

NOTE: It is not necessary to remove the old vinyl top adhesive. However, it is important that the roof surface be smooth and free of irregularities to prevent highlighting after a new cover is installed.

(8) Remove vinyl material from foam padding using 3M General Purpose Adhesive Cleaner, or equivalent.

WARNING: Always use rubber gloves when working with solvents and be sure the work area is well ventilated.

### **Vinyl Roof Installation**

(1) Remove all dust and foreign material from roof panel.

(2) Position padding on roof panel and cut away foam padding at sun roof opening and luggage rack attaching screw holes.

(3) Remove paper backing from foam padding to expose padding adhesive and bond padding to roof panel. Use roller or soft cloth to ensure positive bond.

**NOTE:** Be sure the foam padding is smooth and free from any irregularities to prevent highlighting after a new cover is installed.

(4) Mark centerline of roof panel above windshield and rear window openings.

(5) Align center of vinyl cover with centerline mark above windshield and rear window.

(6) Secure cover to pinch weld flange at centerline locations with tape.

(7) Check cover for alignment at both sides and at roof extension panels.

(8) Fold cover in half at centerline.

(9) Apply smooth, even coat of 3M Vinyl Trim Adhesive or equivalent to 15-inch wide strip of one side of foam padding and to vinyl cover. Start at center when applying adhesive and work from front to rear.

**NOTE:** Allow the adhesive applied to the vinyl material and foam padding to dry until it is tacky to the touch.

(10) Bond cover to foam padding using a roller or soft cloth to ensure positive bond and to eliminate air pockets. Bond cover by starting at centerline and working toward side.

NOTE: To remove wrinkles caused by folding, keep the cover fabric taut while installing it.

(11) Apply adhesive to remainder of cover and foam padding and in drip moulding at side of cover being installed. Allow adhesive to dry until tacky.

(12) Apply smooth, even coat of adhesive to 15-inch wide strip of foam padding and to vinyl cover on opposite side of vehicle. Start at center and work from front to rear when applying adhesive. Allow adhesive to dry until tacky.

NOTE: When applying the cover to the foam padding, always work from the center to the outside to eliminate air pockets to ensure positive bonding. (13) Brush adhesive onto cover, ledge of windshield, and rear window opening. Allow adhesive to dry until tacky before bonding.

(14) Work vinyl cover into crease line areas around roof using smooth fiber stick.

(15) Trim excess cover material from around drip rails, windshield, and rear window.

(16) Trim vinyl material around sun roof opening and luggage rack attaching screw holes.

(17) Brush adhesive onto cover and ledge of sun roof opening. Allow adhesive to dry until tacky before bonding.

(18) Position and work vinyl cover into sun roof opening using smooth fiber stick.

(19) Install luggage rack. Refer to Chapter 3L of 1980 Technical Service Manual.

(20) Apply bead of 3M Super Silicone Sealer (black preferred) or equivalent along top of windshield rubber weather strip and vinyl cover.

NOTE: It may be necessary to apply sealer to the drip rails also.

(21) Remove excess sealer using 3M General Purpose Adhesive Cleaner or equivalent and remove all masking tape and paper.

(22) Install mouldings and clips.

### **Headlining Removal**

(1) Remove sun visors, escutcheons, and center support.

(2) Remove windshield moulding and end caps.

(3) Remove sun roof switch and disconnect switch wires.

(4) Remove sun roof opening trim welt and remove motor cap.

(5) Spray 3M Release Agent or equivalent, across headlining at windshield and around sunroof opening. Allow several minutes for release agent penetration.

CAUTION: When removing the headlining, use care to avoid separating the foam backing from the fabric. If the fabric begins to separate from the backing, make a second application of the release agent.

(6) Remove headlining from roof panel and sun roof opening.

(7) Remove headlining from side retainers

(8) Remove lens from dome lamp. Remove screws attaching lamp to sun roof housing and remove lamp.

(9) Remove coat hooks.

(10) Remove lens from cargo lamp, then remove screws attaching cargo lamp to roof bow and remove lamp and switch.

(11) Remove tailgate opening moulding and end caps.

(12) Spray 3M Release Agent, or equivalent across headlining at tailgate opening moulding. Allow several minutes for release agent penetration.

CAUTION: When removing the headlining, use care to avoid separating the foam backing from the fabric. If the fabric begins to separate from the backing, make a second application of release agent.

(13) Remove headlining from tailgate opening.

(14) Remove headlining from side retainers and slide headliner rearward and out of headlining brackets.

(15) Remove headlining from vehicle through tailgate opening.

#### **Headlining Installation**

(1) Install headlining in vehicle through tailgate opening. Insert headlining in headlining brackets and slide headlining forward.

(2) Spray 3M General Trim Adhesive, or equivalent across at roof panel at tailgate opening.

(3) Attach headlining to roof panel at tailgate opening and install tailgate opening moulding and end caps.

(4) Pull headlining forward. Install headlining up to coat hook locations along both sides using Installer Tool J-2772-C.

(5) Connect and install cargo lamp and lens.

(6) Connect and install cargo lamp switch.

(7) Spray 3M General Trim Adhesive or equivalent, on sun roof opening flange.

(8) Install coat hooks.

(9) Pull headlining forward and attach it to sun roof opening flange.

(10) Install sun roof opening trim welt.

(11) Connect and install dome lamp and lens.

(12) Place strip of masking tape across top of windshield at roof panel. (13) Spray 3M General Trim Adhesive or equivalent, on roof panel along top of windshield.

(14) Using sun visor holes as guides, pull headlining forward and attach it along windshield.

(15) Install headlining along both sides using Installer Tool J-2772-C.

(16) Connect and install sun roof switch.

(17) Install windshield moulding and end caps, and motor cap.

(18) Install sun visors, escutcheons, and center support.

(19) Remove masking tape.

### Power Sun Roof Switch Removal/Installation

(1) Pull switch downward and disconnect switch wires.

(2) Connect switch wires and install switch in switch opening.

**Power Sun Roof Motor Removal** 

(1) Open sun roof glass panel; then disconnect battery negative cable.

(2) Remove sun visors, escutcheons, center support, and windshield moulding and end caps.

(3) Remove sun roof switch and motor cap.

(4) Spray 3M Release Agent or equivalent across headlining at windshield. Allow several minutes for release agent penetration.

CAUTION: When removing the headlining, use care to avoid separating the foam backing from the fabric. If the fabric begins to separate from the backing, make a second application of the release agent.

(5) Pull front edge of headlining downward.

(6) Remove motor mounting screws and remove motor.

Power Sun Roof Motor Installation

(1) Position motor in housing and install motor mounting screws.

(2) Place strip of masking tape across top of windshield at roof panel.

(3) Spray 3M General Trim Adhesive or equivalent on roof panel along top of windshield.

(4) Pull headlining forward and attach it along windshield. Use sun visor holes as guides when attaching headlining.

(5) Connect wires to sun roof switch and install switch and motor cap.

(6) Install sun visors, escutcheons, windshield trim moulding and end caps, and center support.

(7) Connect battery negative cable, and check sun roof operation.

NOTE: If the motor slips and does not open and close the glass panel, the motor clutch located in the gear portion of the motor may have to be adjusted. Refer to Motor Clutch Adjustment in Power Sun Roof Service and Adjustments section.

#### **Motor Clutch Adjustment**

(1) Remove motor cap to gain access to adjusting screw. Cap is located in headlining just above, and at center of windshield.

(2) Loosen clutch plate adjusting screw jamnut using deep socket.

(3) Tighten adjusting screw to 50 inch-pounds (5.6 N·m) torque.

(4) Tighten jamnut and install motor cap.

#### **Glass Panel Parallel Alignment**

CAUTION: Do not operate the electric motor while the glass panel or cables are removed from the track as cable damage could occur.

(1) Open glass panel approximately 1/4-to-1/2 inch.

(2) Determine how much forward edge of glass panel is out of parallel with forward edge of opening in roof panel and note variation.

(3) Open panel approximately eight inches to gain access to cable and drive gear mechanism.

(4) Remove cable front cover and drive gear plate.

(5) Remove one cable from track.

(6) Move one side of glass panel slightly fore or aft as required to obtain parallel alignment with forward edge of roof panel opening (Fig. 6).

(7) Install cable in front track and insert cable in drive gear teeth.

(8) Install drive gear plate and cable front cover.

(9) Position glass panel approximately 1/4-inch from fully closed position.

(10) Check parallel alignment. Repeat steps (2) through (9) to obtain proper alignment if necessary.

Glass Panel Height Adjustment

**Adjusting Front of Panel** 

(1) Remove halo assembly. Refer to Halo Assembly Removal.

(2) Loosen front guide shoe attaching screws (Fig. 7).

(3) Turn knurled nut on each front guide shoe clockwise to lower glass panel or counterclockwise to raise panel and obtain desired height adjustment (Fig. 7).

(4) Tighten front guide shoe attaching screws to 20 inch-pounds  $(2.3 \text{ N} \cdot \text{m})$  torque after adjusting panel height.

CAUTION: Do not adjust the glass panel too high as it could be damaged when the panel is opened or closed.



81106G

Fig. 6 Glass Panel Parallel Alignment



81106H

### Fig. 7 Glass Panel Front Height Adjustment





(5) Check glass panel alignment and operation in open and closed positions. Repeat steps (2) through (4) to obtain proper height if necessary.

(6) Install halo assembly. Refer to Halo Assembly Installation.

### **Adjusting Rear of Panel**

(1) Remove halo assembly. Refer to Halo Assembly Removal.

(2) Release rear slide tension spring and rotate spring to inboard position (Fig. 3).

(3) Loosen rear slide adjuster nut (Fig. 8) and raise or lower panel as required to obtain desired adjustment.

(4) Tighten rear slide adjuster nut to 30 inch-pounds (3.3 N-m) torque after completing adjustment.

(5) Install halo assembly. Refer to Halo Assembly Installation.

### **Manual Operation of Glass Panel**

If an electrical malfunction should ever occur, the glass panel can be opened or closed manually as follows:

(1) Remove small round motor cap located in center of windshield header near front edge of sun roof opening, Cap removal will provide access to motor driveshaft.

(2) Remove screw in driveshaft using flat bladed screwdriver or cranking tool blade end located in glovebox.

(3) Rotate motor driveshaft using cranking tool. Rotate driveshaft clockwise to close glass panel, or counterclockwise to open panel.

(4) Install screw in driveshaft and install access plug in windshield header after opening/closing glass panel.

Vinyl Top Repair

**Bulges or Blisters** 

Bulges or blisters in the vinyl top indicate poor bonding or trapped air. They can be eliminated by piercing the bulge or blister to expel the air. Heat the area for 10 to 15 seconds with Heat Gun J-25070, held 10 to 15 inches from the material. Immediately press and hold vinyl material firmly against foam padding and metal with a felt pad or roller until vinyl cover cools. Do not rub vinyl. Rubbing will result in a polished area.

#### Wrinkles

-

Minor wrinkles in the vinyl top material may be removed with the application of moist heat as follows:

(1) Wash vinyl top surface thoroughly using AMC Vinyl Cleaner or equivalent.

(2) Set heat control or household-type flat iron to warm.

(3) Dampen a clean cloth with clean water and apply it over wrinkled area.

(4) With iron at proper operating temperature, move iron continuously over dampened cloth until wrinkle is removed.

Maintain pressure on vinyl top material until material cools.

CAUTION: Apply pressure to the vinyl top material only. Do not rub the vinyl top repair area as this could impair the finish of the vinyl.

The following operations and standard work times will apply:

	COST	OPERATION		YEAR AND TIME			SKILL
OFERATION DESCRIPTION	CODE	NUMBER	MODEL	80	81	82	LEVEL
PANEL, GLASS SLIDING, SUN ROOF — R & R	25.405	25218	Wag.	0.3			G
Panel — Replace	25.405	A		0.1			G
CABLE, SUN ROOF - REPLACE Includes cable adjustment	28.452	25222	Wag.				G
OneBoth				0.3 0.4			
HEADLINING – R & R	29.011	29125	Wag.	1.3			G
HEADLINING – LOWER FRONT HALF	29.011	29114	Wag.	0.9			G
HEADLINING - LOWER REAR HALF	29.011	29116	Wag.	0.5			G
HOUSING, SUN ROOF — R & R Includes lower front half of headlining	28.454	25220	Wag.	1.8			G
HALO ASSEMBLY, SUN ROOF - R & R	28.468	25216	Wag.	0.1			G
Halo assembly - Replace	28.468	A	-	0.1			G
Sliding Glass Panel - Adjust Height	25,405	В	Wag.	0.2			G
CLUTCH, SUN ROOF MOTOR - ADJUST	28.450	25224	Wag.	0.1			G
MOTOR, SUN ROOF - REPLACE	28.450	25226	Wag.	0.8			G
SWITCH, SUN ROOF - REPLACE	3.810	25228	Wag.	0.2			G

80-123-BSJ

# **Diagnosis and Repair Bulletin**

Subject: Instrument Cluster Lens

Application: 1980 Jeep CJ-5 and CJ-7 Models

File: BODY Body Electrical

No. 80-7 June 30, 1980

On some 1980 CJ-5 and CJ-7 models, a slight mist may form on the instrument cluster lens during high humidity conditions. Although the gauges are still quite visible, a customer may be dissatisfied with this condition.

Service correction involves drilling vent holes in the instrument cluster case as outlined in the following procedure.

### PROCEDURE

(1) Disconnect battery negative cable.

(2) Disconnect speedometer cable at speedometer head.

(3) Remove windshield holddown knobs and fold windshield forward onto hood.

(4) Remove dash pad from dash panel.

(5) Remove steering column bezel.

(6) Remove screws that attach instrument panel to dash panel and move instrument panel outward to gain access to instrument cluster attaching nuts.

(7) Remove instrument cluster attaching nuts and move cluster away from instrument panel.

(8) Tag all bulbs and wires connected to instrument cluster for assembly reference. Then disconnect wires, remove bulbs, and remove instrument cluster.

(9) Remove bezel, retainer, and lens from instrument cluster.

(10) Remove speedometer head from instrument cluster case.

(11) Drill six 1/8-inch diameter holes in instrument cluster case in locations shown in illustration. Position each pair of holes in upper portion of case approximately 3/4-inch apart. Position two holes in lower part of case 1-1/4 inches apart to avoid contacting bulb in this portion of case. CAUTION: Take care to avoid damaging the fuel and temperature gauges when drilling the vent holes in the instrument cluster case.

(12) Clean all metal chips from instrument cluster case.

(13) Install speedometer head in instrument cluster.

(14) Install lens, retainer, and bezel on instrument cluster. Secure parts on cluster by crimping bezel at four locations shown in illustration.



Vent Hole Locations

### **FI** American Motors Sales Corporation

(15) Connect bulbs and wires to instrument cluster. Refer to assembly reference tags for correct wire locations.

(16) Install instrument cluster in instrument panel and install cluster attaching nuts.

(17) Position instrument panel on dash panel and install instrument panel attaching screws.

(18) Install steering column bezel.

The following operation and standard work times will apply:

(19) Install dash pad on dash panel.

(20) Raise windshield and install windshield holddown knobs.

(21) Connect speedometer cable to speedometer head.

(22) Connect battery negative cable.

OPERATION DESCRIPTION	COST	OPERATION	MODEL	YEA	R AND	TIME	SKILL
	CODE	NUMBER	MODEL	80	81	\$2	LEVEL
CLUSTER ASSEMBLY, INSTRUMENT – MODIFY With Air Conditioning – Add With Fabric Top – Add With Molded Top – Add	3,505	3299	CJ	0.8 0.1 0.1 0.3			G

80-117-BSJ

# **Diagnosis and Repair Bulletin**

l Jeep

Subject: Power Window Operation and Diagnosis

Application: 1980 Cherokee, Wagoneer, and Truck Models Equipped With Power Windows and Built Prior to VIN J0D15NC053176 File: BODY Body Electrical

No. 80-6 June 6, 1980

The electrically operated power windows in some 1980 Cherokee, Wagoneer and Truck models built prior to VIN J0D15NC053176 may bind, become inoperative, operate slowly, or become inoperative during cold weather conditions.

Service correction requires an accurate diagnosis of the power window system. Slow operation or a binding condition may be caused by improperly adjusted window glass slide or division channels. An inoperative window condition will require the circuit tests outlined in Section 3J of the 1980 Technical Service Manual Supplement to determine if the condition is related to the window switch, motor, or wiring. If diagnosis indicates motor replacement is necessary, use the service replacement motor described in this bulletin.

The following parts may be required.

Description	Quantity	Part No.	Group
MOTOR ASSEMBLY, Electric Window Drive (Left Side)	1	8132691	23.300
MOTOR ASSEMBLY, Electric Window Drive (Right Side)	1	8132692	23.300

### PROCEDURE

- (1) Disconnect battery negative cable.
- (2) Remove door trim panel and water dam paper.

WARNING: The window regulator assembly is spring loaded. The window glass must be supported in the UP position and the regulator arm connected to the lower slide channel to prevent the regulator spring from unloading.

(3) Support window glass in UP position by inserting wood block through door inner panel to support lower slide channel.

(4) Disconnect feed wires to motor at connector.

(5) Remove motor attaching nuts and bolts and remove motor assembly.

- (6) Install replacement motor assembly.
- (7) Connect feed wires to motor.
- (8) Remove wood block used to support window.
- (9) Install water dam paper and trim panel.
- (10) Connect battery negative cable.

The following operations and standard work times will apply:

OPERATION DESCRIPTION	COST OPERATION	MODEL	YEAR AND TIME			SKILL	
	CODE	NUMBER	MUUEL	80	81	82	LEVEL
MOTOR, ELECTRICALLY OPERATED FRONT DOOR WINDOW - REPLACE	23.103	23158	Wag-Cke Trk	0.6			G
MOTOR, ELECTRICALLY OPERATED REAR DOOR WINDOW — REPLACE	23.173	23168	Wag-Cke Trk	0.5			G

80-109-BSJ

### **VI** American Motors Sales Corporation

/I Jeep

# **Diagnosis and Repair Bulletin**

Subject: AM/FM Stereo Radio Option

Application: 1980 CJ-5 and CJ-7 Models

File: BODY — Body Electrical

No. 80-5 April 30, 1980

An AM/FM stereo radio is now available as an option on 1980 CJ-5 and CJ-7 models. This radio option includes dual speakers that are mounted in the instrument panel.

If it is ever necessary to remove the AM/FM radio and/or speakers on 1980 CJ models equipped with this option, refer to the following removal and installation procedure.

### PROCEDURE

(1) Disconnect battery negative cable.

(2) On models equipped with air conditioning, remove evaporator housing attaching screws and move housing away from instrument panel.

(3) Remove radio control knobs and nuts.

(4) Disconnect speaker wires, radio wires, and antenna wire.

(5) Disconnect radio mounting bracket and remove radio.

(6) Remove nuts that attach speakers to instrument panel and remove speakers.

### Installation

(1) Position speakers on instrument panel and install speaker retaining nuts.

(2) Install radio in instrument panel, connect radio mounting bracket, and install radio nuts and control knobs.

(3) Connect radio wires, speaker wires, and antenna wire.

(4) On models with air conditioning, position evaporator housing on instrument panel and install housing attaching screws.

(5) Connect battery negative cable.

The following standard servicing operations and work times will apply:

OPERATION DESCRIPTION	COST	OPERATION NUMBER	MODEL	YEAR AND TIME			SKILL
	CODE			80	81	82	LEVEL
RADIO, AM/FM STEREO – R & R	15.327	3580	83-93	0.3		<u> </u>	G
SPEAKERS, AM/FM STEREO RADIO — R & R	15.321	3582	88-93	0.3			G
Radio Speaker – Replace	15.321	A	83-93	0.4			G

80-102-BSJ

# American Motors Sales Corporation

# **Diagnosis and Repair Bulletin**

Jeep.

Subject: Stereo Radio Rear Speakers Missing Application: 1980 Cherokee Laredo Models Built Prior to VIN JOE17NN027333 File: BODY Body Electrical

No. 80-4 Feb. 14, 1980

Some 1980 Cherokee Laredo models ordered with the four speaker stereo radio option may have been built without the rear speakers.

Service correction involves installation of the rear speakers and speaker wiring harness if necessary.

The following parts are available and required.

Description	Quantity	Part No.	Group
JUMPER, Harness	1	5751957	15.320
SPEAKER KIT, Rear	1	8997198	15.320

PROCEDURE

#### Vehicles With Power Tailgate

(1) Remove inside spare tire if equipped.

(2) Remove both rear quarter trim panels.

(3) Remove knockouts from trim panels and cut out trim material. Paint bezels and grilles with matching trim colors outlined below. Then install bezels and grilles.

Black	Blue	Russet	Dark Desert Tan			
NA	8993597	8993596	8993499			

(4) Install gaskets around speaker openings on back of trim panels.

(5) Install speakers in left and right mounting brackets.

(6) Position and attach left and right speaker and bracket assemblies to body panels according to template supplied in speaker kit.

(7) Connect speaker wires to cross-body harness connections.

(8) Operate radio to check and ensure that all four speakers are functional.

(9) Install rear quarter trim panels and inside spare tire if equipped.

# Vehicles Without Power Tailgate

(1) Remove inside spare tire if equipped.

(2) Remove both rear quarter trim panels.

(3) Remove knockouts from trim panels and cut out trim material. Paint bezels and grilles with matching trim colors outlined below. Then install bezels and grilles.

Black	Blue	Russet	Dark Desert Tan			
NA	8993597	8993596	8993499			

(4) Install gaskets around speaker openings on back of trim panels.

(5) Install speakers in left and right mounting brackets.

# I American Motors Sales Corporation

(6) Position and attach left and right speaker and bracket assemblies to body panel according to template supplied in speaker kit.

NOTE: The rear speaker harness may have been omitted in production. If the harness cannot be located in the rear quarter panel area, proceed to step (7). However, if the harness is located in the quarter panel area, proceed to step (14).

(7) Remove glove box from dash panel and inspect wire harness running from radio to speakers. Wire harness part number should be 5751957. If not, replace harness as described in following steps.

(8) Remove left scuff plate and loosen carpeting.

(9) Remove seat belt lower mount.

(10) Remove rear floor noulding at tailgate opening.

(11) Position and route harness under carpeting. Start at jumper harness at radio and route back to left speaker and across to right rear speaker.

(12) Operate radio to check and ensure that all four speakers are functional.

(13) Install glove box, seat belt lower mount, scuff plate and rear floor moulding.

(14) Install both rear quarter trim panels and inside spare tire if required.

The following standard servicing operation and work time will apply:

OPERATION DESCRIPTION	COST CODE	OPERATION NUMBER	MODEL	YEAR AND TIME			SKILL
				80	81	82	LEVEL
SPEAKERS, RADIO REAR - INSTALL Includes brackets and color coat	15.321	3603	17	0.7			G
Harness-Install	15.321	A		0.5			G
Material allowance for paint is \$ 0.70							6

80-050-BSJ

# PRODUCT RECALL CAMPAIGN Diagnosis and Repair Bulletin No. 80-3



Date: January 28, 1980

Application: 1980 Jeep Cherokee, Wagoneer and Truck Models

File: BODY-Body Electrical

This is a Type "S" campaign subject to all campaign procedures and involving safety-related elements. A copy of the combined owner notification and correction reporting card for this campaign is shown in Figure 1.

Some 1980 Jeep Cherokee, Wagoneer and Truck models built between VIN numbers JOE17NN000065 and JOE15NN005299 may have been assembled with incorrect headlamps for the U.S. market.

Service correction involves inspecting both the right and left headlamps and if necessary, replacing the headlamps found to be incorrect with the correct parts.

The following part may be required for correction:

			Group
Description	Qty.	Part No.	No.
Bulb, Headlamp	A/R	8128683	3.280
(Sealed Beam)			

The Zone will provide a VIN list for each dealer with any vehicles involved. However, the campaign procedures apply to all dealers. On all undelivered, campaign-involved vehicles, the inspection/ correction must be made before the vehicle is sold or otherwise put in service. The PDC's already have their supply of campaign parts. Parts can now be ordered, only as needed, from your local PDC.

# **INSPECTION PROCEDURE**

1) Inspect headlamps. If cat-head shaped logo appears on glass and a bulb is seen in unit, headlamp(s) are incorrect and must be replaced. Refer to replacement procedure below. If both headlamps are sealed beam units, then vehicle should be returned to the owner.

### **REPLACEMENT PROCEDURE**

1) Remove headlamp retaining ring screws and remove retaining ring.

2) Disconnect wiring and remove lamp assembly and dispose of it.

3) Connect wires on replacement sealed beam headlamp and position lamp in place.

4) Position retaining ring and install retaining ring screws.

5) Aim headlamps according to local standards.

The following operations and standard work time will apply:

OPERATION DESCRIPTION	WARRANTY REPORTING CODE	OPERATION NUMBER	MODEL	YEAR AND TIME	SKILL LEVEL
Bulb-Headlamp-Inspect	3.280	3375	WAG, CKE,	.1	M
Replace (Both)-Incl. Aiming		۸	THK	.3	M

# American Motors Sales Corporation

Service Engineering Department • 14250 Plymouth Road • Detroit, Michigan 48232
#### **CLAIM HANDLING**

Several vehicles may be listed on a single Warranty Claim form, reference the Warranty Administration Manual, Section 7, Product Recall Campaign. Complete and mail the reporting half of the notification card (Fig. 1) for each vehicle as soon as the campaign service is complete.

**CAUTION:** On multiple-vehicle claims, do not delay any claim so that CCD will receive it beyond the time outlined in the Warranty Administration Manual.

Instructions: OWNER	instructions: DEALER
If you do not now own this vehicle, please just fill in below (either a, b, or c) and MAIL DIRECTLY TO AMERICAN MOTORS SALES CORPORATION	This section is for the dealer to use when your vehicle goes in for the required attention
	Correction made
a Sold or Traded to:	Correction not required
Name Please Print)	
Address	
City Stare	
b Present owner name and address not known	
Bemoved from service because of collision	Dealer Signature
damage or otherwise	
	Date Vehicle Serviced
······	Campaign Data Reporting Sectio
	ka,
This notice is sent to you in accordance with the re- Safety Act. Jeep Corporation has determined that some 1980 Jee lamps that do not conform to Federal Motor Vehicle and Associated Equipment. Your vehicle may have a by the Federal Standard. In the interest of your safe Corporation wants to inspect your vehicle to assure sary, we will replace the present headiamp with a se venience to you should a replacement unit of your pr available.	paign Involving Your Vehicle quirements of the National Traffic and Motor Vehicle p Wagoneers, Cherokees, and Trucks may have head Safety Standard No. 108, Lamps, Reflective Devices headlamp that is not a sealed beam type as required ety and complete satisfaction with our product, Jeer that proper headlamps have been installed. If neces aled beam type. This service may eliminate an incom- resent headlamp become necessary and not be readily
This notice is sent to you in accordance with the re- Safety Act. Jeep Corporation has determined that some 1980 Jee lamps that do not conform to Federal Motor Vehicle and Associated Equipment. Your vehicle may have a by the Federal Standard. In the interest of your safe Corporation wants to inspect your vehicle to assure sary, we will replace the present headiamp with a se venience to you should a replacement unit of your pr available. Jeep Corporation urges that you contact your Jeep of dealer to inspect the right and left headiamps, and type. This service will be performed at no charge to vehicle will be approximately 45 minutes. Although one hour, we do suggest that you contact your deal	paign Involving Your Vehicle quirements of the National Traffic and Motor Vehicle p Wagoneers, Cherokees, and Trucks may have head Safety Standard No. 108, Lamps, Reflective Devices headlamp that is not a sealed beam type as required ety and complete satisfaction with our product, Jeer that proper headlamps have been installed. If necess aled beam type. This service may eliminate an incon resent headlamp become necessary and not be readily dealer immediately to arrange an appointment for the if necessary, replace one or both with a sealed beam you. The time necessary to inspect and service your the time required to service your vehicle is less that er to arrange an appointment before tendering your

If your dealer does not perform this service on your mutually arranged appointment date or within rive days thereafter and without charge, please contact the local American Motors Sales Corporation Zone Office (listed in your Owner's Manual) or American Motors Corporation, Owner Relations, 14250 Plymouth Road, Detroit, MI 48232 (Telephone (313) 493-2341). If your dealer fails or is unable to provide this service within a reasonable time or without charge, you may wish to notify the Administrator, National Highway Traffic Safety Administration, Washington, D.C. 20590.

When your vehicle goes in for the required attention: Please be sure this complete notification card goes with it because the card is to be used by the dealer for reporting purposes. In case you do not now own this vehicle please send us the "Change of Ownership" information, using side 2 of this card.

Fig. 1 — Owner Notification and Correction Reporting Card

## **Diagnosis and Repair Bulletin**

Jeeo

Subject: Moisture Entering Parking and Front Directional Signal Lamp Assembly Application: 1976-80 CJ Models

File: BODY Body Electrical

Some 1976-80 CJ models may have moisture entering the parking and front directional signal lamp assembly through the wire harness entrance into the upper side of the lamp housing.

Service correction involves repositioning the lamp housing and replacing the lens gasket or the lamp assembly if necessary.

The following parts are available if required:

Quantity	Part No.	Group
AR	5461340	3.292
AR	991400	3.292
	Quantity AR AR	QuantityPart No.AR5461340AR991400

#### PROCEDURE

(1) Remove park and turn signal lamp assemblies from grille panel and inspect mounting gasket for any distortion. Replace gasket if distorted.

(2) Inspect internal bulb sockets for corrosion.
 (a) If corrosion is not present, then continue procedure on existing assemblies.

(b) If corrosion is present, obtain replacement lamp and continue procedure.

(3) Apply chassis lubricant or dielectric compound, 8127445, to bulb socket to prevent corrosion.



Lamp Assembly and Gaskets

(4) Remove two screws that attach lens and gasket to lamp housing. Separate lens from lamp housing and gasket. Rotate housing and gaskets 180° so wires exit from bottom of housing and assemble lens to housing (see illustration).

(5) Install assembly (with new mounting gasket if required) to grille panel being careful not to strip screws.

NOTE: Use locally procured oversized mounting screws if required.

The following operations and standard work times will apply:

OPERATION DESCRIPTION	COST CODE	OPERATION NUMBER	MODEL	YEAR AND TIME 76-80	SKILL LEVEL
LAMP ASSEMBLIES, PARK AND FRONT DIRECTIONAL SIGNAL- INSPECT AND/OR REPOSITION	3.292	3403	CJ	0.1	G
Replace (One or both)	3.292	A	CJ	0.1	G

80-032-BSA

#### American Motors Sales Corporation

### 71 Jeep,

## **Diagnosis and Repair Bulletin**

Subject: Front Door Wire Router Plates

Application 1980 Wagoneer, Cherokee and Truck Models with Door Speakers

File: BODY Body Electrical

No. 80-1 Nov. 8, 1979

#### PROCEDURE

(1) Using DuPont Galvanized Iron and Zinc Refinishing System Step 2 227 S, or equivalent, follow manufacturers directions and prepare galvanized plates for painting.

(2) Prime wire router plates.

(3) Remove speaker wire retainer caps and remove speaker wire from retainers. Remove retainers from doors.

(4) Inspect speaker wires for signs of damage. Repair area(s) of insulation damage with electrical tape, or if wire is broken, repair by soldering wire ends together using rosin core solder or equivalent and wrap with electrical tape.

NOTE: Do not use excessive wrappings of tape as wire may not fit into the retainer.

(5) Insert speaker wire into plate slot and align plate over opening in front door inner panel. Using two screws, fasten plate to door panel. Make sure tang of plate is engaged into door inner panel.

(6) Color coat plates taking care not to spray front door trim panel.

(7) Slide speaker wires into speaker wire retainers. Install retainer cap. Snap speaker wire retainers into plate and secure retainers with screws. Tape both ends of retainers for added speaker wire retention.

Truck Models have 1980 design front doors with a large opening at the front for wire harness routing and previous design front door hinges which allows the door to open farther than 1980 design hinges. This combination of door and hinges causes both an appearance problem due to the large opening and an unusual stress on front door speaker wires.

Some early built 1980 Wagoneer, Cherokee and

Service correction involves repairing broken speaker wires, replacing speaker wire retainers if necessary and installing a wire router plate in each front door.

The following parts are required and will be available after November 26, 1979. Do not order parts before this date.

Description	ption Quantity		Group
PLATE, Wire Router	2	8130421	15.320
SCREW, No. 10-16 x .50	4	8120054	17.671
RETAINER, Door Speaker Wire	AR	5454901	15.320
RETAINER CAP, Door Speaker Wire	AR	5454902	15.320

The following operations and standard work times will apply:

OPERATION DESCRIPTION	COST CODE	OPERATION	MODEL	YEA	SKILL		
		NUMBER	WODEC	80	81	82	LEVEL
PLATES, FRONT DOOR WIRE ROUTER — INSTALL	15.322	15327	Cke-Wag-Trk	0.4			G
Speaker Wires, Repair	15.322	A		0.1			G

80-016-BSJ

#### **71** American Motors Sales Corporation

Service Engineering Department • 14250 Plymouth Road • Detroit, Michigan 48232

## **Diagnosis and Repair Bulletin**

Jeep.

Subject: Air Control Cable Operation

Application: 1978-81 CJ-5 and CJ-7 Models

File: BODY Heater — Air Conditioning

No. 81-1 April 13, 1981

In November, 1980, a new cowl fresh air intake duct assembly was phased into production of 1981 CJ models. The new duct assembly provides improved air control cable and intake duct vent operation and can also be used on all 1978-81 CJ-5 and CJ-7 models.

If service diagnosis indicates that a bind in the fresh air intake duct linkage caused the air control cable to bind or break due to excessive cable operating effort, the new fresh air duct assembly should be installed along with a replacement air control cable if necessary.

The following part is available and may be required:

Description	Quantity	Part No.	Group
DUCT ASSEMBLY,			
Fresh Air Intake	1	5758809	22.020

#### PROCEDURE

#### Removal

- (1) Disconnect battery negative cable.
- (2) Drain two quarts of coolant from radiator into clean container.
- (3) Disconnect heater hoses at heater housing.
- (4) Remove heater housing drain hose.
- (5) On models with air conditioning, remove screws attaching evaporator housing to instrument panel. Move housing away from panel and disconnect wires at air conditioning control switches.
- (6) Remove screw attaching heater motor housing to bracket.
- (7) Remove nuts that attach heater housing to engine compartment side of dash panel.
- (8) Disconnect speedometer cable.
- (9) Remove glove box.

- (10) Tilt heater housing back, pull housing rearward, and lower housing.
- (11) Disconnect heater control cables.
- (12) Remove defroster duct and tube assembly.
- (13) Remove fresh air intake panel from cowl.
- (14) Remove fresh air intake duct assembly from cowl.

#### Installation

- (1) Install defroster duct and tube assembly.
- (2) Raise and secure windshield.
- (3) Install replacement fresh air intake duct assembly.
- (4) Install fresh air intake panel on cowl.
- (5) Connect heater control cables.
- (6) Position heater housing assembly on dash panel.
- (7) Install nuts attaching heater housing to dash panel.
- (8) Install glove box.
- (9) Connect speedometer cable.
- (10) Install screw attaching heater housing to bracket.
- (11) On models with air conditioning, connect wires to air conditioning control switches and install evaporator housing on instrument panel.
- (12) Connect drain tube to heater housing.
- (13) Connect heater hoses.
- (14) Refill radiator.
- (15) Connect battery negative cable.

The standard servicing operations and work times published in the appropriate SSO manual are not affected by this bulletin.

81-060-13J

#### **#I** American Motors Sales Corporation

Service Engineering Department • 14250 Plymouth Road • Detroit, Michigan 48232

## **Diagnosis and Repair Bulletin**

l Jeep.

Subject: Sun Roof Glass Frame Seal

Application: 1980-81 Cherokee, Wagoneer and Truck Models With Manual Sun Roof File: BODY Headlining — Hardtop Enclosure — Exterior Decals and Overlays

No. 81-2 March 2, 1981

A new sun roof glass frame seal for the pop-up sun roof used on 1980-81 Cherokee, Wagoneer, and Truck models has been released for production and service use. The new seal has an improved configuration for increased compression and sealing ability and entered production on January 5, of this year.

If it becomes necessary to replace the sun roof glass frame seal on a 1980-81 Cherokee, Wagoneer, or Truck model pop-up sun roof, the new seal should be used.

The following part is available and may be required:

Description	Quantity	Part No.	Group
SEAL, Sun Roof Glass Frame	1	8133809	28.811

#### PROCEDURE

#### Removal

(1) Remove glass assembly.

- (2) Apply 3M Release Agent, or equivalent, to seal and allow several minutes for penetration.
- (3) Apply second application of release agent to seal and allow several minutes for adhesive bond to soften.
- (4) Remove seal from frame.
- (5) Remove all adhesive residue from frame using 3M General Purpose Adhesive Remover, or equivalent.

#### Installation

- (1) Apply thin bead of 3M Super Weatherstrip Adhesive, or equivalent, in frame channel.
- (2) Position and install replacement seal in channel.
- (3) Apply thin film of petroleum jelly to seal and glass contact surfaces.
- (4) Install glass assembly.

The following standard service operation and work times will apply:

OPERATION DESCRIPTION	COST	OPERATION	HODE	YEA	SKILL		
	CODE	NUMBER	MODEL	80	81	82	LEVEL
SEAL, SUN ROOF GLASS TO FRAME — REPLACE	28.417	15.375	Cke, Wag., Trk.	0.4	0.4		G

81-065-BSJ

### **71** American Motors Sales Corporation

Service Engineering Department • 14250 Plymouth Road • Detroit, Michigan 48232

#### SCN 376

/ Jeep

## **Diagnosis and Repair Bulletin**

Subject: Sun Roof Arm Operator Application: 1979-80 CJ-7 File: BODY Hardtop Models With Type-1 Headlining-Hardtop Sun Roof **Enclosure-Exterior Decals and Overlays** No. 80-2 Jan. 14, 1981 A new metal arm operator for the Type-1 sun roof used FRAME on 1979 and some 1980 CJ-7 hardtop models has been released. The new arm operator provides increased sealing ability by applying additional compression force on the sun roof weatherstrip improving sealing against water leaks. GLASS

If it becomes necessary to replace the arm operator on a Type-1 sun roof, the following new part should be used.

Description	Quantity	Part No.	Group
OPERATOR, Sun Roof Arm (Metal)	1	8129249	28.806

#### PROCEDURE

- (1) Close sun roof.
- (2) Remove arm operator attaching screws and nuts (see illustration).
- (3) Move arm operator into channel opening and remove arm operator.

Decals and Overlays No. 80-2 Jan. 14, 1981

- (4) Insert replacement arm operator into channel opening and position arm operator on sun roof.
- (5) Install arm operator attaching screws and nuts.

The following standard servicing operation and work time will apply:

OPERATION DESCRIPTION	COST CODE	OPERATION NUMBER		YEA	SKILL		
			MODEL	79	80	81	LEVEL
OPERATOR, SUN ROOF ARM — REPLACE	28.416	25.204	93	0.2	0.2		G

80-164-BSJ

### American Motors Sales Corporation

## **Diagnosis and Repair Bulletin**

Jeep.

Subject: New Sun Roof Vinyl Trim Ring

On some 1980 Cherokee and Wagoneer models equipped with the manual sun roof option, the sun roof trim ring may hang down due to pressure applied

to the trim ring by the headlining. A new sun roof

trim ring has been developed to prevent this condition.

Service correction involves measuring the distance between the sun roof frame and headlining, installing

a new sun roof trim ring, and replacing the front

The following part is available and may be required:

Quantity

1

headlining if necessary.

Description

Vinyl Trim

**RING**, Sun Roof

Application: 1980 Cherokee and Wagoneer Models File: BODY Headlining-Hardtop Enclosure-Exterior Decals and Overlays

No. 80-1 Sept. 18, 1980

#### PROCEDURE

(1) Remove sun roof trim ring.

(2) If headlining extends below trim ring surface of sun roof frame, measure distance between trim ring surface of sun roof frame and headlining.

(a) If distance is less than one inch, proceed to step (3).

(b) If distance is more than one inch, replace front headlining as outlined in 1980 Jeep Technical Service Manual. Use original headlining as template, cut sun roof opening in replacement headlining before installation, and proceed to step (3).

(3) Install new sun roof trim ring.

The following standard servicing operations and work times will apply:

Part No.

8133577

Group

28.810

OPERATION DESCRIPTION	COST	OPERATION		YEA	SKILL		
	CODE	NUMBER	MODEL	80	81	82	LEVEL
RING, SUN ROOF VINYL TRIM – REPLACE Headlining, front – Replace	28.415 29.015	25201 A	Cke-Wag.	0.2 0.4			G G

80-150-BSJ

#### **71** American Motors Sales Corporation

Service Engineering Department • 14250 Plymouth Road • Detroit, Michigan 48232 Additional copies of this bulletin are available through your zone office.

80-79

## **Diagnosis and Repair Bulletin**

Subject: Water Leak or Wind Noise Recommended Sealing Products.

Application: All 1980-81 Jeep Vehicles

File: BODY Metal Repair — Painting — Water Leaks/Wind Noise

No. 81-2 Jan. 21, 1981

Some 1981 vehicles may exhibit some water leak and wind noise problems. Locating the leak can be accomplished by following the test procedures described in chapter 3A of the Technical Service Manual.

The following chart describes some of these typical water leak and wind noise areas and recommended products which can be used to seal these areas.

### Water Leak or Wind Noise Recommended Sealing Products

	Spot Weld Burn Holes	Interior Heater Plenum Chamber	Body Joints and Seams	Floor Pan Plug Holes	Weld Nut and Screw Holes	Drip Raits	Windshield Structurally Sound	Between Butyl Tape and Glass	Between Glass and Weatherstrip	Between Weatherstrip and Body Panel
3M Products										
Brushable Seam Sealer	•		٠	•	•					
· · · · · · · · · · · · · · · · · · ·										
Joint and Seam Sealer		٠	•		•					
All-Around Auto Body Sealant			•	•	•					
Drip Check Sealer					•	•				
Strip Calk	•		•	•	•					
Auto Bedding and Glazing Compound										•
Windshield Sealer							1041 B		•	
Windo-Weld Resealant							•	•		
Kent Industries Products								1		1
Quik Leak Check	•	٠	•		•	٠				
Seal-a-Seam			•	•						
Silver Seal						٠				
Wet/Dry Resealant							•	•		
Leak Seal							•			
Glass Mastic									•	•
Liquid Rubber								•		
Bedding and Glazing Compound										

81-036-BSA/J

### **VI** American Motors Sales Corporation

#### SCN 115

71 Jeep,

## **Diagnosis and Repair Bulletin**

**Subject: Interior Wind Noises** 

Some 1980-81 Cherokee, Wagoneer, and Truck models may develop an interior wind noise or air leak that may be the result of air entering the vehicle in the following areas:

- Front Door Division Channel
- Intersection of Cowl-A-Pillar-Instrument Panel
- Holes in Inner Cowl Panels

Service correction involves performing the repair procedures outlined in this bulletin at each of these areas.

The following parts are available and required:

Description	Quantity	Part No.	Group
BUTTON, Plug	3	4001716	27.038
TOUCH-N-FOAM	AR	8130438	30.051
GASKET-IN-A-TUBE	AR	8993317	15.260

#### PROCEDURE

#### Front Door Division Channel

Noise from this area can be isolated by using a stethoscope placed along the rolled edge of the division channel inside the vehicle during road testing.

(1) Insert small flat blade screwdriver in gap between rolled section and flat section of front door division channel. Insert blade at top and bottom (Fig. 1), and open gap slightly to allow application of sealer.

(2) Apply black silicone sealer, Gasket-In-A-Tube, or equivalent, along gap in division channel.

- (3) Remove screwdriver.
- (4) Wipe off excess sealer.

NOTE: Steps (1) through (4) are to be performed on both the inside and outside surfaces of the division channel.

Application: 1980-81 Cherokee, Wagoneer and Truck Models File: BODY Metal Repair-Paint-Water Leaks/Wind Noise

No. 80-3 Oct. 9, 1980

(5) Repeat sealant application on opposite front door division channel.



#### Intersection of Cowl-A-Pillar-Instrument Panel

An air leak at this area can be detected from inside the vehicle using a stethoscope placed at the lower corner of the windshield at both A-pillars during a road test. In severe cases, an air leak can be detected by placing a hand in the windshield lower corner area to feel the air flow.

(1) Raise hood.

(2) Using grease pencil, place mark on both outer cowl panels 1-inch below horizontal flange and 5/8-inch outboard of vertical flange (Fig. 2).

(3) Centerpunch and drill 1/2-inch diameter hole in each panel at marked locations.

(4) Shake Touch-N-Foam container and install nozzle and tubing on container.

#### **FI American Motors Sales Corporation**

Service Engineering Department • 14250 Plymouth Road • Detroit, Michigan 48232



Fig. 2

(5) Turn Touch-N-Foam container upside down and make trial application of foam on section of cardboard or newspaper.

(6) Insert container tube into holes drilled in cowl panels until container tube contacts A-Pillar.

(7) Pull tubing out approximately 1-inch, aim for A-Pillar, and press and hold nozzle for 8 to 10 seconds.

(8) Release container nozzle. Allow few seconds for foam to stop flowing from container tube before removing tube.

(9) Repeat steps (6) through (8) on opposite outer cowl panel.

NOTE: Uncured foam may be removed from painted surfaces by carefully wiping the area with lacquer thinner or an equivalent solvent.

(10) Install button plugs in holes drilled in outer cowl panels.

(11) Close hood.

(12) Allow foam to cure for 1-1/2 hours; then road test vehicle to verify noise correction.

(13) Remove excess sealer that may appear in lower corner of windshield weatherstrip after foam has cured. Use razor blade or similar tool to remove excess sealer.

#### Holes in Inner Cowl Panels

The inner cowl panel holes may produce a draft on the driver and passenger's legs rather than an actual wind noise. This condition can be detected by a visual inspection.

(1) Open driver's side door and view inner cowl panel through upper hinge pocket in area where instrument panel lower attaching bolt is located (Fig. 3).

(2) Locate weld nut hole in cowl panel that is approximately 3-inches above and 1/2-inch to rear of instrument panel lower attaching bolt (Fig. 3).

(3) Plug weld nut hole using 3M Strip-Caulk or equivalent.

(4) Plug 1/2-inch hole in inner cowl panel located above parking brake assembly. Plug hole using button plug (Fig. 3).

(5) Repeat steps (1) through (3) on passenger side inner cowl panel.

NOTE: The passenger side inner cowl panel has only one hole in it.



Fig. 3

### The following standard servicing operations and work times will apply:

•

	COST CODE	OPERATION NUMBER	MODEL	YEAR AND TIME			SKILL
OPERATION DESCRIPTION				80	81	82	LEVEL
CHANNEL, FRONT DOOR DIVISION – SEAL	23.118	25011	10-20	0.2			G
Material allowance is \$0.70 PANELS, COWL SIDE — SEAL COWL-A-PILLAR-INSTRUMENT PANEL	20.155	20121	10-20	0.2			G
INTERSECTION — SEAL	20.195	20135	10-20	0.2			G
		1					80-149-BS

80-83

### Jeep,

## **Diagnosis and Repair Bulletin**

Subject: 1980 Phase-Out/1981 Phase-In Program Paint Information

**Application: 1980 Jeep Vehicles** 

File: BODY Metal Repair-Painting-Water Leaks/Wind Noise

No. 80-2 July 31, 1980

As part of the 1980 Phase-Out/1981 Phase-In Program, ten new 1981 colors may be used on 1980 models. They are:

1981 Paint Code	Color	Replaces
1A	Montana Blue	ОН
1B	Moonlight Blue	OJ
1C	Sherwood Green Metallic	OE
1D	Autumn Gold	OR
<b>1E</b>	Copper Brown Metallic	New Color
1H	Chestnut Brown Metallic	9A
1J	Vintage Red Metallic	9C
1K	Deep Maroon Metallic	9P
<b>1L</b>	Steel Gray Metallic	OB
1M	Oriental Red	OP

**NOTE:** Some intermix formulas are marked N/A because they were not available at time of publication. Contact your local paint jobber for information not contained herein.

MONTANA BLUE		MONTAN	IA BLUE	MONTAN	A BLUE	MONTANA BLUE		
ENAMEL		ENAI	MEL	LACG	UER	LACQUER		
DITZ	LER	SHERWIN-WILLIAMS DITZLE		LER	SHERWIN-WILLIAMS			
DAR3	3366	35-31503 DDL336		3366				
Mixing	1 Quart	Mixing	1 Quart	Mixing	1 Quart	Mixing	1 Quart	
Code	Setting	Code	Setting	Code	Setting	Code	Setting	
DMR490 DMR411 DMR474 DMR400 DMR414 DXR495 DMR499	60 122 185 297 452 472 1052	F5R-100 F5L-70 F5B-81 V6V-175 F5W-80	108.0 222.0 450.0 495.0 953.0	DMA359 DMA375 DMA321 DMA358 DMA311 DMA310	14 24 444 554 884 1044	L4R-320 L4L-309 L4M-321 L4W-301	114.0 230.0 358.0 922.0	
	1001							

#### **VII** American Motors Sales Corporation

Service Engineering Department • 14250 Plymouth Road • Detroit, Michigan 48232

MOONLIGHT BLUE MOONLIGHT BLUE		IT BLUE	MOONLIGH	IT BLUE	MOONLIGH	IT BLUE	
ENAMEL ENAMEL		EL	LACQU	JER	LACQU	JER	
DITZI	LER 367	SHERWIN-W 35-315	ILLIAMS	DITZL DDL3	ER 367	SHERWIN-W 34-31	TILLIAMS 504
Mixing	1 Quart	Mixing	1 Quart	Mixing	1 Quart	Mixing	1 Quart
Code	Setting	Code	Setting	Code	Setting	Code	Setting
DMR486 DMR400 DMR490 DXR495 DMR413	7 17 61 81 1081	F5P-92 F5W-80 F5Y-72 F5B-81 V6V-175 F5L-94	14.1 35.3 56.5 162.0 207.0 913.0	DMA311 DMA317 DMA320 DMA304 DMA310	4 132 192 672 992	L4W-301 L4Y-334 L4B-320 L4L-313	20.7 51.1 83.7 890.0
SHERWOOI	D GREEN	SHERWOOJ	D GREEN	SHERWOO	D GREEN	SHERWOO	D GREEN
METAI	LLIC	METAJ	LLIC	META	LLIC	META	LLIC
ENAM	IEL	ENAM	4EL	LACQ	UER	LACQ	UER
DITZI DAR3	.ER 368	SHERWIN-W 35-31	/ILLIAMS 505	DITZ	LER	SHERWIN-V 34-31	VILLIAMS 505
Mixing	1 Quart	Mixing	1 Quart	Mixing	1 Quart	Mixing	1 Quart
Code	Setting	Code	Setting	Code	Setting	Code	Setting
DMR435 DMR476 DMR490 DMR440 DXR495 DMR482	10 18 94 248 268 1038	F5N-76 F5N-85 F5S-101 F5B-81 F5G-79 V6V-175 F5Y-72	56.0 112.0 180.0 264.0 384.0 429.0 913.0	N/A		L4S-345 L4S-335 L4B-320 T1C-324 L4N-342 L4G-337 L4Y-334	6.5 23.4 43.0 69.0 226.0 434.0 890.0
AUTUMN	i gold Mel	AUTUMN ENAM	AUTUMN GOLD ENAMEL		GOLD UER	AUTUM	N GOLD UER
DITZI	JER	SHERWIN-WILLIAMS		DITZ	LER	SHERWIN-V	WILLIAMS
DAR3	369	35-31506		DDL3	1369	34-31	
Mixing	1 Quart	Mixing	1 Quart	Mixing	1 Quart	Mixing	1 Quart
Code	Setting	Code	Setting	Code	Setting	Code	Setting
DMR491 DMR400 DMR487 DMR486 DXR495 DMR499	136 326 476 836 856 1106	F5R-100 F5B-81 F5Y-93 V6V-175 F5W-80	6.7 35.5 449.0 494.0 984.0	DMA356 DMA313 DMA333 DMA311 DMA329	6 90 110 540 1060	L4M-338 L4B-320 L4W-301 L4Y-303	4.8 19.1 448.0 924.0
COPPER	COPPER BROWN		BROWN	COPPER	BROWN	COPPER	BROWN
META	METALLIC		LLIC	META	LLIC	META	ALLIC
ENAL	FNAMEL		MEL	LACC	JUER	LACC	QUER
DITZ	LER	SHERWIN-V 35-31	WILLIAMS	DIT2	LER	SHERWIN- 34-31	WILLIAMS
Mixing	1 Quart	Mixing	1 Quart	Mixing	1 Quart	Mixing	1 Quart
Code	Setting	Code	Setting	Code	Setting	Code	Setting
N/.	A	F5M-71 F5N-76 V6V-175 F5S-74	42.1 447.0 492.0 913.0	N/.	A	L4B-302 L4W-301 L4M-341 L4Y-334 L4S-343	8.5 22.2 56.4 158.0 308.0

METALLIC ENAMEL	CHESTNUT BROWN METALLIC ENAMEL	CHESTNUT BROWN METALLIC LACQUER	CHESTNUT BROWN METALLIC LACQUER	
DAR3371	SHERWIN-WILLIAMS 35-31508	DITZLER DDL3371	SHERWIN-WILLIAMS 34-31508	
Mixing 1 Quart Code Setting	Mixing 1 Quart Code Setting	Mixing 1 Quart Code Setting	Mixing 1 Quart Code Setting	
DMR43532DMR453358DMR490434DXR495454DMR4761034	F5S-69         88.0           F5B-81         194.0           F5M-78         459.0           V6V-175         504.0           F5N-85         902.0	DMA320         26           DMA309         34           DMA312         62           DMA360         122           DMA307         982	L4S-345         14.4           L4S-343         57.5           T1C-324         115.0           L4B-320         201.3           L4M-338         496.0           L4N-342         884.0	
VINTAGE RED METALLIC ENAMEL	VINTAGE RED METALLIC ENAMEL	VINTAGE RED METALLIC LACQUER	VINTAGE RED METALLIC LACQUER	
DITZLER DAR3372	SHERWIN-WILLIAMS 35-31509	DITZLER	SHERWIN-WILLIAMS 34-31509	
Mixing 1 Quart Code Setting	Mixing 1 Quart Code Setting	Mixing 1 Quart Code Setting	Mixing 1 Quart Code Setting	
DMR41010DMR451290DMR435336DMR452856DXR495876DMR4991036	F5B-81         25.8           F5M-96         103.0           F5S-101         348.0           V6V-175         393.0           F5M-71         908.0	N/A	L4B-320         13.8           L4S-345         124.0           L4M-318         256.0           T1C-324         532.0           L4M-341         882.0	
DEEP MAROON METALLIC ENAMEL DITZLER	DEEP MAROON METALLIC ENAMEL SHERWIN-WILLIAMS 35-31510	DEEP MAROON METALLIC LACQUER DITZLER	DEEP MAROON METALLIG LACQUER SHERWIN-WILLIAMS	
DEEP MAROON METALLIC ENAMEL DITZLER Mixing 1 Quart Code Setting	DEEP MAROON METALLIC ENAMEL SHERWIN-WILLIAMS 35-31510 Mixing 1 Quart Code Setting	DEEP MAROON METALLIC LACQUER DITZLER Mixing 1 Quart	DEEP MAROON METALLIG LACQUER SHERWIN-WILLIAMS 34-31510 Mixing 1 Quart	
DEEP MAROON METALLIC ENAMEL DITZLER Mixing 1 Quart Code Setting N/A	DEEP MAROON METALLIC ENAMEL           SHERWIN-WILLIAMS 35-31510           Mixing         1 Quart Code           Code         Setting           F5S-74         80.0           F5P-92         224.0           F5B-81         384.0           V6V-175         429.0           F5M-71         908.0	DEEP MAROON METALLIC LACQUER DITZLER Mixing 1 Quart Code Setting N/A	DEEP MAROON METALLIG LACQUER SHERWIN-WILLIAMS 34-31510 Mixing 1 Quart Code Setting L4S-343 22.7 L4B-320 107.7 L4M-321 312.0 T1C-324 538.0 L4M-341 878.0	
DEEP MAROON METALLIC ENAMEL DITZLER Mixing 1 Quart Code Setting N/A STEEL GRAY METALLIC ENAMEL	DEEP MAROON METALLIC ENAMEL SHERWIN-WILLIAMS 35-31510 Mixing 1 Quart Code Setting F5S-74 80.0 F5P-92 224.0 F5B-81 384.0 V6V-175 429.0 F5M-71 908.0 STEEL GRAY METALLIC ENAMEL	DEEP MAROON METALLIC LACQUER DITZLER Mixing 1 Quart Code Setting N/A STEEL GRAY METALLIC LACQUER	DEEP MAROON METALLIG LACQUER SHERWIN-WILLIAMS 34-31510 Mixing 1 Quart Code Setting L4S-343 22.7 L4B-320 107.7 L4M-321 312.0 T1C-324 538.0 L4M-341 878.0 STEEL GRAY METALLIC LACQUER	
DEEP MAROON METALLIC ENAMEL DITZLER Mixing 1 Quart Code Setting N/A STEEL GRAY METALLIC ENAMEL DITZLER DAR3374	DEEP MAROON METALLIC ENAMEL SHERWIN-WILLIAMS 35-31510 Mixing 1 Quart Code Setting F5S-74 80.0 F5P-92 224.0 F5B-81 384.0 V6V-175 429.0 F5M-71 908.0 STEEL GRAY METALLIC ENAMEL SHERWIN-WILLIAMS 35-31511	DEEP MAROON METALLIC LACQUER DITZLER Mixing 1 Quart Code Setting N/A N/A STEEL GRAY METALLIC LACQUER DITZLER	DEEP MAROON METALLIG LACQUER SHERWIN-WILLIAMS 34-31510 Mixing 1 Quart Code Setting L4S-343 22.7 L4B-320 107.7 L4M-321 312.0 T1C-324 538.0 L4M-341 878.0 STEEL GRAY METALLIC LACQUER SHERWIN-WILLIAMS 34-31511	
DEEP MAROON METALLIC ENAMEL DITZLER Mixing 1 Quart Code Setting N/A STEEL GRAY METALLIC ENAMEL DITZLER DAR3374 Mixing 1 Quart Code Setting	DEEP MAROON METALLIC ENAMEL SHERWIN-WILLIAMS 35-31510 Mixing 1 Quart Code Setting F5S-74 80.0 F5P-92 224.0 F5B-81 384.0 V6V-175 429.0 F5B-81 384.0 V6V-175 429.0 F5M-71 908.0 STEEL GRAY METALLIC ENAMEL SHERWIN-WILLIAMS 35-31511 Mixing 1 Quart Code Setting	DEEP MAROON METALLIC LACQUER DITZLER Mixing 1 Quart Code Setting N/A STEEL GRAY METALLIC LACQUER DITZLER Mixing 1 Quart Code Setting	DEEP MAROON METALLIG LACQUER SHERWIN-WILLIAMS 34-31510 Mixing 1 Quart Code Setting L4S-343 22.7 L4B-320 107.7 L4M-321 312.0 T1C-324 538.0 L4M-341 878.0 STEEL GRAY METALLIC LACQUER SHERWIN-WILLIAMS 34-31511 Mixing 1 Quart Code Satting	

ORIENTAL RED ENAMEL DITZLER		ORIENTA ENAM	L RED EL	ORIENTA LACQ	L RED UER	ORIENTAL RED LACQUER		
		SHERWIN-W 35-31	VILLIAMS 512	DITZI DDL3	DITZLER DDL3375		SHERWIN-WILLIAMS 34-31512	
Mixing Code	1 Quart Setting	Mixing Code	1 Quart Setting	Mixing Code	1 Quart Setting	Mixing Code	1 Quart Setting	
N/	/Α	F5W-80 F5B-81 F5P-92 V6V-175 F5E-86	7.4 31.6 423.0 468.0 953.0	DMA358 DMA333 DMA359 DMA362	4 132 506 1058	L4W-301 L4B-302 L4M-321 L4E-317	2.7 14.6 406.0 918.0	
							00 1 96 DS	

## **Diagnosis and Repair Bulletin**

Subject: Paint Information — All Jeep Vehicles **Application: 1980 Jeep Vehicles** 

File: BODY Metal Repair-Painting-Water Leaks/Wind Noise

No. 80-1 Sept. 27, 1979

Attached is the 1980 DuPont color chart. Color names and code numbers are included in each chart.

This bulletin is being sent to all Jeep dealers in reduced quantities. If additional quantities are

required, contact your Zone Service Manager, or Service Manager, or Service Representative.

80-006-21 A/J

American Motors Sales Corporation

Service Engineering Department • 14250 Plymouth Road • Detroit, Michigan 48232 Additional copies of this bulletin are available through your zone office.

80-88



KEY: S-Spirit, E-Eagle, P-Pacer, C-Concord, J-Jeep

LUCITE Acrylic Lacquer, CENTARI Acrylic Enamel, and DULUX Enamel are Registered Trademarks of the Du Post Company. Suffixes shown are subject to change when Formulations are finalized.

Color chips reproduced on paper cannot be considered totally accurate color matches to either car makers standards or Du Pont material.



E-28001

### AMERICAN MOTORS CORPORATION PRIOR YEARS COLOR INFORMATION 1977

Mfr. Paint Code	Color	Lucite* Code	Centariª Cede	Dolux* Code	Mfr. Paint Code	Enter	Lucite <sup>4</sup> Code	Centari* Code	Dulux* Code
67	Alpine White	43499L	43499A	43499D	70	Powder Blue	84102LH	4410244	14102011
12	Brandywine Met.	43510LM	43510AW	435100M	76	Dak Leaf Brown	4415210	44192A0	44192UH
P1	Black	99L	994	93.005	78	Midnight Blue Mat	43101L	40101A	4410200
6D	Sand Tan	441111	44111A	441110	71	I oden Green Met	44155LM	4419340	44153UH
6)	Silver Frost Met.	441131	44113A	441130	71	Colden Gierer Met	4413461	44174AT	4415400
6P	Firecracker Red	44116LM	44116AW	44116DW	78	Lime Green	44133LH	4419340	4419508
6R	Brilliant Blue	44117LH	44117AH	44117D	7₩	Cantain Rive Met	44150LM	4412040	4419000
61	Sunshine Yellow	44119LH	44119AH	441190	74	Тамен Огавле	4413/LIT	4419/AR	4419/08
7A	Misty Jade Met.	441901	44190A	441900H	77	Sup Grange	44130LI	44130A	4410000
7B	Mocha Brown Met.	44191LH	44191AM	44191DM	en l	Closet Ded Mat	44133LI	44133AN	441990n
70	Autumn Red Met.	44793LW	44793AW	44793DM	90	vidiel neu mel.	4010014	4510UAM	-

### 1978

Mir. Paint Code	Celor	Lucite* Code	Centari# Code	Datux* Code	Mfr. Paint Code	Celor	Lucite* Code	Centari* Code	Dulux*
P1	Black	99L	99A	93-005	7K	Midnight Blue Met.	44193LM	HAF9144	441930H
67	Alpine White	43499L	43499A	43499D	71	Loden Green Met.	44194LH	44194AH	44194DH
60	Sand Tan	44111L	44111A	44111D	7M	Golden Ginger Met.	441951 8	441954H	44195DM
6P	Firecracker Red	44116LM	44116AW	44116DW	7W	Captain Blue Met.	441971H	44197AH	44197DH
6R	Brilliant Blue	44117LH	44117AH	44117D	72	Sun Orange	441991H	44199AH	4419904
6V	Sunshine Yellow	44119LH	44119AH	44119D	84	Khaki	451031	451034	451030
_7B	Mocha Brown Met.	44191LH	44191AM	44191DM	8B	British Bronze Met	451021	45102AH	451020
70	Autumn Red Met.	44793LW	44793AW	44793DM	8C	Quicksilver Met	45104	451044H	4510201
7D	Powder Blue	44192LH	44192AH	44192DH	8D	Claret Met.	45100LW	45100AM	45100DW

1979

Mfr. Paint Code	Celor	Usage	Lucite* Code	Centari® Code	Dulux* Code	Mfr. Paint Code	Color	Usage	Lucite* Code	Centari* Code	Dulux* Code
P1	Black	S-C-P-J	99L	99A	93-005	91	Arrowhead Silver Met	1	457061	457064	457060
6P	Firecracker Red	S-C-P-J	44116LM	44116AW	44116DW	9K	Sable Brown Met	S.C.P.I	457071 H	45707AM	4570704
88	Khaki	S-C-P	45103L	45103A	45103D	91	Saxon Yellow	S.C.P.I	457081	43791011	4570804
8B	British Bronze Met.	S-C-P	45102L	45102AH	45102DH	9M	Starboard Blue Met.	S.C.P	457091	457094	4570901
8C	Quick Silver Met.	S-C-P	45104L	45104AH	45104DH	9N	Morocco Buff	S-C-P-I	457101	457104	457100
9A	Alpaca Brown Met.	S-C-P-J	45700L	45700AH	45700DH	99	Bordeaux Met.	S.C.P.I	457111 M	45711AW	4671104
98	Olympic White	S-C-P-J	45701L	45701A	45701D	9T	Ensign Blue	1	457131	457134	457130
90	Russet Met.	S-C-P-J	45702LM	45702AW	45702DM	9₩	Mandarin'Orange		457141 H	45714AH	45714DH
9E	Wedgwood Blue	S-C-P-J	45704L	45704A	45704D	9Z	Misty Beige Met. CC/CC	P	458501 H	45850AW	-
91	Cumberland Green Met.	S-C-P-J	45705L	45705A	45705DH				TOOBOCH	4000000	· · · · ·

KEY S-Spirit, C-Concord, P-Pacer, J-Jeep

#### INTERIOR COLORS

#### **1980 AMERICAN MOTORS CORPORATION**



#### **1980 AMERICAN MOTORS** STRIPING COLORS

MFR. PAINT CODE	COLOR	STOCK NUMBER		
P84	Red Gold	B8095LM		
R40	Black	99L		
R80	Blue	43688LH		
R122 Russet		45717LH		

LUCATE Acrylic Lacquer, CENTARI Acrylic Enamel, and DULUX Enamel are Registered Trademarks of the Du Pont Company. Suffixes shown are subject to change when Formulations are finalized. Color chips reproduced on paper cannot be considered totally accurate color matches to either car makers standards or Du Pont material.



E-28001

AUTOMOTIVE REFINISH COLORS Page 2

QUPOND



File: Service General No.81-10 March 20,1981

Subject	Information
Revision to Part Number In DRB 81-1, Transfer Case Output Shaft Seal Leak Diagnosis, Dated February 23, 1981, and Filed Under CHASSIS - Transfer Case/ Quadra-Trac	The part number for the front and rear output seal listed in the subject bulletin has been revised. The new part number for this seal is 8133432. Please note this change in your copies of the subject bulletin.
Oil Return Channel Access Hole Plug Service - 1980-81 Jeep Model 219 Quadra-Trac Transfer Case	A rear bearing oil return channel access hole has been added to the rear case on 1980-81 model 219 transfer cases as a running change. A rubber plug, part number 8131617, is used to seal the access hole. When servicing the rear case on a 1980-81 Model 219 transfer case, the rubber plug which is located in the upper side portion of the rear case should also be inspected. If the plug has become loose, damaged, or will not seal properly, a replacement plug should be installed. In addition, if the rear case is replaced, be sure to install a plug as the replacement case may not have a plug installed

### **FI** American Motors Sales Corporation

File: Service General No. 81-8 Feb.19, 1981

Subject	Information
Windshield Wipers Inoperative On Low and Intermittent Speeds - 1980-81 Cherokee, Wagoneer and Truck Models - Addition to Windshield Wiper Service Diag- nosis, Page 3T-11 In 1980-81 Jeep Technical Service Manuals	When checking for loose connections and ground circuit continuity, be sure to check for a poor ground between the windshield wiper switch and dash panel. To correct this condition, remove the switch and install a 7/16 I.D. star washer, G178551, between the switch and dash panel to improve the ground.
Correction to Clutch Aligning Tool Number - 1980 Jeep Technical Service Manual Supplement and 1980-81 Jeep Technical Service Manuals	The clutch aligning tool number for four-, six-, and eight-cylinder engines in the 1980 Jeep Technical Service Manual Supplement and 1980-81 Jeep Technical Service Manuals is incorrect.
	The correct number for this tool is J-5824-01. Please note this correction in Chapter 2A of the 1980 Jeep Technical Service Manual Supplement and 1980-81 Jeep Technical Service Manuals.
~	

/ Jeep.

**VI American Motors Sales Corporation** Service Engineering Dept. • 14250 Plymouth Rd. • Detroit, Mich. 48232 Additional copies of this letter are available through your zone office. /I Jeep. 🔤

# **Service Technical Letter**

File: Service General No. 81-6 Jan. 23, 1981

Subject	Information
Water Leaks Caused By Dealer Installed Radio Antenna - 1981 Jeep Vehicles	Some 1981 Jeep vehicles may have water leaking into the passenger compartment through holes made for radio antenna installation. This is a result of water being routed along the antenna lead-in cable and entering the compartment through the dash panel which may not be sealed by grommets or other suitable sealers. When installing an antenna, be sure a grommet is used where the antenna cable goes through the dash panel and be sure the cable is properly seated in the grommet hole.
Power Steering Pressure Test Gauge Adapter Set Tool Number Revision	The pressure and return port fittings on 1980-81 Jeep power steering pumps and gears have metric threads. In order to connect the pressure test gauge J-21567 to these fittings, it will be necessary to use Adapter Set J-5176-20. Please note this information in Chapter 2L of your 1980 and 1981 Jeep Technical Service Manuals.
Correction to 1980-81 Cherokee and Wagoneer Fuel Tank Capacity Specification Charts	The fuel tank capacity for all 1980-81 Cherokee and Wagoneer models is 20.5 gallons (77.6 liters). Please note this change in the Fuel Tank Specifications Charts on page 1J-10 of the 1980 Jeep Technical Service Manual, page 1J-11 of the 1981 Jeep Technical Service Manual, page 88 of the 1980 Jeep Service Specifications Handbook, and page 90 of the 1981 Jeep Service Specifications Handbook.

### American Motors Sales Corporation

## Service Technical Letter (cont'd)

Subject	Information
Correction to 1980 Jeep Four- Cylinder Engine Piston Fit Information	<ul> <li>The following information should be used when fitting pistons in 1980 Jeep four cylinder engines:</li> <li>Measure the cylinder bore at a point 2-1/4 inches from the top of the bore.</li> <li>Measure the piston diameter at a point perpendicular to the piston pin and 1-13/16 inches from the top surface of the piston.</li> <li>Please note these corrections on pages 26 and 30 of the 1980 Jeep Technical Service Manual Supplement.</li> </ul>
Short Oil Pump Attaching Screw Torque Specification Revision - 1981 6-Cylinder Engines	The torque specification for the short oil pump attaching screw used on 1981 6-Cylinder engines has been revised as follows: <u>USA (Foot/Pounds) Metric (Nm)</u> <u>Service Service Service</u> Service In-Use Service In-Use Set-To Recheck Set-To Recheck <u>Torque Torque Torque Torque</u> 17 12-20 23 16-27 Please note this revision in your 1981 AMC Technical Service Manual and 1981 AMC Speci- fications Handbook.

≡**71** Jeep Ξ

# **Service Technical Letter**

File: Service General No. 81-4 Nov. 10, 1980

Subject		Informatio	on	
1981 6-cylinder Main Bearing Capscrew Torque Specification Revision	The 1981 6 specificat	The 1981 6-cylinder main bearing capscrew torque specification has been revised as follows:		cew torque ows:
	<u>U.S.A. (</u>	Foot-pounds)	Metric (N	<u>m</u> )
	Service Set-To Torque	Service In-Use Recheck Torque	Service Set-To Torque	Service In-Use Recheck Torque
	65	65-70	88	88-95
	Please not Technical Specificat	e this revision in Service Manual and ions handbook.	n your 1981 I 1981 Jeep	Јеер
Reverse Gear Selector Pivot Pin Service — 1980-81 SR4 Four-Speed Manual Transmission	If it is n four-speed out or dam selector p to any oth is threade as the rev or damaged be replace	ecessary to servic manual transmissi aged gear conditic ivot pin should be er damaged compone d into the transmi erse lever pivot, by the conditions d to ensure proper	e a 1980-81 on for a ge on, the reve replaced i nts. The p ssion case may have be described shifting.	SR4 ear jump- erse gear in addition oin, which and serves ecome bent and should
Fuel Feedback Modules Damaged By Incorrect Battery Cable Connection - 1980-81 Jeep Vehicles Equipped With Fuel Feedback System	It is impo connected negative-t fuel feedb damage the	rtant that the bat to the battery pos o-negative to prev ack module. Rever alternator diodes	tery cables itive-to-po ent damagin se polarity and radios	are ositive and og the may also.

### **FI** American Motors Sales Corporation

/ Jeep

# **Service Technical Letter**

File: Service General No. 80-19 Nov. 21, 1980

Subject	Information
Revision to Diagnosis and Repair Bulletin No. 80-6 Exhaust Gas Recirculation (EGR) System Revision, Dated October 27, 1980, Filed Under POWER PLANT — Fuel and Exhaust Systems	The service procedure in the subject D&RB is correct. However, the second paragraph in the text should read as follows: Service revision involves replacing the EGR valve restrictor plate and forward delay valve, and adding a non-linear valve to the spark advance system.

**FI American Motors Sales Corporation** Service Engineering Dept. • 14250 Plymouth Rd. • Detroit, Mich. 48232 Additional copies of this letter are available through your zone office.

File: Service General No. 80-18 Sept. 25,1980

Subject	Information
Sun Roof Sealer — 1980 Jeep Vehicles	On some late production Jeep vehicles equipped with a manually operated sun roof, a black butyl sealer was used to seal the area between the sun roof frame and roof panel. Whenever the sun roof frame has been removed, a butyl or silicone sealer may be used to seal the area between the sun roof frame and roof panel. Apply an even bead of sealer to the roof panel surface approximately 1/8 inch from the edge of the roof opening.
Standard Oil Filter Damaged Dur Severe Off-Road Operation — 1974-80 Jeep Cherokee-Wagoneer- Truck Models With Six-Cylinder Engine	ing A new oil filter, part number 3240511, has been released for use on 1974-80 Cherokee, Wagoneer, and Truck models. The filter is longer in length and has a smaller diameter for additional filter- to-engine mount area clearance during severe off- road operation.

#### **VI American Motors Sales Corporation** Service Engineering Dept. • 14250 Plymouth Rd. • Detroit, Mich. 48232 Additional copies of this letter are available through your zone office.

File: Service General No. 80-17 Sept. 1, 1980

Subject	Information
SR4 Four-Speed Manual Transmission Changed for 1980 Models	The SR4 transmission has been changed for the 1980 models. The components and part numbers affected by the change are as follows:
	<ul> <li>A new design transmission case, part number 8132594;</li> </ul>
	<ul> <li>A new shorter length reverse idler gear, part number 8132882;</li> </ul>
	<ul> <li>A new reverse idler shaft with modified angle, part number 8133524.</li> </ul>
	The new shorter length reverse idler gear can be used in either the new or old transmission case.
-1	The new reverse idler shaft can be used in either the new or old transmission case and can also be used with either the new or old reverse idler gear.
	The old design length reverse idler gear can be used in the old transmission case only.
Revision to Diagnosis and Repair Bulletin No. 80-1, Transfer Case Shift Lever and Shaft Replacement, Dated January 9, 1980, Filed Under	The service procedure in the subject DRB is correct. However, new part numbers have been assigned to the parts outlined in the bulletin. The new numbers are:
CHASSIS - Iransfer Case/Quadra- Trac	Description Qty. Part No. Group
On and a lower	SHAFT, Transfer Case Shift 1 5362034 18.180
	LEVER, Transfer Case 1 5362033 18.125 83-93 - 4-cyl. and SR4 83 - 6- or 8-cyl. and T-176 93 - 8-cyl. and T-176
	LEVER, Transfer Case 1 5362036 18.125 93 - 6-cyl. and SR4
	NUT, Transfer Case Shift 1 4004837 18.180 Shaft Retaining
	NOTE: The threaded end of transfer case shift shaft, part number 5362034, is larger in diameter than the previous design shaft. This shaft can only be used with the above listed transfer case levers and shift shaft retaining nut. In addition, the transfer case shift shaft retaining nut should be tightened to 40-45 foot-pounds $(54-61 \text{ N}\cdot\text{m})$ torque.

#### **VI** American Motors Sales Corporation

### **∕I** Jeep,≣

# **Service Technical Letter**

File: Service General No.80-16 July 28, 1980

Subject	Information
Two-Stage Power Valve - Carburetor Models 2100 and 2150 — 1978-80 Jeep Vehicles	Some of the two-stage power values used in subject model carburetors have been replaced for what appears to be a leakage problem. Although a small amount of fuel may enter the power value cover via the carburetor manifold vacuum chamber, it does not constitute a leak problem. This condition is normal and will not effect performance or economy.
Tire Vibration — 1979-80 131-Inch Wheelbase J-10 Truck Models Equipped With H78-15, Load Range B, Firestone Town and Country Tires	The subject tires may be the cause of unexplained vibration problems on 1979-80, long wheelbase J-10 trucks. If diagnosis and test procedures do not reveal any type of runout or imbalance condition, install a set of test tires other than Firestone on the vehicle and road test again. If the vibration is now corrected, contact the nearest Firestone regional service center.

### **VI** American Motors Sales Corporation

# **VI** Jeep **E** PRODUCT RECALL CAMPAIGN **Diagnosis and Repair Bulletin No. 80-15**

2127000)

y 1, 80 through

No.

(Pa)

Janu

Date: July 21, 1980

Application: Tow Bar

File: Service General

SE2127000 for CJ Models

 $\mathbf{O}$ 

TOW BAR COUPLER NUT

Skill

Level

G

0

Year & Time

80 and Prior

0.2

Ð

Subject:

Cracked Co. Ordered fn May 31, 19

coupler nut.

nut replaced.

(1)

(2)

Je

on

**EDC** 

Some Jeep accessory tow bars, part number SE2127000, manufactured by the Dualmatic Manufacturing Company, may have a cracked

inventory or sold after January 1, 1980.

Each Jeep dealer will receive a coupler

nut for every tow bar ordered from the local Jeep PDC between January 1, 1980

and May 31, 1980. Additional nuts are available from the Zone Field Service

Remove and discard original coupler

The following operation and standard work time will apply:

Cost

Code

35.215

Operation

Model

83-93

Number

15401

American Motors Sales Corporation Service Engineering Department • 14250 Plymouth Read • Detroit, Michigan 48232 80-101

Install replacement coupler nut. Tighten nut until coupler threads extend 1/8 to 1/4 inch beyond

Manager. Dealers are responsible for notifying customers that may have purchased one of the affected tow bars from their dealership. These customers must be instructed to return their tow bar to the dealership to have the coupler

PROCEDURE

nut (see illustration).

shoulder of nut.

Operation Description

NUT, TOW BAR COUPLER-

REPLACE

on all affected tow bars in dealer

twee

This nut must be replaced

#### **/ Jeep**

# **Service Technical Letter**

File: Service General No. 80-14 July 1, 1980

Subject	Information
Subject Fiberglass Hardtop Interior Appearance - 1980 CJ-7 Models	Information Some fiberglass hardtops on 1980 CJ-7 models may develop what appears to be a crack in the portion of the hardtop that parallels the windshield frame. However, this crack is not in the hardtop but in the joint material applied to the area where the hardtop side-panel and top-panel overlap. If necessary, this condition can be corrected by removing the joint material and painting the overlap area.



File: Service General No. 80-13 June 16, 1980

Subject	Information
Correction to Quadra-Trac Differential End Cap Attaching Screw Torque — 1976 Jeep Technical Service Manual	The Quadra-Trac differential end cap attaching screw torque in step (22) on page 8-27 in the 1976 Jeep Technical Service Manual is incorrect. Please change this step to read as follows: "Tighten end cap attaching screws to 27 foot- pounds (36 N·m) torque."
	*
Engine Oil Capacity — 1980 Jeep Four-Cylinder Engines	1980 Jeep four-cylinder engines have an oil capacity of three quarts (2.84 liters) with or without an oil filter change.
	Overfilling the crankcase on these engines will result in oil aeration (foaming), tappet noise, and possible engine damage.
	To ensure an accurate dipstick reading on 1980 four-cylinder engines, check engine oil level after the engine has been shut down and the oil has drained back into the pan.
	Please note the four-cylinder engine oil capacity on page B-14 of the 1980 Jeep Technical Service Manual and page 22 of the 1980 Jeep Service Specifications Booklet.
ч. — — — — — — — — — — — — — — — — — — —	

#### I Jeep

# **Service Technical Letter**

File: Service General No. 80-12 June 9, 1980

Subject	Information
Radiator Hose Clamp Torque Specifications - 1980 Jeep	Radiator hose clamps should be tightened to the following torque specification.
Automobiles	Service Service In-Use Set-To Torque Recheck Torque
	22 inch-pounds       18-26 inch-pounds         (2.5 N·m)       (2-3 N·m)
	Please note these torque specifications in your 1980 Jeep Technical Service Manual.
Speedometer Adapter O-Ring Seal - 1980 Cherokee, Wagoneer, and Truck Models With Transfer Case Model 208 or 219	The speedometer adapter O-ring seal used in production of the subject models is black in color and is reusable. If an adapter equipped with a black O-ring seal is removed for service, the adapter can be installed using the original black color O-ring seal.
	The service parts replacement speedometer adapter O-ring seal is orange in color and can be used once only. This seal is designed to swell in service to improve its sealing qualities and could become damaged during adapter removal, or during installation if reuse is attempted.
	The part number for the orange color service parts replacement seal is as follows:
	Description Quantity Part No. Group
	O-Ring, Speedometer Adapter 1 4006574 3.591

### **71** American Motors Sales Corporation

I Jeep

# **Service Technical Letter**

File: Service General No. 80-11 May 23, 1980

e crankshaft main bearing clearance specifica- ons for 1980 six-cylinder engines have been vised as follows:
e crankshaft main bearing clearance specifica- ons for 1980 six-cylinder engines have been vised as follows:
mber 1 Main Bearing
in Bearing Clearance: 0.001 to 0.0025 inch eferred Clearance : 0.0015 inch
mber 2 Through 7 Main Bearings
in Bearing Clearance: 0.001 to 0.003 inch eferred Clearance : 0.0015 to 0.002 inch
ease note these revised specifications in your 80 Technical Service Manual and Service ecifications Handbook.
e exhaust pipe-to-manifold bolts on 1980 49- ate four-cylinder engines with a dual outlet pe should be tightened to 35 foot-pounds 0 N·m) toruqe. In-use recheck torque is 30-40 ot-pounds (40-60 N·m) for these bolts. haust pipe-to-manifold nuts on 1980 California ur-cylinder engines with a single outlet pipe ould be tightened to 35 foot-pounds torque 0 N·m). In-use recheck torque is 30-40 foot- unds (40-60 N·m) torque for these nuts. ease note these specifications in your 1980 chnical Service Manual and Service Specifica- ons Handbook.

**FI American Motors Sales Corporation** Service Engineering Dept. • 14250 Plymouth Rd. • Detroit, Mich. 48232 Additional copies of this letter are available through your zone office.

File: Service General No. 80-10 May 14, 1980

Subject	Information
AM-FM Radio Right to Left Balance Control Adjustment — 1980 Jeep Vehicles	Some of the AM-FM radios in 1980 Jeep vehicles are not equipped with a slide switch above the station dial for right to left balance control adjustment. On these radios, balance adjustment is accomplished by gently pulling the volume control knob outward and turning it right or left to adjust balance as described in the 1980 Technical Service Manual. Before removing one of these radios to correct a suspected balance problem, be sure the balance control has been adjusted properly and that the owner is aware of this adjustment procedure.
Chrome Wheel Discoloration - 1980 Jeep Models Equipped With Chrome Wheels	Discoloration or surface rust may appear just inboard of the wheel spokes on 1980 Jeep chrome wheels. If this condition occurs, it is possible to improve wheel appearance by cleaning the inside of the wheel and applying a silver or aluminum colored enamel paint to the discolored area. However, if the wheel is exposed to salt or stone chips, this condition may reoccur.

#### **FI** American Motors Sales Corporation Service Engineering Dept. • 14250 Plymouth Rd. • Detroit, Mich. 48232 Additional copies of this letter are available through your zone office.

File: Service General No. 80-9 April 15, 1980

Subject	Information
1980 CJ Oil Pressure Gauge	The specifications for oil pressure gauge sending unit resistance on page 1L-40 of the 1980 Jeep Technical Service Manual are incorrect. The correct resistance values should read as follows: Oil Pressure Gauge Sending Unit Resistance (Ohms)
	PSI 0 40 80
	0 40 10 0 10
	The bumper jack in 1980 Cherokee and Wagoneer models built after March of this year will be secured with a plastic tie-down strap. This strap is for transportation use only and should be removed before delivering each vehicle.

/ Jeep.

### **71** American Motors Sales Corporation

File: Service General No. 80-8 March 31, 1980

#### Subject

#### Information

Correction to Diagnosis and Repair Bulletin No. 80-4, Stereo Radio Rear Speakers Missing, dated February 14, 1980, filed under BODY-Body Electrical If the stereo radio rear speakers do not function properly after performing procedural step (8), under Vehicles With Power Tailgate, the vehicle may have an incorrect rear speaker wire harness. Remove the glove box from the dash panel and check the wire harness part number. If the harness number is not 5751957, replace the harness.

#### **FI American Motors Sales Corporation** Service Engineering Dept. • 14250 Plymouth Rd. • Detroit, Mich. 48232
### **71** Jeep,

# **Service Technical Letter**

File: Service General No. 80-7 March 27, 1980

Subject	Information		
Camshaft Spring Pin Correction — Six-Cylinder Camshaft Pin Breakage on 1977-80 Jeep Vehicles — DRB 80-3 dated February 4, 1980, Filed Under POWER PLANT-Engines	When performing the camshaft pin replacement procedure, order spring pin G456384. Do not order pin GM456384.		
, , ,			

I Jeep,

# **Service Technical Letter**

File: Service General No. 80-6 March 19, 1980

Subject	Information		
Assembling Piston and Connecting Rod — 1980 Four-Cylinder Engines	When assembling the piston and connecting rod on a four-cylinder engine, the notch in the top of the piston must be 180° opposite the raised notch in the large end of the connecting rod.		
	a)		

### **VI American Motors Sales Corporation**

### **71** Jeep

# **Service Technical Letter**

File: Service General No. 80-5 Feb. 4, 1980

Subject		Informatio	n.	
New Propeller Shaft-to-Yoke Attaching Bolt— all 1980 Jeep Vehicles	A new propeller shaft-to-yoke attaching bolt has been released for service. The bolt features a 12-point head and increased length for improved thread engagement. This bolt has already been installed in some Jeep rear axle yokes to ensure thread engagement in yokes with damaged threads. The new bolts can be used to salvage other yokes having damaged threads by tapping the yoke and installing the new, longer bolt.			
	The tightening torque specification for the new bolt remains at 15 foot-pounds (20 N·m) torque plus or minus 1 foot-pound (1 N·m) torque. The new bolts will be available the week of February 18, 1980. Do not order bolts until this date.			
	Description	Quantity	Part No.	Group
Revised Fuse Rating for Cigar Lighter Circuit— 1980 Jeep CJ Models With 4 and 6-Cylinder Engines.	BOLT, Propeller Shaft-to-Yoke (1/4-28 x 7/8) The originally specificigar lighter circuit h 20 amp fuse.	AR ed 10 amp fuse as been changed	4006698 e in the d to a	9.100

#### **FI American Motors Sales Corporation** Service Engineering Dept. • 14250 Plymouth Rd. • Detroit, Mich. 48232 Additional copies of this letter are available through your zone office.

### / Jeep.

# **Service Technical Letter**

File: Service General No. 80-4 Jan. 30, 1980

Subject	Information	
Correction to In-Vehicle Torque Bias Check — 1980 Cherokee, Wagoneer, and Truck Models With Model 219 Quadra-Trac Transfer Case	<pre>Steps (2) and (3) of the In-Vehicle Torque Bias Check on page 147, Chapter 2D, of the 1980 Technical Service Manual Supplement have been revised. Step (2) should read: "Place transmission shift lever in NEUTRAL and transfer case shift lever in 4-HIGH position." Step (3) should read: "Raise one FRONT wheel off floor."</pre>	
Correction to Camber Specifi- cations - 1980 Cherokee, Wagoneer and Truck Models	Front wheel camber specifications for 1980 Cherokee, Wagoneer and Truck models have been changed. The camber specifications for CJ models remains the same. The second sentence under Camber on page 2M-4 of the 1980 Technical Service Manual should read: "Correct wheel camber of $0^{\circ}$ ( $\pm$ 1/2°) for Cherokee, Wagoneer and Truck models and $\pm$ 1-1/2° ( $\pm$ 1/2°) for CJ models is preset at time of manufacture and cannot be altered by adjustment." The camber specifications in the Front Wheel Alignment Specifications Chart on page 2M-6 should read: CJ $\pm 1-1/2^{\circ}$ ( $\pm$ 1/2°) Cherokee, Wagoneer and Truck $0^{\circ}$ ( $\pm$ 1/2°)	

### **VI** American Motors Sales Corporation

# **Service Technical Letter**

**FI** Jeep

File: Service General No. 80-3 Dec. 11,1979

Subject	Information
Correct Tempatrol Fan Assembly Storage — 1980 and Prior Jeep Models	To prevent silicone fluid from draining into the fan drive bearing and contamina- ting the lubricant, <u>do not</u> place a Tempatrol fan unit on a workbench or storage shelf with the rear of the shaft (mounting flange) pointing downward.
Part Number Change - Service Technical Letter Number 80-2, Dated November 10, 1979	In the first item on the subject Service Technical Letter, the lock mode indicator switch part number given as 8130826, should be changed to 8130829. Please note this change on Service Technical Letter 80-2.
ii	

American Motors Sales Corporation
 Service Engineering Dept. • 14250 Plymouth Rd. • Detroit, Mich. 48232
 Additional copies of this letter are available through your zone office.

# **Service Technical Letter**

File: Service General No. 80-2 Nov. 10, 1979

Subject	Information		
Four Wheel Drive Indicator Lamp Operation and Switch Usage — 1980 Jeep Cherokee, Wagoneer and Truck Models with Model 208 or 219 Transfer Case	1980 Jeep vehicles equipped with a model 219 or 208 transfer case have an indicator lamp which lights in certain four-wheel drive ranges. The model 208 and 219 require different switches to operate the lamp. Although the two switches look very similar, they operate differently. Refer to the following descriptions to verify correct operation and switch usage.		
	On vehicles with a model 219, the indicator lamp should light when the lever is 4H LOCK position only. If the lamp lights in any other shift mode, remove the indicator switch and check switch continuity. The switch is normally in a closed position. If incorrect, install a model 219 lock mode indicator switch, part number 8132843. A correction should be made to the description of the model 208 transfer case on page 2D-4 of the 1980 Technical Service Manual under Four-Wheel Drive Indicator Lamp. On vehicles with a model 208, the indicator lamp is illuminated in four wheel high range and four wheel low position, not in high range only as was published. If the light is on in any other position, remove the indicator switch on the transfer case and check continuity. The switch is normally open. The correct model 208 lock mode indicator switch part number is 8130826.		
Model T-176 4-Speed Manual Trans- mission Released as a Production Option to Model SR-4 4-Speed Manual Transmission - 1980 CJ-7 Models Built With 6-Cylinder Engine and Manual Transmission	The model T-176 4-speed manual transmission will be used as an option in production to the model SR-4 4-speed manual transmission on 1980 CJ-7 models built with a 6-cylinder engine. The model T-176 transmission can be distinguished from the SR-4 transmission by checking the shifter location. The model T-176 transmission shifter is located on top of the transmission case while the model SR-4 transmission shifter is located in the adapter housing attached to the rear of the trans- mission case.		

### **VI** American Motors Sales Corporation

## Service Technical Letter (cont'd)

Subject	Information		
	Related components such as propeller shafts, trans- fer case torque reaction bracket, clutch housing and shift knob also differ when a model T-176 is used. Note this change on the Power Train Combinations - 1980 CJ Models chart on page A-12 of the General Information section in the 1980 Jeep Technical Service Manual.		
Revised Clutch Overcenter Spring Removal Procedures - 1979 CJ Models Built After Mid-April	A revised procedure has been developed for removal of the heavier gauge clutch overcenter spring. This spring was phased into production during mid- April along with other clutch related components as described in STL 9-12, dated August 23, 1979. Revise DRB 9-02, dated July 18, 1979, and filed under Chassis, Clutch-Manual Transmission (Group 6.000) as follows. After step (4) of Clutch Overcenter Spring and after step (7) of Clutch Pedal Replacement add: Clamp vise grips on lower end of clutch pedal support bracket. Bend bracket downward to provide access to end of over- center spring that is attached to bracket. NOTE: Refer to the 1980 Jeep Technical Service Manual for procedures on 1980 CJ models. The Standard Servicing Operations and work times as published are not affected by this revision.		

/ Jeep

# **Service Technical Letter**

 File: Service General

 No. 80-1
 Sept. 19, 1979

Subject	Information	
Tape Player Inoperative Caused By Transit Screw - 1980 Jeep Models AM/FM/Cassette Radio	The AM/FM/Cassette radio has a transit screw installed at time of manufacture to ensure that the tape transport mechanism is not damaged during shipment. If this screw is not removed, the cassette tape player will not operate. The tape cartridge will only engage part way. This screw must be removed before the radio is installed. The screw is located on the top of the radio and is identified by a label that states: "WarningThis screw must be removed before installation".	
Relocation of Safety Certifica- tion and Emission Control Labels — 1980 Jeep CJ Models	The Safety Certification and Emission Control labels on 1980 Jeep CJ models have been relocated from the instrument panel to the inside of the left lower body panel just below the door opening. The Emission Control Maintenance Information Label remains under the hood in front of the radiator.	

### **VI** American Motors Sales Corporation



FILE: Engines-Fuel Systems Engine Electrical-Cooling (POWER PLANT-Engines)

No. 1-10-82 Sept. 8, 1982

### **TECHNICAL BULLETIN**

PROBLEM AND	The pushrods in some 1981-82 Jeep 258 CID six-cylinder engines
APPLICATION:	built prior to May 1982, may disengage from the rocker arms
	causing noise, backfire, or a miss.

CORRECTION: Install the following replacement 0.070 inch longer pushrods as outlined in the appropriate Jeep Technical Service Manual if any of the original pushrods become disengaged or bent. The original pushrods are 9.640 to 9.660-inches long. The replacement pushrods, part number 3242395, are 9.710 to 9.730-inches long.

NOTE: The original (shorter) pushrods, part number 3227329, are still recommended for use in 1980 and prior Jeep 258 CID six-cylinder engines.

PARTS:	Description	Quantity	Part Number	Group
	ROD, Valve Push	12	3242395	1.095

S.R.T. Consult the T.I.C. manual and appropriate S.R.T. manual. INFORMATION:

DEALER Reimbursable within the provisions of the applicable warranty. REIMBURSEMENT:

# American Motors Sales Corporation Service Engineering Department • 14250 Plymouth Road • Detroit, Michigan 48232 Additional copies of this builletin are available through your zone office

2 82-070-A/J