


IS.

INFORMATIONS SERVICE SERVICE INFORMATION SERVICE INFORMATIONEN SERVICE INFORMATION INFORMACIONES SERVICIO INFORMAZIONI SERVIZIO SERVICE INFORMASJONER SERVICE INFORMATIE SERVICEINFORMATION INFORMAÇAO SERVIÇO 6E

SEPTEMBER 1985 ENGLISH EDITION

1984-1986 JEEP WAGONEER/TRUCK



**GEARBOXES** 

Attention: Workshop, Parts Department

## **MODEL 208 TRANSFER CASE REVISION ANNULUS GEAR**


Two annulus gear assemblies were used in Model 208 transfer cases. They are interchangeable.

Type I has a metal hub annulus and does require a thrust washer.

Type II has a nylon hub annulus and does not require a thrust washer.

## **PROCEDURE**

When replacing a Type I annulus gear with a Type II annulus gear (B), be sure to discard the thrust washer (A) located between the annulus and planetary gears.



86493A

## **FILING INSTRUCTIONS**

Record this I.S. Note on page E-26 and file it in your M.R. 253 binder.